

**App. B:
Petrie Decl., Ex. 2
Part II**

Confidential

9983	700	27359	308 WIN	2-Feb-12	N	S	21-Feb-14	21-Feb-14	Fired on Bolt Opening	Altered Adjustments or Components	338474	F	Per Ilion, replace trigger, check over and test fire at no charge
9988	700	25763	22-250 REM	15-Jan-86	N	S	24-Feb-14	24-Feb-14	Fired on Bolt Closing	AFT MKT TRIGGER ASSM	338618	F	Per Ilion, replace trigger, check over, and test at 50% discount
9989	700	N/A	17 REM	6-Apr-73	N	S	24-Feb-14	24-Feb-14	Fired on Bolt Closing	Altered Adjustments or Components	338549	F	Per Ilion, quote to repair BLM
9990	504	26500	22 LR	22-Feb-04	N	S	24-Feb-14	24-Feb-14	Fired on Safe Release	Altered Adjustments or Components	338550	F	Per Ilion, check over, repair as needed, and test at 50% discount
9991	700	N/A	270 WIN	7-Aug-78	N	S	24-Feb-14	11-Mar-14	Fired on Bolt Closing	Improper Maintenance	340169	F	Per Ilion, quote to repair BLM
9993	597	N/A	17 HMR	26-Aug-03	N	PD/S	24-Feb-14	12-Mar-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	340054	F	Replacing with Ramac 70701 in exchange
9992	597	26536	17 HMR	27-Jan-03	N	PD/S	24-Feb-14	15-Apr-15	My Gun Blew Up	Not Examined by Product Service	495494	F	Gun not examined by Product Service in Ilion
9995	700	84206	223 REM	26-Jun-09	N	S	25-Feb-14	25-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	338721	F	Per Ilion - Repair at n/c - goodwill
10001	700	84229	308 WIN	27-Apr-11	N	S	25-Feb-14	7-Mar-14	Fired on Bolt Closing	Altered Adjustments or Components	339914	F	Per Ilion, replace trigger, check over, and test at 50% discount
10002	700	n/a	270 WIN	9-Apr-69	N	S	25-Feb-14	7-Mar-14	Fired on Safe Release	Could Not Duplicate Concern	339793	F	Per Ilion - Quote to repair under BLM
10005	700	85441	3006 SPRG	11-Sep-09	N	S	26-Feb-14	26-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	338824	F	Replacing with Ramac 87203 in exchange
10006	700	27253	270 WSM	11-Sep-06	N	S	26-Feb-14	26-Feb-14	Fired on Bolt Closing	Altered Adjustments or Components	338764	F	Per Ilion, replace trigger, check over, and test at 50% discount
10007	740	N/A	308 WIN	1-Oct-59	N	S	26-Feb-14	26-Feb-14	Fired on Bolt Closing	Sent in for Evaluation	338814	F	Per Ilion, check over, repair as needed, and test at no charge
10012	700	n/a	243 WIN	20-May-71	N	S	26-Feb-14	19-Mar-14	Fired on Safe Release	Could Not Duplicate Concern	340886	F	Per Ilion - Quote to repair under BLM
10013	700	not avail.	3006 SPRG	17-Jul-75	N	S	27-Feb-14	27-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	338961	F	Per Ilion - Quote to repair under BLM
10014	700	25709	308 WIN	24-Apr-13	N	S	27-Feb-14	27-Feb-14	Fired on Safe Release	Other - Unspecified or Undetermined - Firearms	338919	F	Per Ilion - Repair at n/c - warranty
10015	700	27476	270 WIN	25-May-02	N	S	27-Feb-14	27-Feb-14	Fired on Bolt Closing	Altered Adjustments or Components	339015	F	Per Ilion, replace trigger, check over, and test at 50% discount
10016	320	24813	12 GA	4-Nov-94	N	S	27-Feb-14	27-Feb-14	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	338935	F	Per Ilion, check over, repair as needed, and test at 50% discount
10017	700	not avail.	270 WIN	3-Apr-74	N	S	27-Feb-14	27-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	338938	F	Per Ilion - Quote to repair under BLM
10018	597	26550	22 LR	20-Nov-98	N	S	27-Feb-14	27-Feb-14	Ammunition Exploded	Other - Unspecified or Undetermined - Firearms	339007	F	Per Ilion, check over, repair as needed, and test at no charge
10022	700	n/a		8-Jun-73	N	S	27-Feb-14	27-Feb-14	Fired on Safe Release	Not Examined by Product Service	n/a	F	Referred customer to Gravel Agency in Canada
10023	700	27480	7MM REM MA	3-May-00	N	S	27-Feb-14	12-Mar-14	Fired on Bolt Closing	Improper Maintenance	340289	F	Per Ilion - Quote to repair @ discount
10025	870	25583	20 GA	11-Sep-13	N	S	28-Feb-14	28-Feb-14	Fired on Bolt Closing	Could Not Duplicate Concern	339062	F	Per Ilion, check over, repair as needed, and test at no charge

RAC001182

Confidential

10026	660	N/A	308 WIN	19-Aug-69	N	S	28-Feb-14	28-Feb-14	Fired With Safe ON	Could Not Duplicate Concern	339218	F	Per Ilion, replace trigger, check over and test fire at no charge
10027	660	not avail.	243 WIN	10-Jul-69	N	S	28-Feb-14	28-Feb-14	Fired on Safe Release	Improper Maintenance	339196	F	Per Ilion - Repair at n/c
10032	700	n/a	3006 SPRG	16-May-78	N	S	28-Feb-14	7-Oct-14	Fired on Safe Release	Altered Adjustments or Components	470289	F	Ilion repaired at n/c under BLM
10035	700ML	27588	50 CAL	12-Nov-01	Y	S	28-Feb-14	14-Mar-14	Fired on Safe Release	Altered Adjustments or Components	340473	F	Per Ilion - Quote to repair @ discount
10037	870	25568	12 GA	7-Feb-14	N	S	3-Mar-14	3-Mar-14	Fired With Safe ON	Improper Assembly by Customer	339357	F	Per Ilion, check over, repair as needed, and test at no charge
10038	700	not avail.	223 REM		N	S	3-Mar-14	3-Mar-14	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Consumer does not own the rifle & refused to provide owner's name
10043	700	not avail.	7MM MAG	8-Jun-80	N	S	3-Mar-14	6-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	341099	F	Not Examined by Product Service
10044	721	N/A	270 WIN	1-Dec-53	N	S	4-Mar-14	4-Mar-14	Dissatisfied with Service - Firearms	Altered Adjustments or Components	339458	F	Replace trigger, check over, and test at no charge
10047	700	N/A	300 WBY MA	12-Jun-93	N	S	4-Mar-14	14-Mar-14	Delayed Firing - Firearms	Altered Adjustments or Components	340521	F	Per Ilion, replace trigger, check over, and test at 50% discount
10049	710	27410	3006 SPR	30-Nov-05	Y	PD/S	4-Mar-14	6-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
10052	1911	96323	45 ACP	19-Apr-13	N	PI/PD/S	5-Mar-14	24-Mar-14	Personal Injury while using firearm	Other - Unspecified or Undetermined - Firearms	340873	F	Check over completely, repair as needed, and test fire at no charge
10054	700	not avail.	22-250 REM	29-Nov-77	N	S	6-Mar-14	6-Mar-14	Fired on Safe Release	Altered Adjustments or Components	339647	F	Per Ilion - Quote to repair under BLM
10058	700	25787	243 WIN	5-May-03	N	PD/S	6-Mar-14	8-Oct-14	Fired on Bolt Closing	Could Not Duplicate Concern	470122	F	Check over completely, repair as needed, and test fire at no charge
10059	700	29694	300 WIN MA	23-Apr-93	N	S	6-Mar-14	31-Mar-14	Fired on Safe Release	Could Not Duplicate Concern	341925	F	Per Ilion, check over, repair as needed, and test at 50% discount
10061	887	82502	12 GA	13-Jan-14	N	S	7-Mar-14	7-Mar-14	Fired on Bolt Closing	Could Not Duplicate Concern	339812	F	Per Ilion - Repair at n/c - warranty
10074	597	26536	17 HMIR	26-Mar-03	N	PD/S	10-Mar-14	6-May-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	342215	F	Replacing with Ramac 70723 in exchange
10076	700	N/A	25-06 REM	19-Mar-71	N	S	11-Mar-14	6-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
10078	700	84521	270 WIN	26-Mar-11	N	S	12-Mar-14	12-Mar-14	Fired on Safe Release	Altered Adjustments or Components	340244	F	Per Ilion - Quote to repair @ discount
10079	700	not avail.	7MM REM MA	21-May-75	N	S	12-Mar-14	12-Mar-14	Fired on Safe Release	Altered Adjustments or Components	340305	F	Per Ilion - Quote to repair under BLM
10083	700	27512	22-250 REM	3-Mar-03	N	S	14-Mar-14	14-Mar-14	Fired on Safe Release	Altered Adjustments or Components	340486	F	Returning as received
10084	7	24792	17 REM	21-May-92	N	S	14-Mar-14	16-Apr-14	Fired on Safe Release	Altered Adjustments or Components	340476	F	Repair @ n/c
10085	700	N/A	243 WIN	8-Sep-78	N	S	14-Mar-14	14-Mar-14	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	340274	F	Per Ilion, quote to repair BLM
10086	700	not avail.	270 WIN	11-Nov-70	N	PD/S	14-Mar-14	31-Mar-14	Fired With Safe ON	Could Not Duplicate Concern	341408	F	BLM @ n/c - goodwill gesture
10088	700	not avail.	3006 SPRG	2-Feb-81	N	S	14-Mar-14	27-Mar-14	Fired on Safe Release	Improper Maintenance	341696	F	Repair @ n/c - goodwill gesture
10089	597	N/A	17 HMIR		N	PI/PD/S	14-Mar-14	14-Apr-15	My Gun Blew Up	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam

RAC001183

Confidential

10092	700	84152	7MM RUM	25-Jan-08	N	S	17-Mar-14	17-Mar-14	Fired on Safe Release	Could Not Duplicate Concern	340635	F	Per Ilion, replace trigger, check over, and test at 50% discount
10097	597	26516	17 HMR	4-May-04	N	PI/PD/S	17-Mar-14	1-Apr-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	342024	F	Replacing with Ramac 70723 in exchange
10095	597	26516	17 HMR	9-Feb-03	N	PI/PD/S	17-Mar-14	7-Jan-15	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	479355	F	Replace with Ramac 70743 in exchange
10101	597	N/A	17 HMR	7-Feb-03	N	PD/S	18-Mar-14	16-Apr-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	343381	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
10098	XV15E2S	90391	223/5.56	24-Jun-13	N	S	19-Mar-14	19-Mar-14	Went Automatic	Could Not Duplicate Concern	340899	F	Per Ilion - Repair at n/c
10099	700	29694	300 WIN MA	26-Aug-94	N	S	19-Mar-14	19-Mar-14	Fail to Fire	Altered Adjustments or Components	340844	F	Per Ilion, replace trigger, check over, and test at 50% discount
10100	597	80852	22 LR	21-Dec-12	N	S	19-Mar-14	19-Mar-14	Defective Parts	Could Not Duplicate Concern	340917	F	Per Ilion - Repair at n/c - warranty
10103	870	25587	12 GA	20-Aug-13	N	S	20-Mar-14	20-Mar-14	Fired With Safe ON	Could Not Duplicate Concern	340992	F	Per Ilion, replace trigger, check over and test fire at no charge
10105	700	85433	223 REM	8-Feb-11	N	S	20-Mar-14	20-Mar-14	Fired on Safe Release	Could Not Duplicate Concern	341073	F	Per Ilion - Repair at n/c - warranty
10110	597	80910	22 LR	30-Aug-13	N	S	21-Mar-14	21-Mar-14	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	341151	F	Per Ilion, check over, repair as needed, and test at no charge
10112	600	N/A	243 WIN	18-Jun-71	N	S	24-Mar-14	24-Mar-14	Fired on Bolt Closing	Improper Maintenance	341310	F	Per Ilion, replace trigger, check over and test fire at no charge
10113	541	29800	22 LR	7-Jun-76	N	S	24-Mar-14	24-Mar-14	Fired on Safe Release	Altered Adjustments or Components	341323	F	Per Ilion, check over, repair as needed, and test at 50% discount
10114	700	N/A	6MM REM	1-Oct-68	N	S	24-Mar-14	24-Mar-14	Fired on Safe Release	Improper Maintenance	341320	F	Per Ilion, quote to repair BLM
10118	700	29699	300 WBY MA	19-May-90	N	S	25-Mar-14	22-Apr-14	Fired on Bolt Closing	Could Not Duplicate Concern	343684	F	Replace trigger, check over, and test at no charge
10119	597	26536	17 HMR	31-Mar-03	N	PD/S	25-Mar-14	14-Apr-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	343103	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
10124	1911	96323	45 ACP	24-May-10	N	S	25-Mar-14	13-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
10125	770	not avail.	7MM REM MA		N	PD/S	25-Mar-14	6-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
10041	700	84515	3006 SPR	15-Feb-10	N	S	26-Mar-14	2-Apr-14	Fired on Safe Release	Could Not Duplicate Concern	341512	F	Per Derek Watkins, gun will be checked over completely at no charge.
10120	660	N/A	243 WIN	9-Feb-70	N	S	26-Mar-14	26-Mar-14	Fired on Bolt Closing	Could Not Duplicate Concern	341450	F	Per Ilion, quote to repair BLM
10121	700	26129	3006 SPRG	23-Dec-98	N	S	26-Mar-14	26-Mar-14	Delayed Firing - Firearms	Altered Adjustments or Components	341498	F	Per Ilion, replace trigger, check over, and test at 50% discount
10122	700	27267	270 WIN	17-Jun-13	N	S	26-Mar-14	26-Mar-14	Fired on Safe Release	Could Not Duplicate Concern	341645	F	Per Ilion, replace trigger, check over and test fire at no charge
10134	722	N/A	222 REM	1-Feb-52	Y	S	28-Mar-14	16-Apr-14	Fired on Bolt Closing	Could Not Duplicate Concern	343372	F	Per Ilion, quote to repair BLM

RAC001184

Confidential

10135	700	not avail.	3006 SPRG	1-Sep-69	N	S	28-Mar-14	29-May-14	Fired on Safe Release	Could Not Duplicate Concern	413287	F	Repair @ n/c
10136	700	85375	7MM REM MA	23-Sep-08	N	S	31-Mar-14	31-Mar-14	Fired on Safe Release	Could Not Duplicate Concern	341892	F	Replace trigger, check over, and test at no charge
10137	700	27351	223 REM	8-Aug-08	N	S	31-Mar-14	17-Apr-14	Fired on Bolt Closing	Could Not Duplicate Concern	343450	F	Per Ilion, replace trigger, check over and test fire at no charge
10140	700	26039	7MM REM MA	7-Dec-01	N	S	31-Mar-14	8-Apr-14	Fired on Safe Release	Improper Maintenance	342722	F	Per Ilion - Quote to repair @ discount
10146	700	27455	300 WIN MA	19-Nov-02	N	S	1-Apr-14	1-Apr-14	Fired With Safe ON	Could Not Duplicate Concern	342058	F	Repair @ n/c - goodwill gesture
10147	700	29709	270 WIN	23-Aug-94	N	S	1-Apr-14	17-Apr-14	Fired on Safe Release	Improper Maintenance	343553	F	Per Ilion, replace trigger, check over, and test at 50% discount
10152	597	N/A	17 HMR	15-Jun-04	N	PI/PD/S	1-Apr-14	6-May-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	343645	F	Replacing with Ramac 70723 in exchange
10156	700	25768	2506 REM	19-Jan-83	N	S	3-Apr-14	3-Apr-14	Fired on Safe Release	Broken or Missing Parts	342176	F	Per Ilion - Quote to repair @ discount
10158	1911	96324	45ACP	7-Mar-12	N	S	3-Apr-14	3-Apr-14	Went Automatic	Other - Unspecified or Undetermined - Firearms	342298	F	Per Ilion, check over, repair as needed, and test at no charge
10160	XM15E2S	N/A	223/5.56	21-Jul-09	N	S	3-Apr-14	3-Apr-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	342260	F	Per Ilion, check over, repair as needed, and test at no charge
10161	600	N/A	222 REM	12-Jul-77	Y	S	3-Apr-14	3-Apr-14	Fired on Bolt Closing	Improper Maintenance	342300	F	Per Ilion, quote to repair BLM
10168	700	N/A	7MM REM MA	8-Nov-73	N	S	4-Apr-14	4-Apr-14	Delayed Firing - Firearms	Improper Maintenance	342358	F	Per Ilion, check over, repair as needed, and test at 50% discount
10169	700	84466	223 REM	14-Mar-09	N	S	4-Apr-14	1-May-14	Blowback in Face	Other - Unspecified or Undetermined - Ammunition	342422	F	Per Ilion, check over, repair as needed, and test at no charge
10171	887	82500	12 GA	19-Jul-13	N	S	4-Apr-14	4-Apr-14	Fired With Safe ON	Sent in for Evaluation	342468	F	Per Ilion, check over, repair as needed, and test at no charge
10174	SP10	not avail.	10 GA		Y	S	7-Apr-14	2-May-14	Went Automatic	Could Not Duplicate Concern	342536	F	Quote to repair at a discount goodwill gesture
10186	597	26536	17 HMR	19-Mar-03	N	PI/PD/S	8-Apr-14	22-Apr-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	343680	F	Sent \$250 rebate coupon as requested by customer
10191	770	85655	270 WIN	29-Oct-08	N	S	9-Apr-14	9-Apr-14	Fired on Safe Release	Could Not Duplicate Concern	342833	F	Per Ilion, replace trigger, check over, and test at 50% discount
10196	DPMS A-15	not avail.	223 REM		N	PD/S	9-Apr-14	19-May-14	Fired With Safe ON	Other - Unspecified or Undetermined - Firearms	n/a	F	Per Release - \$2,992.69 reimbursement for gun & damages
10206	700	25793	3006 SPRG	16-Jul-90	N	S	10-Apr-14	23-Apr-14	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	343932	F	Repair @ n/c - goodwill gesture
10207	700	N/A	3006 SPRG	1-Oct-74	N	S	11-Apr-14	11-Apr-14	Fired on Safe Release	Could Not Duplicate Concern	342998	F	Per Ilion, quote to repair BLM
10208	541	29800	22 RF	2-Apr-82	Y	S	11-Apr-14	11-Apr-14	Fired on Safe Release	Improper Maintenance	342981	F	Per Ilion - Quote to repair @ discount
10212	700	25827	6MM REM	24-Jan-90	N	S	14-Apr-14	14-Apr-14	Delayed Firing - Firearms	Improper Maintenance	343099	F	Per Ilion, replace trigger, check over, and test at 50% discount

RAC001185

Confidential

10217	700	27169	7MM REM MA	13-Jun-06	N	S	15-Apr-14	15-Apr-14	Fired on Bolt Closing	Could Not Duplicate Concern	343278	F	Per Ilion, replace trigger, check over and test fire at no charge
10218	522	29792	22 LR	11-Jun-93	N	S	15-Apr-14	15-Apr-14	Fired on Bolt Closing	Could Not Duplicate Concern	343286	F	Returning as received
10219	700	85409	7MM08 REM	28-May-10	N	S	15-Apr-14	15-Apr-14	Fired on Safe Release	Could Not Duplicate Concern	343294	F	Per Ilion, replace trigger, check over and test fire at no charge
10221	887	82502	12 GA	29-Oct-09	N	S	15-Apr-14	15-Apr-14	Fired Out of Battery	Could Not Duplicate Concern	343228	F	Per Ilion, check over, repair as needed, and test at no charge
10222	770	85633	3006 SPRG	21-Nov-11	N	S	15-Apr-14	15-Apr-14	Delayed Firing - Firearms	Could Not Duplicate Concern	343238	F	Per Ilion, check over, repair as needed, and test at no charge
10228	722	20000	222 REM	1-Feb-53	N	S	16-Apr-14	16-Apr-14	Fired on Bolt Closing	Altered Adjustments or Components	343428	F	Per Ilion, quote to repair BLM
10233	700	N/A	270 WIN	27-May-81	N	S	17-Apr-14	17-Apr-14	Fired on Safe Release	Altered Adjustments or Components	343487	F	Per Ilion, quote to repair BLM
10234	700	N/A	6MM REM	27-Sep-73	N	S	17-Apr-14	17-Apr-14	Fired on Safe Release	Altered Adjustments or Components	343471	F	Per Ilion, replace trigger, check over and test fire at no charge
10235	7400	24716	3006 SPRG	18-Jan-90	Y	PD/S	17-Apr-14	19-Jun-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	417226	F	Repair @ n/c - goodwill gesture
10236	700	not avail.	3006 SPR	16-Jun-78	N	PI/S	17-Apr-14	6-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
10237	700	N/A	7MM REM MA	17-Jan-73	N	S	21-Apr-14	21-Apr-14	Fired on Bolt Closing	Altered Adjustments or Components	343581	F	Per Ilion, replace trigger, check over and test fire at no charge
10239	700	84371	308 WIN	6-May-10	N	S	21-Apr-14	21-Apr-14	Fired on Safe Release	Could Not Duplicate Concern	343595	F	Per Ilion, replace trigger, check over and test fire at no charge
10244	700	27480	7MM REM MA	25-Mar-00	N	PD/S	21-Apr-14	15-May-14	Unexplained Discharge Safe ON	Could Not Duplicate Concern	401057	F	Check over completely, repair as needed, and test fire at no charge
10247	CARBON 15	90689	223/5.56	8-Apr-09	N	S	23-Apr-14	23-Apr-14	Went Automatic	Could Not Duplicate Concern	343919	F	Per Ilion, replace trigger, check over and test fire at no charge
10248	597	26514	17 HMR	22-Feb-05	N	PD/S	23-Apr-14	21-May-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	343867	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
10249	XM15E25	90641	5.56	31-Jul-12	N	S	23-Apr-14	23-Apr-14	Went Automatic	Could Not Duplicate Concern	343901	F	Per Ilion, check over, repair as needed, and test at no charge
10251	700	25709	308 WIN	4-Jun-12	N	S	23-Apr-14	23-Apr-14	Light Trigger Pull	Altered Adjustments or Components	343978	F	Per Ilion, replace trigger, check over and test fire at no charge
10256	CARBON 15	90689	5.56	16-May-13	N	S	24-Apr-14	24-Apr-14	Went Automatic	Sent in for Evaluation	344113	F	Per Ilion, replace trigger, check over and test fire at no charge
10258	597	26536	17 HMR	18-Jun-03	N	PD/S	24-Apr-14	6-May-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	388643	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
10268	700	25718	300 WIN MA	14-May-13	N	S	28-Apr-14	19-May-14	Fired on Safe Release	Altered Adjustments or Components	406340	F	Per Ilion, replace trigger, check over and test fire at no charge

RAC001186

Confidential

10269	597	26536	17 HMR	29-Oct-02	N	PI/PD/S	28-Apr-14	15-Jul-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	436219	O	Replacing with Ramac 70741 in exchange
10273	700	N/A	6MM REM		N	S	28-Apr-14	25-Jun-14	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	429202	F	Per Ilion, replace trigger, check over and test fire at no charge
10267	600	N/A	308 WIN	1-Jun-67	N	S	29-Apr-14	29-Apr-14	Fired on Bolt Closing	Improper Maintenance	344619	F	Per Ilion, replace trigger, check over and test fire at no charge
10272	CARBON 15	90689	5.56	12-Jun-13	N	S	30-Apr-14	30-Apr-14	Went Automatic	Sent in for Evaluation	353003	F	Per Ilion, check over, repair as needed, and test at no charge
10281	597	26516	17 HMR	14-Oct-03	N	S	30-Apr-14	22-May-14	Other - Firearms	Other - Unspecified or Undetermined - Firearms	409019	F	Replacing with Ramac 70723 in exchange
10277	597	26550	22 LR	2-Oct-13	N	S	1-May-14	1-May-14	Went Automatic	Could Not Duplicate Concern	353894	F	Per Ilion, check over, repair as needed, and test at no charge
10282	597	26516	17 HMR	26-Jul-06	N	S	1-May-14	22-Oct-15	Other - Firearms	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10283	BACR	90838	5.56	24-Sep-13	N	S	2-May-14	2-May-14	Went Automatic	Could Not Duplicate Concern	356653	F	Per Ilion, check over, repair as needed, and test at no charge
10285	700	not avail.	7MM REM EX	1-Sep-79	N	S	2-May-14	7-Oct-14	Fired on Bolt Closing	Could Not Duplicate Concern	470220	F	Ilion repaired at n/c under BLM
10288	CARBON 15	90689	223/5.56	8-Dec-12	N	S	5-May-14	5-May-14	Went Automatic	Sent in for Evaluation	374504	F	Per Ilion - Repair at n/c - warranty
10290	700	not avail.	3006 SPR	4-Apr-72	N	S	5-May-14	16-May-14	Fired on Bolt Closing	Altered Adjustments or Components	406052	F	Per Ilion - Repair at n/c
10293	700	not avail.	3006 SPR	7-Mar-79	N	S	5-May-14	22-May-14	Fired on Bolt Opening	Could Not Duplicate Concern	409418	F	Per Ilion - Quote to repair under BLM & refinish
10289	Seven	29559	7mm SAUM	24-Feb-03	N	S	5-May-14	6-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
10294	700	25634	3006 SPRG	18-Jul-90	N	S	6-May-14	6-May-14	Fired on Bolt Closing	Improper Maintenance	387155	F	Repair @ n/c
10295	700	27475	243 WIN	9-Jul-09	N	PI/S	6-May-14	16-Jun-14	Fired on Bolt Closing	Could Not Duplicate Concern	415730	F	Repair @ n/c
10296	700	27099	300 WM	6-Jun-12	N	S	7-May-14	7-May-14	Fired on Safe Release	Broken or Missing Parts	395609	F	Per Ilion, replace trigger, check over and test fire at no charge
10297	700	N/A	3006 SPRG	27-May-88	N	S	7-May-14	7-May-14	Fired on Safe Release	Could Not Duplicate Concern	395642	F	Per Ilion, check over, repair as needed, and test at no charge
10305	700	27476	270 WIN	28-Jun-95	N	S	8-May-14	8-May-14	Delayed Firing - Firearms	Improper Maintenance	400935	F	Per Ilion, replace trigger, check over and test fire at no charge
10306	LR-308	90828	308 WIN	12-Apr-13	N	S	8-May-14	8-May-14	Went Automatic	Sent in for Evaluation	401119	F	Per Ilion, check over, repair as needed, and test at no charge
10307	700	84404	3006 SPRG	13-May-09	N	S	8-May-14	8-May-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	401067	F	Per Ilion, replace trigger, check over and test fire at no charge
10311	700	84215	223 REM	10-Jan-11	N	PD/S	9-May-14	4-Aug-14	Fired on Bolt Closing	Could Not Duplicate Concern	432576	F	Replace trigger at no charge. Reimburse damage to ceiling \$575.
10309	700	not avail.	3006 SPRG	3-Feb-81	N	S	12-May-14	12-May-14	Fired With Safe ON	Could Not Duplicate Concern	401789	F	Per Ilion - Repair at n/c

RAC001187

Confidential

10312	597	26516	17 HMR	26-Aug-03	N	PD/S	13-May-14	13-May-14	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	402114	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
10313	700	85351	223 REM	5-Mar-08	N	S	13-May-14	13-May-14	Fired on Bolt Closing	AFT MKT TRIGGER ASSM	402151	F	Per Ilion, replace trigger, check over and test fire at no charge
10314	700	27119	243 WIN	21-Jul-08	N	PD/S	13-May-14	19-Jun-14	Fired on Bolt Opening	Could Not Duplicate Concern	418453	F	Repair @ n/c
10316	597	26536	17 HMR	5-Nov-02	N	PI/PD/S	13-May-14	22-May-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	409119	F	Replacing with Ramac 70723 in exchange
10319	CARBON 15	90689	5.56	10-Apr-13	N	S	15-May-14	15-May-14	Went Automatic	Sent in for Evaluation	404279	F	Gun replaced by Consumer Service
10320	788	not avail.	308 WIN	27-Dec-78	Y	S	15-May-14	29-May-14	Fired on Safe Release	Improper Maintenance	413218	F	Quote to repair at a discount goodwill gesture
10321	700	N/A	3006 SPRG	28-Feb-74	N	S	16-May-14	16-May-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	405188	F	Per Ilion, replace trigger, check over and test fire at no charge
10323	700	27391	7MM-08	21-Mar-13	N	PD/S	16-May-14	4-Feb-15	Unexplained Discharge - No Mention of Safety Position	Not Examined by Product Service	331089	F	Gun not examined by Product Service
10327	597	N/A	17 HMR	18-Jun-03	N	PD/S	19-May-14	3-Jun-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	414850	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
10328	597	N/A	17 HMR	26-Mar-04	N	PD/S	19-May-14	3-Jun-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	414888	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
10331	700	25793	3006 SPR	14-Oct-94	N	S	19-May-14	6-Jun-14	Fired With Safe ON	Improper Maintenance	417515	F	Per Ilion, replace trigger, check over and test fire at no charge
10330	660	N/A	243 WIN	1-May-68	Y	S	20-May-14	20-May-14	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	407527	F	Per Ilion, replace trigger, check over and test fire at no charge
10332	700	85478	270 WIN	18-May-10	N	S	20-May-14	20-May-14	Fired on Bolt Closing	Could Not Duplicate Concern	407524	F	Per Ilion - Replace TA @ n/c to restore confidence
10333	700	25714	223 REM	8-May-13	N	S	20-May-14	20-May-14	Fired on Bolt Closing	Could Not Duplicate Concern	407781	F	Per Ilion, replace trigger, check over and test fire at no charge
10334	700	84461	308 WIN	24-Feb-10	N	S	20-May-14	20-May-14	Fired on Bolt Closing	Could Not Duplicate Concern	407806	F	Per Ilion, replace trigger, check over and test fire at no charge
10335	700	84207	308 WIN	13-Feb-12	N	S	20-May-14	20-May-14	Fired on Safe Release	Could Not Duplicate Concern	407834	F	Per Ilion, replace trigger, check over and test fire at no charge
10336	700	N/A	3006 SPRG	22-Jun-81	N	S	20-May-14	20-May-14	Fired on Safe Release	Could Not Duplicate Concern	407510	F	Per Ilion, replace trigger, check over and test fire at no charge
10338	700	27094	270 WIN	28-Jul-10	N	PD/S	20-May-14	28-Jul-14	Unexplained Discharge - No Mention of Safety Position	Over pressured shell	420338	F	Ilion repaired firearm and Lonoke will send customer ammunition replacement.

RAC001188

Confidential

10342	597	26516	17 HMR	14-Jan-04	N	PD/S	20-May-14	16-Jun-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	421594	O	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
10340	CARBON 15	90689	5.56	20-Mar-13	N	S	21-May-14	21-May-14	Went Automatic	Other - Unspecified or Undetermined - Firearms	408652	F	Per Ilion, replace trigger, check over and test fire at no charge
10343	700	27516	308 WIN	17-Nov-01	N	S	21-May-14	24-Jul-14	Fired on Bolt Closing	Altered Adjustments or Components	416743	F	Per Release - Replace w/29663 in exchange
10346	700	25798	223 REM	19-Feb-02	N	S	23-May-14	9-Jun-14	Fired on Bolt Closing	Could Not Duplicate Concern	417894	F	Per Ilion, replace trigger, check over and test fire at no charge
10347	597	26536	17 HMR	12-Feb-03	N	PD/S	27-May-14	12-Jun-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	420329	F	Replacing with Ramac 70723 in exchange
10348	700	27133	223 REM	29-Mar-12	N	S	28-May-14	28-May-14	Fired on Bolt Closing	Could Not Duplicate Concern	411366	F	Per Ilion, replace trigger, check over and test fire at no charge
10349	700	27516	308 WIN	25-May-04	N	S	28-May-14	28-May-14	Fired With Safe ON	Could Not Duplicate Concern	411772	F	Per Ilion, replace trigger, check over and test fire at no charge
10352	700	26129	3006 SPR	30-Oct-01	N	S	28-May-14	6-Apr-15	Delayed Firing - Firearms	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
10354	700	not avail.	3006 SPR		N	PD/S	28-May-14	6-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
10357	700	26285	7MM 08 REM	10-Jul-06	N	S	29-May-14	29-May-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	413568	F	Per Ilion, replace trigger, check over and test fire at no charge
10359	700	25933	7MM REM MA	15-Jan-96	N	S	29-May-14	29-May-14	Fired on Safe Release	Altered Adjustments or Components	413709	F	Per Ilion, replace trigger, check over and test fire at no charge
10360	700	84370	223 REM	11-Aug-08	N	S	29-May-14	29-May-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	413519	F	Per Ilion, replace trigger, check over, and test at no charge
10363	700	not avail.	7MM REM MA	24-Aug-78	N	S	29-May-14	6-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
10367	700	N/A	3006 SPRG	1-Dec-80	N	S	30-May-14	30-May-14	Fired on Bolt Closing	Could Not Duplicate Concern	414197	F	Per Ilion, replace trigger, check over and test fire at no charge
10368	700	25773	3006 SPRG 22-250 REM	19-Feb-90	N	S	30-May-14	30-May-14	Fired on Safe Release	Could Not Duplicate Concern	413883	F	Per Ilion, replace trigger, check over and test fire at no charge
10371	700	85434	REM	28-Dec-12	N	PD/S	2-Jun-14	22-Oct-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10372	VERSA MAX	81054	12 GA	28-Apr-11	N	S	3-Jun-14	3-Jun-14	Went Automatic	Broken or Missing Parts	415362	F	Per Ilion, check over, repair as needed, and test at no charge
10373	VERSA TACTICAL	81059	12 GA	11-Mar-14	N	S	3-Jun-14	18-Jun-14	Went Automatic	Could Not Duplicate Concern	415353	F	Returning as received
10378	700	27097	7MM REM MA	24-Jun-06	N	PD/S	3-Jun-14	24-Jun-14	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	427312	F	Check over completely, repair as needed, and test fire at no charge
10379	700	25791	270 WIN	25-Feb-13	N	S	3-Jun-14	3-Jul-14	Fired on Safe Release	Could Not Duplicate Concern	435004	F	Per Ilion, replace trigger, check over and test fire at no charge
10383	660	N/A	308 WIN	1-May-68	Y	S	6-Jun-14	6-Jun-14	Fired on Bolt Closing	Improper Maintenance	417162	F	Per Ilion, replace trigger, check over and test fire at no charge

RAC001189

Confidential

10384	CARBON 15	90689	5.56	26-Feb-13	N	S	6-Jun-14	6-Jun-14	Went Automatic	Other - Unspecified or Undetermined - Firearms	417246	F	Per Ilion, check over, repair as needed, and test at no charge
10387	700	25787	243 WIN	11-Dec-02	N	S	9-Jun-14	9-Jun-14	Fired on Safe Release	Improper Maintenance	418640	F	Per Ilion, replace trigger, check over and test fire at no charge
10388	XP100	25387	260 REM	23-Dec-97	Y	S	9-Jun-14	9-Jun-14	Fired on Safe Release	Altered Adjustments or Components	418916	F	Per Ilion, replace trigger, check over and test fire at no charge
10389	597	26550	22 LR	25-Apr-00	N	PD/S	9-Jun-14	9-Jun-14	Went Automatic	Other - Unspecified or Undetermined - Firearms	418531	F	Per Ilion, check over, repair as needed, and test at no charge
10393	700	27092	243 WIN	30-Apr-10	N	S	10-Jun-14	22-Oct-15	Fired on Bolt Opening	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10398	700	27094	270 WIN	23-Apr-10	N	S	11-Jun-14	25-Jun-14	Fired on Safe Release	Could Not Duplicate Concern	429208	F	Per Ilion, replace trigger, check over and test fire at no charge
10397	700	N/A	3006 SPRG	19-Dec-77	N	S	12-Jun-14	12-Jun-14	Fired on Safe Release	Could Not Duplicate Concern	420100	F	Per Ilion, replace trigger, check over and test fire at no charge
10399	700	25955	3006 SPR	10-Nov-04	N	S	12-Jun-14	3-Jul-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	435099	F	Ilion repaired at n/c
10402	700	84205	300 Blacko	28-Aug-13	N	S	12-Jun-14	12-Jun-14	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Consumer refused to provide his name, address & phone #
10404	700	not avail.	243 WIN	16-Nov-80	N	PI/PD/S	12-Jun-14	25-Jul-14	Fired on Bolt Opening	Could Not Duplicate Concern	430338	F	Repair @ n/c
10405	770	85632	270 WIN	21-May-13	N	PD/S	13-Jun-14	13-Jun-14	Barrel Burst/Split (Other than Chamber)	Fired While Obstructed	420752	F	Replacing with Ramac 85632 in exchange
10406	700	26989	3006 SPRG	13-Jan-97	N	S	13-Jun-14	13-Jun-14	Fired on Bolt Closing	Altered Adjustments or Components	420343	F	Per Ilion, replace trigger, check over and test fire at no charge
10408	700	85374	3006 SPRG	11-Mar-08	N	PI/S	13-Jun-14	25-Jul-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	431629	F	Repair @ n/c
10414	1911 R1	96323	45 ACP	29-Mar-12	N	S	17-Jun-14	17-Jun-14	Went Automatic	Could Not Duplicate Concern	423272	F	Per Ilion, check over, repair as needed, and test at no charge
10415	700	N/A	7MM REM MA	14-May-09	N	PD/S	17-Jun-14	21-Jul-14	Fired on Bolt Closing	Could Not Duplicate Concern	445070	F	Check over completely, repair as needed, and test fire at no charge
10416	BACR	90838	5.56	18-Jul-13	N	S	18-Jun-14	18-Jun-14	Went Automatic	Other - Unspecified or Undetermined - Firearms	423679	F	Per Ilion - Repair at n/c
10417	700	not avail.	300 RUM 7MM REM MA		N	S	18-Jun-14	18-Jun-14	Unexplained Discharge - No Mention of Safety Position	Not Examined by Product Service	n/a	F	Referred customer to Gravel Agency in Canada
10418	700	25803	7MM REM MA	7-Oct-85	N	S	18-Jun-14	1-Jul-14	Fired on Bolt Closing	Improper Maintenance	432835	F	Ilion repaired at n/c
10420	700	N/A	6MM REM	1-Jan-68	N	S	19-Jun-14	19-Jun-14	Fired on Safe Release	Improper Maintenance	424902	F	Per Ilion, replace trigger, check over and test fire at no charge
10423	700	N/A	22-250 REM	22-Dec-94	N	PD/S	19-Jun-14	25-Jul-14	Fired on Bolt Closing	Altered Adjustments or Components	450070	F	Replace trigger, check over, and test at no charge

RAC001190

Confidential

10426	700	27017	3006 SPRG	17-Mar-05	N	S	20-Jun-14	25-Jul-14	Fired on Safe Release	AFT MKT TRIGGER ASSM	426726	F	Per Ilion - Repair at n/c - goodwill
10428	700	84216	22-250 REM	22-Dec-11	N	S	20-Jun-14	20-Jun-14	Fired on Bolt Closing	Altered Adjustments or Components	426545	F	Per Ilion, replace trigger, check over and test fire at no charge
10432	700	26440	300 WIN MA	20-Jul-04	N	S	23-Jun-14	23-Jun-14	Other - Firearms	Altered Adjustments or Components	427465	O	Per Ilion, replace trigger, check over and test fire at no charge
10433	597	26537	22 LR	5-Sep-08	N	S	23-Jun-14	23-Jul-14	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	427439	F	Replace w/26537 in exchange
10435	700	n/a	270 WIN	1-Oct-79	N	S	23-Jun-14	23-Jun-14	Fired With Safe ON	Could Not Duplicate Concern	427325	F	Ilion repaired at n/c
10436	1911 R1	96323	45 ACP	14-Apr-14	N	S	23-Jun-14	23-Jun-14	Fired With Safe ON	Other - Unspecified or Undetermined - Firearms	427529	F	Per Ilion, check over, repair as needed, and test at no charge
10452	7	N/A	243 WIN	20-Mar-84	N	S	24-Jun-14	15-Jul-14	Fired on Bolt Closing	Improper Maintenance	443830	F	Check over completely, repair as needed, and test fire at no charge
10440	700	84165	300 RUM	14-Feb-14	N	S	25-Jun-14	25-Jun-14	Fired on Safe Release	Not Examined by Product Service	406105	F	Per Ilion, replace trigger, check over and test fire at no charge
10441	887	82500	12 GA	12-Nov-13	N	S	25-Jun-14	25-Jun-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	429143	F	Per Ilion, check over, repair as needed, and test at no charge
10443	722	N/A	308 WIN	1-Jun-55	Y	S	25-Jun-14	25-Jun-14	Fired on Bolt Opening	Altered Adjustments or Components	429223	F	Per Ilion, quote to repair BLM
10453	700	N/A	25-06 REM	10-Apr-75	N	S	25-Jun-14	14-Jul-14	Fired on Safe Release	Could Not Duplicate Concern	439913	F	Check over completely, repair as needed, and test fire at no charge
9711	700	26031	25-06 REM	27-Jan-98	N	S	26-Jun-14	26-Jun-14	Fired on Safe Release	Altered Adjustments or Components	430283	F	Per Ilion, replace trigger, check over and test fire at no charge
10445	700	N/A	3006 SPRG	16-Sep-70	N	S	26-Jun-14	26-Jun-14	Fired on Bolt Closing	Improper Maintenance	429231	F	Per Ilion, replace trigger, check over and test fire at no charge
10446	700	N/A	270 WIN	17-Nov-71	N	S	26-Jun-14	26-Jun-14	Fired on Bolt Closing	Improper Maintenance	429265	F	Per Ilion, replace trigger, check over and test fire at no charge
10447	700	N/A	7MM REM MA	22-Nov-82	N	S	26-Jun-14	26-Jun-14	Fired on Bolt Closing	Improper Maintenance	430010	F	Per Ilion, replace trigger, check over and test fire at no charge
10448	600	N/A	35 REM	1-Jul-65	Y	S	26-Jun-14	26-Jun-14	Fired on Bolt Closing	Improper Maintenance	430036	F	Per Ilion, replace trigger, check over and test fire at no charge
10449	700	27009	2506 REM	5-Oct-10	N	S	26-Jun-14	26-Jun-14	Fired on Safe Release	Could Not Duplicate Concern	430533	F	Per Ilion, replace trigger, check over and test fire at no charge
10450	BR 308	90702	308 WIN	18-Dec-13	N	S	26-Jun-14	26-Jun-14	Fired on Bolt Closing	Could Not Duplicate Concern	430093	F	Per Ilion, check over, repair as needed, and test at no charge
10455	700	26096	300 RUM	11-Apr-01	N	S	30-Jun-14	23-Jul-14	Fired on Safe Release	Could Not Duplicate Concern	449921	F	Per Ilion, replace trigger, check over and test fire at no charge
10456	700	85374	3006 SPRG	22-Dec-09	N	PI/S	30-Jun-14	28-Dec-15	Fired With Safe ON	Could Not Duplicate Concern	507534	F	Per Ilion - Replace TA & test @ n/c
10457	CARBON 15	90689	5.56	21-Feb-11	N	S	1-Jul-14	1-Jul-14	Went Automatic	Could Not Duplicate Concern	433275	F	Per Ilion - Repair at n/c
10458	XM10	90702	308 WIN	27-Mar-13	N	S	1-Jul-14	1-Jul-14	Went Automatic	Sent in for Evaluation	431617	F	Per Ilion - Repair at n/c - warranty

RAC001191

Confidential

10459	597	RECEIVER	17 HMIR	9-Jan-04	N	PD/S	1-Jul-14	6-Aug-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	431373	F	Converting to 22 WMIR as requested by customer, repair and check over completely at no charge.
10465	CARBON 15	90863	5.56	13-Sep-11	N	S	2-Jul-14	2-Jul-14	Went Automatic	Sent in for Evaluation	433566	F	Per Ilion - Repair at n/c
10467	700	26129	3006 SPRG	13-Jul-00	N	S	2-Jul-14	1-Aug-14	Fired on Safe Release	Could Not Duplicate Concern	453245	F	Ilion repaired at n/c
10468	700	n/a	270 WIN	18-Mar-70	N	PD/S	3-Jul-14	11-Dec-14	Remington Firearm Damaged while using Remington Ammunition	Improper Maintenance	479117	A	Per Ilion - Repair at n/c
10469	770	85663	3006 SPRG	1-Sep-10	N	S	7-Jul-14	26-Aug-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	461146	F	Per Ilion, replace trigger, check over and test fire at no charge
10470	700	N/A	3006 SPR	16-Jul-76	N	S	7-Jul-14	25-Jul-14	Fired on Safe Release	Could Not Duplicate Concern	450869	F	Per Ilion, replace trigger, check over and test fire at no charge
10472	700	25787	243 WIN	17-May-12	N	PD/S	8-Jul-14	26-Mar-15	Fired on Bolt Closing	Could Not Duplicate Concern	453869	F	Check over completely, repair as needed, and test fire at no charge
10473	552	not avail.	22 LR		N	PI/S	8-Jul-14	7-Aug-15	Ammunition Exploded	Not Examined by Product Service	not avail.	A	
10475	700	85569	308 WIN	7-Feb-13	N	PI/PD/S	10-Jul-14	14-Nov-14	Fired on Bolt Closing	Could Not Duplicate Concern	448967	F	Per Release - Replace gun w/Item# 84218, replace scope & send ammo
10477	700	not avail.	243 WIN	13-Feb-70	N	S	11-Jul-14	1-Aug-14	Fired on Bolt Closing	Could Not Duplicate Concern	453355	F	Ilion repaired at n/c
10479	700	N/A	35 WHELEN	28-Jul-88	N	S	14-Jul-14	14-Jul-14	Fired on Bolt Closing	Altered Adjustments or Components	442047	F	Per Ilion, replace trigger, check over and test fire at no charge
10480	700	N/A	270 WIN	20-Nov-78	N	S	14-Jul-14	14-Jul-14	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	439995	F	Per Ilion, replace trigger, check over and test fire at no charge
10481	710	27410	3006 SPRG	22-May-02	Y	S	14-Jul-14	14-Jul-14	Fired on Bolt Closing	Could Not Duplicate Concern	437401	F	Per Ilion, check over, repair as needed, and test at no charge
10482	700	n/a	3006 SPRG	10-Mar-77	N	S	14-Jul-14	13-Aug-14	Fired on Bolt Closing	Improper Maintenance	456454	F	Ilion repaired at n/c
10487	700	not avail.	3006 SPRG	1-Aug-75	N	PD/S	15-Jul-14	22-Sep-14	Fired on Bolt Closing	Improper Maintenance	459616	F	Repair @ n/c - goodwill gesture
10488	700	85430	2506 REM	1-Feb-13	N	S	16-Jul-14	16-Jul-14	Unexplained Discharge - No Mention of Safety Position	Returned due to Recall	415980	F	Cleaned and reset trigger under recall
10489	1187	83700	12 GA	5-Sep-13	N	S	16-Jul-14	16-Jul-14	Went Automatic	Could Not Duplicate Concern	446964	F	Per Release Replacing with Ramac 83700 in exchange
10493	700	n/a	7MM REM MA	26-Sep-73	N	S	17-Jul-14	17-Jul-14	Fired on Safe Release	Could Not Duplicate Concern	447090	F	Per Ilion - Repair at n/c
10495	700	N/A	7MM REM EX	12-Sep-79	N	PI/S	18-Jul-14	11-Sep-14	Fired on Safe Release	Could Not Duplicate Concern	462652	F	Check over completely, repair as needed, and test fire at no charge
10501	700	N/A	270 WIN	21-Feb-75	N	PD/S	18-Jul-14	14-Aug-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	453367	F	Check over completely, repair as needed, and test fire at no charge

RAC001192

Confidential

10502	700	25791	270 WIN	12-Dec-95	N	S	18-Jul-14	1-Aug-14	Other - Does not trust firearm	Could Not Duplicate Concern	453357	O	Per Ilion, replace trigger, check over and test fire at no charge
10504	700	N/A	22-250 REM	22-May-73	N	PD/S	18-Jul-14	28-Aug-14	Fired on Safe Release	Improper Maintenance	461056	F	Check over completely, repair as needed, and test fire at no charge
10496	700	N/A	3006 SPRG	12-Aug-75	N	S	21-Jul-14	21-Jul-14	Fired on Safe Release	Could Not Duplicate Concern	448317	F	Per Ilion, replace trigger, check over, and test at no charge
10497	700	85566	308 WIN	8-Apr-09	N	S	21-Jul-14	21-Jul-14	Fired on Safe Release	Could Not Duplicate Concern	447522	F	Ilion repaired at n/c
10513	700	N/A	243 WIN	19-Apr-72	N	S	21-Jul-14	31-Jul-14	Fired on Bolt Closing	Could Not Duplicate Concern	453033	F	Per Ilion, replace trigger, check over and test fire at no charge
10507	700	n/a	17 REM	5-Oct-71	N	S	22-Jul-14	22-Jul-14	Fired on Bolt Closing	Broken or Missing Parts	448236	F	Per Ilion - Replace TA @ n/c, Quote to replace stock
10509	700	N/A	3006 SPRG	24-Oct-73	N	S	22-Jul-14	22-Jul-14	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	448242	F	Per Ilion, replace trigger, check over and test fire at no charge
10510	660	N/A	350 REM MA	25-Mar-75	Y	S	22-Jul-14	22-Jul-14	Fired on Bolt Closing	Altered Adjustments or Components	449302	F	Per Ilion, replace trigger, check over and test fire at no charge
10511	700	N/A	3006 SPRG	25-Apr-75	N	S	22-Jul-14	22-Jul-14	Fired on Safe Release	Improper Maintenance	449258	F	Per Ilion, replace trigger, check over and test fire at no charge
10515	700	29709	270 WIN	1-Mar-99	N	S	23-Jul-14	23-Jul-14	Fired on Safe Release	Could Not Duplicate Concern	449757	F	Per Ilion, replace trigger, check over and test fire at no charge
10516	700	N/A	3006 SPRG	1-Sep-74	N	S	23-Jul-14	23-Jul-14	Fired on Safe Release	Altered Adjustments or Components	449735	F	Per Ilion, replace trigger, check over and test fire at no charge
10519	700	n/a	270 WIN	8-Jun-71	N	S	23-Jul-14	11-Aug-14	Fired on Safe Release	Altered Adjustments or Components	454964	F	Ilion repaired at n/c
10521	700	N/A	270 WIN	1-Apr-74	N	S	23-Jul-14	15-Aug-14	Fired on Bolt Closing	Could Not Duplicate Concern	457826	F	Per Ilion, replace trigger, check over and test fire at no charge
10526	700	N/A	3006 SPR	7-Jul-77	N	S	23-Jul-14	11-Aug-14	Fired on Safe Release	Improper Maintenance	453922	F	Per Ilion, replace trigger, check over and test fire at no charge
10520	700	20000	22-250 REM		N	PD/S	23-Jul-14	22-Oct-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10523	700	25793	3006 SPRG	24-Aug-12	N	S	24-Jul-14	24-Jul-14	Fired on Bolt Closing	Could Not Duplicate Concern	428823	F	Per Release - refund \$804.99
10524	7	24741	7MM08 REM	9-Oct-96	N	S	24-Jul-14	24-Jul-14	Fired on Bolt Closing	Could Not Duplicate Concern	450308	F	Per Ilion, replace trigger, check over and test fire at no charge
10530	700	25634	3006 SPRG	9-Apr-86	N	S	25-Jul-14	25-Jul-14	Fired on Safe Release	Altered Adjustments or Components	451479	F	Per Ilion, replace trigger, check over and test fire at no charge
10531	700	25634	3006 SPRG	1-Apr-86	N	S	25-Jul-14	25-Jul-14	Fired on Safe Release	Altered Adjustments or Components	451476	F	Ilion repaired at n/c
10537	597	26536	17 HMR	27-Jun-03	N	PI/PD/S	28-Jul-14	15-Aug-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	457576	O	Replacing with Ramac 70703 in exchange
10532	700	27097	7MM MAG	3-Oct-11	N	PD/S	28-Jul-14	16-Feb-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	487889	F	Repair @ n/c under XMP recall

RAC001193

Confidential

10539	700	84207	308 WIN	12-Jan-12	N	S	29-Jul-14	29-Jul-14	Fired on Safe Release	Could Not Duplicate Concern	417972	F	Ilion repaired at n/c
10540	Sportsman 78	26162	270 WIN	27-May-86	Y	S	29-Jul-14	29-Jul-14	Fired on Safe Release	Could Not Duplicate Concern	451914	F	Ilion repaired at n/c
10542	722	n/a	222 REM	1-Dec-51	Y	S	29-Jul-14	29-Jul-14	Fired on Safe Release	Altered Adjustments or Components	451831	F	Per Ilion - Quote to repair under BLM
10543	700	n/a	3006 SPRG	24-Jun-76	N	S	29-Jul-14	29-Jul-14	Fired on Safe Release	Could Not Duplicate Concern	451830	F	Ilion repaired at n/c
10544	700	27093	243 WIN	13-Jun-11	N	S	29-Jul-14	29-Jul-14	Light Trigger Pull	Could Not Duplicate Concern	427531	F	Per Ilion, replace trigger, check over and test fire at no charge
10546	700	26917	308 WIN	24-Feb-95	N	S	30-Jul-14	30-Jul-14	Fired on Bolt Closing	Could Not Duplicate Concern	452382	F	Ilion repaired at n/c
10548	870	81150	20 GA	14-Feb-14	N	S	30-Jul-14	30-Jul-14	Fired on Bolt Closing	Could Not Duplicate Concern	452217	F	Per Ilion - Repair at n/c - warranty
10554	700	25971	300 RUM	16-Mar-01	N	S	31-Jul-14	31-Jul-14	Fired With Safe ON	Could Not Duplicate Concern	452951	F	Per Ilion, replace trigger, check over and test fire at no charge
10557	700	N/A	3006 SPRG	16-Mar-82	N	S	1-Aug-14	1-Aug-14	Delayed Firing - Firearms	Improper Maintenance	451942	F	Per Ilion, replace trigger, check over and test fire at no charge, replace stock at 30% discount
10558	700	25791	270 WIN	20-Jun-86	N	S	1-Aug-14	1-Aug-14	Fired on Bolt Closing	Altered Adjustments or Components	453158	F	Per Ilion, replace trigger, check over and test fire at no charge
10560	721	not avail.	270 WIN	1-Oct-48	Y	PD/S	1-Aug-14	19-Aug-14	Fired on Safe Release	Could Not Duplicate Concern	459344	F	Per Ilion - Repair at n/c
10566	700	n/a	3006 SPRG	3-Apr-69	N	S	6-Aug-14	21-Aug-14	Fired on Bolt Closing	Improper Maintenance	459985	F	Ilion repaired at n/c
10569	700	27333	300 WSM	13-May-13	N	S	7-Aug-14	3-Sep-14	Fired on Bolt Closing	Could Not Duplicate Concern	462752	F	Replaced rifle w/84017 & placed order for 1 case of ammo 29489
10573	700	84016	7MM REM MA	23-Mar-07	N	S	11-Aug-14	11-Aug-14	Unexplained Discharge - No Mention of Safety Position	Not Examined by Product Service	409260	F	Per Ilion, XMP update
10574	700	27095	3006 SPRG	2-Jan-13	N	S	11-Aug-14	11-Aug-14	Unexplained Discharge - No Mention of Safety Position	Not Examined by Product Service	428132	F	Per Ilion, repair and test
10575	700	n/a	270 WIN 22/250	1-Mar-74	N	S	11-Aug-14	11-Aug-14	Fired on Safe Release	Altered Adjustments or Components	451780	F	Ilion repaired at n/c
10576	788	n/a	REM	8-May-70	Y	S	11-Aug-14	11-Aug-14	Fired With Safe ON	Sent in for Evaluation	455288	F	Per Ilion - Quote to repair @ discount
10577	700	N/A	3006 SPRG	1-Feb-63	N	S	11-Aug-14	11-Aug-14	Fired on Bolt Closing	Could Not Duplicate Concern	454109	F	Per Ilion, replace trigger, check over and test fire at no charge
10578	700	N/A	7MM REM MA	1-Aug-67	N	S	11-Aug-14	11-Aug-14	Fired on Bolt Closing	Could Not Duplicate Concern	453539	F	Per Ilion, replace trigger, check over and test fire at no charge
10579	700	26963	7MM08 REM	18-Mar-96	N	S	11-Aug-14	11-Aug-14	Fired on Safe Release	Altered Adjustments or Components	455233	F	Per Ilion, replace trigger, check over and test fire at no charge
10583	597	26516	17 HMR	20-Mar-03	N	PD/S	11-Aug-14	11-Aug-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	454834	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
10584	700	26035	3006 SPRG	12-Mar-99	N	S	12-Aug-14	12-Aug-14	Fired on Safe Release	Improper Maintenance	454115	F	Per Ilion, replace trigger, check over and test fire at no charge

RAC001194

Confidential

10585	XP 100	N/A	221 FB	20-Mar-79	Y	S	12-Aug-14	12-Aug-14	Fired on Bolt Closing	Improper Maintenance	454038	F	Per Ilion, replace trigger, check over and test fire at no charge
10586	700	N/A	308 WIN	16-Feb-76	N	S	12-Aug-14	12-Aug-14	Fired on Bolt Closing	Altered Adjustments or Components	455029	F	Per Ilion, replace trigger, check over and test fire at no charge
10587	BR 308	90828	308 WIN	23-Dec-13	N	S	12-Aug-14	12-Aug-14	Went Automatic	Could Not Duplicate Concern	453497	F	Per Ilion, replace trigger, check over and test fire at no charge
10588	700	N/A	3006 SPRG	25-Mar-75	N	S	13-Aug-14	13-Aug-14	Fired on Safe Release	Could Not Duplicate Concern	455794	F	Per Ilion, replace trigger, check over and test fire at no charge
10589	700	84179	7MM REM MA	15-Oct-12	N	S	13-Aug-14	13-Aug-14	Fired on Safe Release	Could Not Duplicate Concern	457088	F	Per Ilion, replace trigger, check over and test fire at no charge
10592	700	27476	270 WIN	31-May-00	N	S	14-Aug-14	14-Aug-14	Fired on Safe Release	Could Not Duplicate Concern	456231	F	Ilion repaired at n/c
10593	700	25871	17 REM	29-Sep-99	N	S	14-Aug-14	14-Aug-14	Fired on Bolt Closing	Improper Maintenance	457537	F	Per Ilion, replace trigger, check over and test fire at no charge
10594	700	25773	3006 SPRG	13-Feb-01	N	S	14-Aug-14	14-Aug-14	Fired on Safe Release	Improper Maintenance	457536	F	Per Ilion, replace trigger, check over and test fire at no charge
10595	700	25777	7MM REM MA	10-Mar-86	N	S	14-Aug-14	14-Aug-14	Fired on Safe Release	Broken or Missing Parts	457538	F	Per Ilion, replace trigger, check over and test fire at no charge
10602	700	84207	308 WIN	18-Sep-13	N	S	15-Aug-14	15-Aug-14	Fired on Bolt Closing	Could Not Duplicate Concern	458082	F	Ilion repaired at n/c
10603	700	n/a	3006 SPRG	2-May-75	N	S	15-Aug-14	15-Aug-14	Fired on Bolt Closing	Altered Adjustments or Components	457486	F	Ilion repaired at n/c
10604	710	27410	3006 SPRG	31-Mar-01	Y	S	15-Aug-14	15-Aug-14	Fired on Bolt Closing	Improper Maintenance	457998	F	Per Ilion - Quote to repair @ discount
10606	700	N/A	25-06 REM		N	S	15-Aug-14	6-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
10608	700	N/A	3006 SPR	1-Jul-68	N	S	18-Aug-14	29-Aug-14	Fired on Bolt Closing	Improper Maintenance	461790	F	Per Ilion, replace trigger, check over and test fire at no charge
10611	783	85836	3006 SPRG	18-Jun-13	N	S	19-Aug-14	19-Aug-14	Fired With Safe ON	Broken or Missing Parts	459320	F	Per Ilion, replace trigger, check over and test fire at no charge
10612	750	85684	308 WIN	12-Feb-08	N	S	19-Aug-14	19-Aug-14		Sent in for Evaluation	459310	F	Per Ilion, check over, repair as needed, and test at no charge
10613	700	85373	270 WIN	22-Sep-11	N	PI/S	19-Aug-14	22-Oct-15	Unexplained Discharge - No Mention of Safety Position	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10619	700	29701	22-250 REM	20-Feb-01	N	S	21-Aug-14	21-Aug-14	Fired With Safe ON	Altered Adjustments or Components	459943	F	Per Ilion, replace trigger, check over and test fire at no charge
10621	700	26107	300 RUM	29-Jan-01	N	S	21-Aug-14	21-Aug-14	Fired on Safe Release	Could Not Duplicate Concern	459216	F	Per Ilion, replace trigger, check over and test fire at no charge
10623	870	82001	20 GA	4-Sep-07	N	S	21-Aug-14	21-Aug-14	Delayed Firing - Firearms	Sent in for Evaluation	459696	F	Per Ilion, replace trigger, check over and test fire at no charge
10627	700	27094	270 WIN	12-Mar-14	N	S	21-Aug-14	9-Oct-14	Fired on Safe Release	Could Not Duplicate Concern	464152	F	TA replaced @ n/c

RAC001195

Confidential

10628	700 trigger only	N/A			N	S	22-Aug-14	26-Sep-14	Unexplained Discharge - No Mention of Safety Position	No Fault Found	451536	F	Customer request do not return trigger.
10629	700	85491	3006 SPRG	23-Jul-10	N	S	22-Aug-14	22-Aug-14	Fired With Safe ON	Could Not Duplicate Concern	460471	F	Per Ilion, replace trigger, check over and test fire at no charge
10631	721	N/A	3006 SPRG	1-May-53	Y	S	22-Aug-14	22-Aug-14	Fired With Safe ON	Improper Maintenance	460077	F	Per Ilion, quote to repair BLM
10632	700	84203	308 WIN	11-Jul-11	N	S	22-Aug-14	22-Aug-14	Fired on Safe Release	Could Not Duplicate Concern	460735	F	Per Ilion, replace trigger, check over and test fire at no charge
10634	700	84373	22-250 REM	18-Feb-08	N	S	25-Aug-14	25-Aug-14	Unexplained Discharge Safe ON	Could Not Duplicate Concern	460807	F	Per Ilion, replace trigger, check over and test fire at no charge
10635	ACR	90838	223/5.56	27-Sep-13	N	S	25-Aug-14	25-Aug-14	Went Automatic	Could Not Duplicate Concern	460758	F	Per Ilion, check over, repair as needed, and test at no charge
10636	SEVEN	85952	223 REM	25-Apr-08	N	PD/S	25-Aug-14	17-Nov-14	Fired on Bolt Closing	Could Not Duplicate Concern	466342	F	Repair of rifle and check for \$1,500.00 compensation for property damage
9595	7400	N/A	3006 SPR	1-Apr-81	Y	PD/S	26-Aug-14	3-Sep-14	Ammunition Exploded	Sent in for Evaluation	462103	A	Check over completely, repair as needed, and test fire at no charge
10638	710	27410	3006 SPRG	19-Jun-05	Y	S	26-Aug-14	23-Sep-14	Fired on Bolt Closing	Broken or Missing Parts	467027	F	Per Ilion - Repair at n/c
10639	700	26281	270 WIN	14-Apr-08	N	PD/S	27-Aug-14	26-Sep-14	Fired on Safe Release	Could Not Duplicate Concern	467599	F	Check over completely, repair as needed, and test fire at no charge
10642	597	26516	17 HMR	31-Jan-05	N	PI/PD/S	27-Aug-14	17-Dec-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	n/a	F	Replace with Ramac 26581 in exchange
10640	700	85205	308 WIN	28-Oct-13	N	S	28-Aug-14	28-Aug-14	Fired on Bolt Closing	Could Not Duplicate Concern	461697	F	Ilion repaired at n/c
10647	600	N/A	243 WIN	4-Jun-75	Y	S	29-Aug-14	29-Aug-14	Fired on Bolt Opening	Could Not Duplicate Concern	461733	F	Per Ilion, replace trigger, check over and test fire at no charge
10649	700	N/A	3006 SPRG	1-Jun-74	N	S	3-Sep-14	3-Sep-14	Fired on Bolt Closing	Could Not Duplicate Concern	462403	F	Per Ilion, replace trigger, check over and test fire at no charge
10650	700	84373	22-250REM	22-Dec-09	N	S	3-Sep-14	3-Sep-14	Fired on Bolt Closing	Could Not Duplicate Concern	462799	F	Per Ilion, replace trigger, check over and test fire at no charge
10651	700	N/A	7MM REM MA	28-May-75	N	S	3-Sep-14	3-Sep-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	462656	F	Per Ilion, replace trigger, check over and test fire at no charge
10654	700	84218	308 WIN	22-Nov-13	N	S	3-Sep-14	6-Oct-14	Fired on Bolt Closing	Sent in for Evaluation	464568	F	Ilion repaired at n/c
10659	700	N/A	7MM REM MA	12-Jun-75	N	S	5-Sep-14	5-Sep-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	463260	F	Per Ilion, replace trigger, check over and test fire at no charge
10660	700	N/A	243 WIN	18-Oct-77	N	S	5-Sep-14	5-Sep-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	4633270	F	Per Ilion, replace trigger, check over and test fire at no charge
10661	600	N/A	243 WIN	22-Sep-76	N	S	5-Sep-14	5-Sep-14	Fired on Safe Release	Broken or Missing Parts	463446	F	Per Ilion, replace trigger, check over and test fire at no charge

RAC001196

Confidential

10662	700	27478	3006 SPRG	6-Jun-97	N	S	5-Sep-14	5-Sep-14	Fired on Bolt Closing	Could Not Duplicate Concern	463383	F	Per Ilion, replace trigger, check over and test fire at no charge
10663	700	N/A	2506 REM	6-Apr-76	N	S	5-Sep-14	5-Sep-14	Fired on Safe Release	Altered Adjustments or Components	463319	F	Per Ilion, replace trigger, check over and test fire at no charge
10672	700	N/A	7MM REM MA	8-Nov-75	N	S	5-Sep-14	30-Sep-14	Fired on Bolt Closing	Altered Adjustments or Components	468590	F	Per Ilion, replace trigger, check over and test fire at no charge
10667	700	not avail.	3006 SPRG		N	S	5-Sep-14	6-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
10670	700	27167	30-06 SPRG	9-Aug-05	N	S	8-Sep-14	8-Sep-14	Fail to Fire	Could Not Duplicate Concern	463695	F	Per Ilion, replace trigger, check over and test fire at no charge
10675	700	N/A	3006SPR	13-Jul-77	N	S	9-Sep-14	9-Sep-14	Delayed Firing - Firearms	Improper Maintenance	463623	F	Per Ilion, replace trigger, check over and test fire at no charge
10676	700	N/A	3006SPRG	17-Mar-75	N	S	9-Sep-14	9-Sep-14	Fired on Bolt Closing	Could Not Duplicate Concern	463844	F	Per Ilion, replace trigger, check over and test fire at no charge
10677	VersaMax	81049	12GA	7-May-13	N	S	9-Sep-14	9-Sep-14	Unexplained Discharge - Safe ON	Could Not Duplicate Concern	464060	F	Replacing with Ramac 81049 in exchange
10679	700	N/A	243 WIN	17-Oct-80	N	S	9-Sep-14	3-Oct-14	Fired on Safe Release	Could Not Duplicate Concern	469555	F	Per Ilion, replace trigger, check over and test fire at no charge
10680	700	N/A	243 WIN	1-Feb-79	N	S	9-Sep-14	6-Oct-14	Fired on Safe Release	Could Not Duplicate Concern	469560	F	Per Ilion, replace trigger, check over and test fire at no charge
10684	700	26425	3006 SPRG	7-Sep-06	N	PD/S	10-Sep-14	1-Oct-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	467572	F	Replace TA & test
10687	SPORTSMAN 78	26162	270 WIN	3-Jul-84	N	S	11-Sep-14	11-Sep-14	Fired on Safe Release	Could Not Duplicate Concern	464436	F	Per Ilion, replace trigger, check over and test fire at no charge
10688	700	85478	270WIN	18-Aug-11	N	S	11-Sep-14	11-Sep-14	Fired on Bolt Closing	Could Not Duplicate Concern	464429	F	Per Ilion, replace trigger, check over and test fire at no charge
10691	700	29696	338WINMAG	19-Jul-04	N	S	12-Sep-14	12-Sep-14	Fired on Safe Release	Could Not Duplicate Concern	464979	F	Per Ilion, replace trigger, check over and test fire at no charge
10692	700	85414	3006 SPRG	13-May-09	N	S	12-Sep-14	12-Sep-14	Fired on Safe Release	Could Not Duplicate Concern	465357	F	Per Ilion, replace trigger, check over and test fire at no charge
10693	700	N/A	3006SPRG	1-Oct-65	N	S	12-Sep-14	11-Sep-14	Fired on Safe Release	Could Not Duplicate Concern	465356	F	Per Ilion, replace trigger, check over and test fire at no charge
10695	887	82500	12 GA	23-Jun-14	N	S	15-Sep-14	15-Sep-14	Fired on Bolt Closing	Could Not Duplicate Concern	465571	F	Per Ilion - Repair at n/c
10700	700	not avail.	3006 SPR	28-Oct-81	N	S	15-Sep-14	6-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
10702	700	27007	243 WIN	12-Apr-06	N	S	16-Sep-14	16-Sep-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	465538	F	Ilion repaired at n/c
10704	660	n/a	243WIN	24-Aug-73	Y	S	16-Sep-14	16-Sep-14	Fired on Safe Release	Altered Adjustments or Components	465931	F	Per Ilion - Repair at n/c
10706	CARBON 15	91037	5.56 NATO	25-Feb-14	N	S	16-Sep-14	16-Sep-14	Went Automatic	Other - Unspecified or Undetermined - Firearms	465734	F	Ilion repaired at n/c

RAC001197

Confidential

10707	BACR	90704	5.56 NATO	28-Jul-10	N	S	16-Sep-14	16-Sep-14	Went Automatic	Other - Unspecified or Undetermined - Firearms	465878	F	Per Ilion, check over, repair as needed, and test at no charge
10711	700	N/A	3006 SPRG	7-Oct-82	N	S	17-Sep-14	17-Sep-14	Fired on Bolt Closing	Could Not Duplicate Concern	466074	F	Per Ilion, replace trigger, check over and test fire at no charge
10712	770	85630	243 WIN	3-Mar-09	N	S	17-Sep-14	17-Sep-14	Fired on Bolt Opening	Could Not Duplicate Concern	466071	O	Per Ilion, replace trigger, check over and test fire at no charge
10716	870	81111	12GA	10-Mar-10	N	PD/S	19-Sep-14	30-Oct-14	Fired Out of Battery	Sent in for Evaluation	466318	F	Check over completely, repair as needed, and test at no charge
10717	700	n/a	243 WIN	3-Jun-76	N	S	19-Sep-14	19-Sep-14	Fired on Bolt Closing	Could Not Duplicate Concern	466418	F	Ilion repaired at n/c under BLM
10718	600	N/A	308WIN	20-Mar-72	N	S	19-Sep-14	19-Sep-14	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	466333	F	Per Ilion, replace trigger, check over and test fire at no charge
10719	700	85373	270 WIN	23-Jan-08	N	S	19-Sep-14	19-Sep-14	Fired on Safe Release	Could Not Duplicate Concern	466384	F	Per Ilion - Repair at n/c under recall
10724	700	n/a	270 WIN	27-Apr-76	N	S	19-Sep-14	3-Oct-14	Fired on Bolt Opening	Altered Adjustments or Components	469553	F	Per Ilion - Repair at n/c
10726	700	29694	300 WIN MA	8-Mar-94	N	PI/S	22-Sep-14	13-Oct-14	Fired on Safe Release	Could Not Duplicate Concern	470562	F	Ilion repaired at n/c
10728	700	84362	223 REM	4-Feb-10	N	S	23-Sep-14	23-Sep-14	Fired on Bolt Closing	Could Not Duplicate Concern	467130	F	Per Ilion - Repair at n/c
10729	700	n/a	270 WIN	1-Oct-76	N	S	23-Sep-14	23-Sep-14	Fired With Safe ON	Could Not Duplicate Concern	467143	F	Ilion repaired at n/c under BLM
10731	BACR	n/a	5.56		N	S	23-Sep-14	23-Sep-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	467419	F	Ilion repaired at n/c
10732	700	n/a	3006 SPRG		N	S	23-Sep-14	23-Sep-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	467413	F	Per Ilion - Repair at n/c
10733	Spartan SPR 310	89716	20GA	20-May-08	Y	S	23-Sep-14	23-Sep-14	Fired on Bolt Closing	Could Not Duplicate Concern	467221	F	Returned as Received - Ilion cannot repair
10734	870	25103	12 GA	1-Oct-13	N	S	23-Sep-14	16-Jan-15	Failed to Extract	Could Not Duplicate Concern	472904/484864	F	Replace with Ramac 25103 in exchange
10735	XIM15-E2S	n/a	5.56	14-Jan-09	N	S	24-Sep-14	24-Sep-14	Went Automatic	Could Not Duplicate Concern	467437	F	Ilion repaired at n/c
10736	700	27502	7MM STW	22-May-98	N	S	24-Sep-14	24-Sep-14	Fired on Safe Release	Could Not Duplicate Concern	467591	F	Ilion repaired at n/c
10739	7	24774	243 WIN	24-Jan-97	N	S	25-Sep-14	25-Sep-14	Fired With Safe ON	Could Not Duplicate Concern	467704	F	Ilion repaired at n/c
10740	788	N/A	243 WIN	8-Apr-79	N	S	25-Sep-14	25-Sep-14	Fired on Safe Release	Improper Maintenance	467693	F	Returning as received
10743	700	27478	3006 SPR	23-Jun-98	N	S	26-Sep-14	17-Oct-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	471452	F	Per Ilion replace trigger at no charge.
10744	887	82501	12 GA	28-May-14	N	S	29-Sep-14	29-Sep-14	Fired on Bolt Closing	fired on bolt closing	467456	F	Per Ilion - Repair at n/c
10747	700	27097	7MM REM MA	26-Apr-12	N	PD/S	29-Sep-14	10-Nov-14	Fired on Bolt Closing	Could Not Duplicate Concern	472867	F	Replace trigger assembly, check over and test fire at no charge
10749	700	27516	308 WIN	6-Mar-02	N	S	30-Sep-14	30-Sep-14	Fired on Bolt Closing	Could Not Duplicate Concern	468189	F	Ilion repaired at n/c
10751	700	n/a	3006 SPRG	3-Sep-76	N	S	30-Sep-14	30-Sep-14	Fired on Safe Release	Altered Adjustments or Components	468664	F	Ilion repaired at n/c

RAC001198

Confidential

10754	700	27522	270WIN	20-Jun-03	N	S	1-Oct-14	1-Oct-14	Fired on Safe Release	Could Not Duplicate Concern	469038	F	Ilion repaired at n/c
10755	700	n/a	270WIN	12-May-76	N	S	1-Oct-14	1-Oct-14	Delayed Firing - Firearms	Improper Maintenance	468748	F	Ilion repaired at n/c
10756	750	27059	270WIN	30-Jul-10	N	S	1-Oct-14	1-Oct-14	Fired Out of Battery	Sent in for Evaluation	468908	F	Per Ilion, check over completely, repair as needed, and test at no charge.
10757	700	n/a	270 WIN	17-Nov-81	N	S	1-Oct-14	1-Oct-14	Fired on Safe Release	Altered Adjustments or Components	469168	F	Ilion repaired at n/c under BLM
10760	700	n/a	7MM REM MA	18-May-76	N	PI/S	1-Oct-14	15-Dec-14	Fired on Bolt Opening	Altered Adjustments or Components	477211	F	Repair @ n/c
10761	700	n/a	3006SPRG	20-Jan-77	N	S	2-Oct-14	2-Oct-14	Fired on Safe Release	Could Not Duplicate Concern	468962	F	Ilion repaired at n/c under BLM
10762	78	26164	3006SPRG	24-Jan-85	Y	S	2-Oct-14	2-Oct-14	Fired on Bolt Closing	Altered Adjustments or Components	469278	F	Per Ilion, replace trigger assembly,check over and test fire at no charge
10763	597	26536	17 HMR	28-Mar-03	N	PD/S	2-Oct-14	2-Oct-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	469266	F	Per Ilion, converting to 22 WMR as requested by customer.
10764	700ML	86950	50 CAL	11-Aug-14	Y	S	2-Oct-14	2-Oct-14	Fired on Bolt Closing	Could Not Duplicate Concern	469316	F	Per Ilion, replace trigger assembly,check over and test fire at no charge
10765	700	84601	22-250REM	4-Dec-12	N	S	2-Oct-14	2-Oct-14	Fired on Bolt Closing	Could Not Duplicate Concern	469128	F	Per Ilion - Repair at n/c under recall
10766	700ML	86950	50 CAL	22-Jul-14	Y	S	2-Oct-14	2-Oct-14	Fired on Bolt Closing	Could Not Duplicate Concern	469322	F	Per Ilion, replace trigger assembly,check over and test fire at no charge
10767	700	85372	243 WIN	9-May-12	N	S	2-Oct-14	2-Oct-14	Fired on Bolt Closing	Could Not Duplicate Concern	469237	F	Per Ilion, replace trigger assembly,check over and test fire at no charge
10772	700ML	27572	50CAL	23-Apr-97	Y	S	3-Oct-14	3-Oct-14	Fired on Safe Release	Broken or Missing Parts	469546	F	Ilion repaired at n/c
10775	700	n/a	6MM REM	13-Sep-78	N	S	3-Oct-14	3-Oct-14	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	469588	F	Ilion repaired at n/c under BLM
10778	700ML	27572	50 CAL	7-Feb-97	Y	S	6-Oct-14	6-Oct-14	Broken Part	Broken or Missing Parts	469399	F	Per Ilion - Repair at n/c
10779	700	n/a	308 WIN		N	S	6-Oct-14	29-Oct-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	469896	F	Ilion replaced the TA at n/c
10780	700	n/a	3006 SPRG	9-Sep-70	Y	S	6-Oct-14	6-Oct-14	Fired on Safe Release	Improper Maintenance	469814	F	Ilion repaired at n/c under BLM
10781	700	N/A	7MM REM MA	25-Jun-75	N	S	6-Oct-14	6-Oct-14	Fired on Safe Release	Could Not Duplicate Concern	469787	F	Per Ilion, replace trigger assembly,check over and test fire at no charge
10783	700	n/a	17 REM	7-Nov-73	N	S	7-Oct-14	7-Oct-14	Fired on Bolt Closing	Altered Adjustments or Components	470165	F	Ilion repaired at n/c under BLM
10784	700	27482	338RUM	16-Feb-99	N	S	7-Oct-14	7-Oct-14	Fired on Bolt Closing	Altered Adjustments or Components	470168	F	Per Ilion, replace trigger assembly,check over and test fire at no charge
10785	597	26514	17 HMR	22-Feb-05	N	S	8-Oct-14	10-Nov-14	Other - Firearms	Other - Unspecified or Undetermined - Firearms	474959	F	Converting to 22 WMR as requested by customer
10786	700	n/a	3006 SPRG	3-Mar-72	N	PD/S	9-Oct-14	18-Nov-14	Fired on Bolt Closing	Altered Adjustments or Components	476145	F	Repair @ n/c
10790	700	N/A	7MM REM MA	24-Jan-14	N	S	9-Oct-14	28-Oct-14	Fired on Bolt Opening	Could Not Duplicate Concern	472545	F	Per Ilion, replace trigger assembly,check over and test fire at no charge

RAC001199

Confidential

10797	700	25851	270 WIN	8-Sep-00	N	S	13-Oct-14	13-Oct-14	Fired on Safe Release	Could Not Duplicate Concern	470682	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10798	700	26096	300 RUM	27-Nov-01	N	S	13-Oct-14	13-Oct-14	Fired on Safe Release	Could Not Duplicate Concern	470563	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10796	700	84524	7MM MAG	21-Sep-10	N	PD/S	13-Oct-14	12-Jan-15	Fired on Bolt Opening	Could Not Duplicate Concern	475151	F	Per Release - \$1,106.91 reimbursement for truck & camper repair
10799	870	25569	12 GA	20-May-96	N	S	14-Oct-14	14-Oct-14	Delayed Firing - Firearms	Sent in for Evaluation	471231	F	Per Ilion - Quote to repair @ discount
10800	700	27480	7MM REM MA	28-Feb-97	N	S	14-Oct-14	14-Oct-14	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	470958	F	Ilion repaired at n/c
10801	597	26562	22 LR	10-May-06	N	S	14-Oct-14	14-Oct-14	Cartridge Cases Damaged during firing	Could Not Duplicate Concern	471143	F	Per Ilion - Repair at n/c
10804	700	27351	223 REM	16-Dec-09	N	S	14-Oct-14	15-Oct-14	Fired on Bolt Closing	Sent in for Evaluation	455171	F	Per Ilion - Repair at n/c under recall
10803	700	26331	7MM RUM	9-Apr-02	N	S	15-Oct-14	15-Oct-14	Fired on Safe Release	Improper Maintenance	471435	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10810	700	27009	2506 REM	8-Feb-11	N	S	17-Oct-14	17-Oct-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	471470	F	Per Ilion - Repair at n/c under recall
10811	700	27011	270 WIN	29-Jun-04	N	S	17-Oct-14	17-Oct-14	Fired on Safe Release	Altered Adjustments or Components	471687	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10813	700	N/A	222 REM	14-Feb-69	N	S	17-Oct-14	17-Oct-14	Fired on Bolt Opening	Improper Maintenance	471786	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10818	1911	96323	45 ACP	16-Sep-11	N	PI/S	21-Oct-14	22-Oct-14	Broken Part	Sent in for Evaluation	470915	F	Ilion checked over & tested at no charge
10817	1911	96323	45 ACP	13-Feb-13	N	S	22-Oct-14	22-Oct-14	Fired on Bolt Closing	Broken or Missing Parts	470440	F	Per Ilion - Repair at n/c - warranty
10820	7	24728	223 REM	26-Aug-02	N	S	22-Oct-14	22-Oct-14	Fired on Bolt Closing	Could Not Duplicate Concern	472221	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10822	700	N/A	3006 SPRG	29-May-80	N	S	22-Oct-14	22-Oct-14	Fired on Safe Release	Altered Adjustments or Components	472001	O	Per Ilion, replace trigger assembly, check over and test fire at no charge
10824	700	N/A	270 WIN	13-Mar-70	N	PD/S	23-Oct-14	12-Dec-14	Fired on Safe Release	Could Not Duplicate Concern	477344	F	Check over completely, repair as needed, and test at no charge
10828	700	N/A	7MM REM MA	25-May-76	N	S	23-Oct-14	23-Oct-14	Fired on Safe Release	Altered Adjustments or Components	471931	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10829	H&R Hand-Rifle	72560	243 WIN	23-Oct-07	N	S	23-Oct-14	3-Dec-14	Action Opened on Firing	Could Not Duplicate Concern	472440	F	Repair @ n/c
10830	700	N/A	308 WIN	23-Jul-79	N	S	23-Oct-14	23-Oct-14	Delayed Firing - Firearms	Improper Maintenance	472488	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10833	597	N/A	17 HMR	17-Mar-03	N	PI/PD/S	24-Oct-14	24-Nov-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	477177	F	Converting to 22 WMR as requested by customer
10845	700	n/a	222 REM	1-Jan-75	N	PD/S	28-Oct-14	15-Dec-14	Fired on Safe Release	Altered Adjustments or Components	477685	F	Repair @ n/c

RAC001200

Confidential

10846	700	N/A	7MM RM	13-May-76	N	PD/S	28-Oct-14	10-Dec-14	Fired on Safe Release	Could Not Duplicate Concern	478868	F	Check over completely, repair as needed, and test at no charge
10843	700	27053	300 RUM	15-Jul-05	N	PI/S	28-Oct-14	18-May-15	Fired on Bolt Closing	Altered Adjustments or Components	498064	F	Replace in exchange with Ramac 27061
10844	700	27095	3006 SPRG	7-Mar-12	N	PI/S	28-Oct-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10847	700	84205	300 BLK OU	28-Aug-13	N	PD/S	30-Oct-14	31-Oct-14	Delayed Firing - Firearms	Could Not Duplicate Concern	455135	F	Per Ilion - Repair at n/c under recall
10850	1187	83612	12GA	6-Aug-12	N	PD/S	3-Nov-14	3-Nov-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	473580	F	Per Ilion - Repair at n/c
10851	700ML	27572	50 CAL	21-Jun-97	Y	S	3-Nov-14	3-Nov-14	Fired on Safe Release	Broken or Missing Parts	473529	F	Per Ilion - Repair at n/c
10852	870	24907	12 GA	4-Jun-97	N	PD/S	3-Nov-14	3-Nov-14	Fired Out of Battery	Fired Out of Battery	473528	F	Per Ilion, check over completely, repair as needed, and test at a 50% discount.
10853	770	85635	7MM REM MA	9-Feb-13	N	S	3-Nov-14	3-Nov-14	Delayed Firing - Firearms	Sent in for Evaluation	473424	F	Per Ilion - Repair at n/c - warranty
10855	700	N/A	308 WIN	17-Jun-76	N	PD/S	3-Nov-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10860	770	85635	7MM REM MA	30-Oct-13	N	S	4-Nov-14	4-Nov-14	Fired With Safe ON	Could Not Duplicate Concern	470461	F	Ilion replaced w/85635 at no charge
10869	700	27476	270 WIN	27-Sep-97	N	PI/S	4-Nov-14	10-Jul-15	Fired With Safe ON	Could Not Duplicate Concern	499696	F	Check over completely, repair as needed, and test at no charge
10857	700	N/A	25-06 REM	4-Apr-78	N	PD/S	4-Nov-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10862	1187	83609	12GA	3-Oct-12	N	S	5-Nov-14	5-Nov-14	Fired on Bolt Closing	Could Not Duplicate Concern	474156	F	Per Ilion - Repair/adjust at n/c
10868	700	84216	22-250 REM	14-Mar-08	N	S	5-Nov-14	5-Nov-14	Fired on Bolt Closing	Could Not Duplicate Concern	473891	F	Per Ilion - Repair at n/c
10870	700ML	27580	50 CAL	29-Oct-97	N	S	5-Nov-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10872	700	27529	3006 SPR	18-Oct-99	N	S	7-Nov-14	7-Nov-14	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	473362	F	Ilion repaired at n/c
10873	700	27482	300 WIN MA	28-Jan-04	N	S	7-Nov-14	7-Nov-14	Fired on Safe Release	Could Not Duplicate Concern	474009	F	Ilion repaired at n/c
10874	7	24741	7MM-08 REM	23-Jul-97	N	S	7-Nov-14	7-Nov-14	Fired on Safe Release	Altered Adjustments or Components	474454	F	Ilion repaired at n/c
10875	700	not avail.	3006 SPR	1-Jan-68	N	S	7-Nov-14	7-Nov-14	Fired on Safe Release	Altered Adjustments or Components	474504	F	Ilion repaired at n/c
10877	700	27387	300 WIN MA	12-May-11	N	S	7-Nov-14	7-Nov-14	Fired on Safe Release	Could Not Duplicate Concern	474542	F	Ilion repaired at n/c
10879	SEVEN	24788	308 WIN	23-Jul-96	N	PI/S	7-Nov-14	21-Jan-15	Fired on Safe Release	Improper Maintenance	485583	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10890	700	N/A	3006 SPRG	19-May-75	N	S	7-Nov-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10884	700ML	27580	50 CA	2-Aug-96	Y	S	10-Nov-14	10-Nov-14	Fired on Bolt Closing	Worn parts or components	475094	F	Per Ilion - Repair at n/c
10885	600	not avail.	6.5MM REM	1-Jul-66	Y	S	10-Nov-14	10-Nov-14	Fired on Safe Release	Altered Adjustments or Components	475368	F	Ilion repaired at n/c
10886	887	82501	12GA	28-May-14	N	S	10-Nov-14	10-Nov-14	Fired on Bolt Closing	Could Not Duplicate Concern	475356	F	Per Ilion - Repair at n/c - warranty
10896	770	85634	308 WIN	4-Sep-13	N	S	10-Nov-14	2-Dec-14	Delayed Firing - Firearms	Could Not Duplicate Concern	477914	F	Per Ilion, replace trigger assembly, check over and test fire at no charge

RAC001201

Confidential

10892	770	85637	243 WIN	7-Feb-14	N	PI/S	10-Nov-14	7-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	481626	F	Per Ilion, replace with Ramac 85832 in exchange
10894	887	82500	12 GA	9-Apr-14	N	S	11-Nov-14	11-Nov-14	Fired With Safe ON	Sent in for Evaluation	475875	F	Per Ilion - Repair at n/c - warranty
10898	700	29708	270 WIN	19-May-93	N	S	11-Nov-14	9-Dec-14	Fired on Safe Release	Improper Maintenance	478896	F	Per Ilion - Repair at n/c
10899	700	not avail.	3006 SPRG	20-Sep-77	N	PD/S	11-Nov-14	17-Dec-14	Fired With Safe ON	Could Not Duplicate Concern	478078	F	Repair @ n/c - goodwill gesture
10903	887	82500	12 GA	6-Jun-14	N	PD/S	12-Nov-14	8-Dec-14	Fired With Safe ON	Fired on safe	478055	F	Replace with Ramac 81046 in exchange
10907	700	27478	3006 SPR	30-Aug-95	N	S	13-Nov-14	13-Nov-14	Fired on Bolt Closing	Could Not Duplicate Concern	475628	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10908	660	not avail.	243 WIN	1-Jan-68	Y	S	13-Nov-14	13-Nov-14	Fired on Safe Release	Could Not Duplicate Concern	474049	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10909	700	87268	300 WBY MA	25-Sep-14	N	S	13-Nov-14	13-Nov-14	Fired on Bolt Closing	Could Not Duplicate Concern	476068	F	Repair @ n/c under XMP recall
10910	700	not avail.	6MM REM	6-Jul-76	N	S	13-Nov-14	13-Nov-14	Fired on Bolt Closing	Altered Adjustments or Components	476200	F	Ilion repaired at n/c
10911	700	not avail.	270 WIN	29-Apr-77	N	S	13-Nov-14	13-Nov-14	Fired on Safe Release	Altered Adjustments or Components	476161	F	Ilion repaired at n/c
10912	700	25771	270 WIN	21-Sep-84	N	S	13-Nov-14	13-Nov-14	Fired With Safe ON	Could Not Duplicate Concern	476204	F	Ilion repaired at n/c
10921	700	84401	25-06 REM	16-Feb-09	N	S	13-Nov-14	12-Dec-14	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	479540	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10929	700	N/A	3006 SPRG	9-Jul-76	N	S	13-Nov-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10919	887	82500	12 GA	6-Jun-14	N	PD/S	14-Nov-14	31-Dec-14	Fired With Safe ON	Other - Unspecified or Undetermined - Firearms	478567	F	Replace w/82500 in exchange
10930	700	25771	270 WIN	31-May-00	N	S	14-Nov-14	16-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	485527	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10938	700	25800	7MM-08	11-Dec-93	N	S	14-Nov-14	23-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	487076	F	Per Ilion - Repair at n/c - goodwill
10934	700	N/A	7MM REM MA	1-Jun-62	N	S	14-Nov-14	12-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	492388	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10926	742	N/A	3006 SPRG	27-Jan-78	Y	PD/S	14-Nov-14	27-Feb-15	Unexplained Discharge Safe ON	Could Not Duplicate Concern	478676	F	clean and check over trigger assembly at no charge as a goodwill gesture
10922	700	not avail.	222 REM	4-Feb-88	N	S	17-Nov-14	17-Nov-14	Fired on Safe Release	Could Not Duplicate Concern	476575	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10923	770	85637	243 WIN	19-Jan-09	N	S	17-Nov-14	17-Nov-14	Delayed Firing - Firearms	Sent in for Evaluation	476548	F	Per Ilion, check over completely, repair as needed, and test at no charge.
10924	770	85637	243 WIN	5-Dec-12	N	S	17-Nov-14	17-Nov-14	Fail to Fire	Sent in for Evaluation	476253	F	Per Ilion, check over completely, repair as needed, and test at no charge.
10925	700	n/a	3006 SPRG	11-Jun-69	N	S	17-Nov-14	5-Dec-14	Fired on Bolt Opening	Improper Maintenance	478503	F	Ilion repaired at n/c under BLM
10927	700	26967	308 WIN	28-Dec-95	N	S	17-Nov-14	9-Dec-14	Delayed Firing - Firearms	Could Not Duplicate Concern	478756	F	Per Ilion - Replace TA & test @ n/c

RAC001202

Confidential

10996	660	not avail.	243 WIN	24-Jul-69	Y	S	17-Nov-14	12-Dec-14	Fired on Safe Release	Altered Adjustments or Components	479426	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10957	788	N/A	7MM-08	5-Nov-81	Y	S	17-Nov-14	21-Jan-15	Fired on Safe Release	Improper Maintenance	481500	F	Per Ilion, check over completely, repair as needed, and test at a 50% discount.
10959	700	N/A	3006 SPRG	31-Mar-88	N	S	17-Nov-14	8-Jan-15	Fired on Safe Release	Altered Adjustments or Components	483961	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10928	700	N/A	3006 SPRG		N	PI/PD/S	17-Nov-14	22-Oct-15	Unexplained Discharge - No Mention of Safety Position	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10994	700	N/A	270 WIN	25-Nov-70	N	S	17-Nov-14	22-Oct-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10931	700	not avail.	243 WIN	18-Sep-80	N	S	18-Nov-14	18-Dec-14	Fired on Safe Release	Altered Adjustments or Components	480785	F	Ilion repaired at n/c
10935	700	85421	3006 SPRG	28-Aug-09	N	S	18-Nov-14	19-Dec-14	Fired on Safe Release	Could Not Duplicate Concern	481322	F	Per Ilion - Repair at n/c under recall
10937	700	25791	270 WIN	22-Apr-04	N	S	18-Nov-14	4-Dec-14	Fired on Safe Release	Improper Maintenance	478407	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10948	700	N/A	6MM REM	23-Jun-77	N	PD/S	18-Nov-14	16-Dec-14	Fired on Bolt Opening	Altered Adjustments or Components	479440	F	Check over completely, repair as needed, and test at no charge
10955	700	N/A	3006 SPRG	27-Jul-73	N	S	18-Nov-14	18-Dec-14	Fired on Safe Release	Altered Adjustments or Components	480875	F	Replace trigger assembly, check over and test fire at no charge
10997	700	N/A	3006 SPRG	12-Aug-75	N	S	18-Nov-14	18-Dec-14	Fired on Safe Release	Altered Adjustments or Components	480700	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10998	700	N/A	243 WIN	27-Feb-70	N	S	18-Nov-14	18-Dec-14	Fired on Bolt Closing	Altered Adjustments or Components	480857	F	Replace trigger assembly, check over and test fire at no charge
11080	700	25775	308 WIN	13-Feb-86	N	S	18-Nov-14	3-Feb-15	Delayed Firing - Firearms	Improper Maintenance	489347	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10933	700	85336	3006 SPRG	22-Jul-13	N	S	18-Nov-14	22-Oct-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10999	700	N/A	7MM REM MA		N	S	18-Nov-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10939	770	85632	270WIN	13-Mar-13	N	S	19-Nov-14	19-Nov-14	Fired on Bolt Closing	Could Not Duplicate Concern	475965	F	Per Ilion - Repair at n/c - warranty
10940	CARBON 15	90689	5.56	5-Jun-13	N	S	19-Nov-14	19-Nov-14	Went Automatic	Sent in for Evaluation	474723	F	Per Ilion - Repair at n/c
10941	700	27480	7MM REM MA	30-Nov-01	N	S	19-Nov-14	19-Nov-14	Fired on Safe Release	Altered Adjustments or Components	476727	F	Ilion repaired at n/c
10942	700	not avail.	3006 SPR	25-Oct-76	N	S	19-Nov-14	19-Nov-14	Fired on Safe Release	Could Not Duplicate Concern	476729	F	Ilion repaired at n/c
10944	770	85632	270 WIN	17-Oct-12	N	S	19-Nov-14	19-Nov-14	Fired With Safe ON	Could Not Duplicate Concern	476780	F	Per Ilion - Repair at n/c - goodwill
10949	700	N/A	3006 SPRG	24-Feb-69	N	S	19-Nov-14	9-Dec-14	Delayed Firing - Firearms	Improper Maintenance	478810	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11083	700	N/A	25-06 REM		N	S	19-Nov-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11081	700	N/A	3006 SPRG	26-Feb-76	N	S	19-Nov-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10954	700	27389	300 RUM	22-Sep-08	N	S	20-Nov-14	20-Nov-14	Fired on Safe Release	Not Examined by Product Service	n/a	F	Not Examined by Product Service

RAC001203

Confidential

10956	700	n/a	3006 SPRG	8-Feb-79	N	PD/S	20-Nov-14	30-Dec-14	Fired on Bolt Opening	Could Not Duplicate Concern	481793	F	Repair @ n/c
10958	700	25802	7MM RM	22-Apr-92	N	PD/S	20-Nov-14	11-Dec-14	Fired on Safe Release	Improper Maintenance	478803	F	Repair @ n/c - goodwill gesture
10960	597	26516	17 HMR	8-Dec-04	N	PD/S	20-Nov-14	9-Dec-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	478755	F	Per Ilion, converting to 22 WMR as requested by customer.
10953	SEVEN	24741	7MM-08	18-Jul-97	N	S	20-Nov-14	22-Oct-15	Delayed Firing - Firearms	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10082	700	25634	3006 SPR	27-Feb-86	N	S	21-Nov-14	21-Nov-14	Fired on Bolt Closing	Improper Maintenance	477209	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10961	887	82500	12 GA	23-Jun-14	N	S	21-Nov-14	21-Nov-14	Fired on Bolt Closing	Sent in for Evaluation	475737	F	Per Ilion - Repair at n/c - warranty
10962	700	84370	223 REM	11-Jan-08	N	S	21-Nov-14	21-Nov-14	Fired on Bolt Closing	Could Not Duplicate Concern	476988	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10963	700	not avail.	270 WIN	22-Mar-79	N	S	21-Nov-14	21-Nov-14	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	477154	F	Ilion repaired at n/c
10964	700	not avail.	243 WIN	24-Jan-69	N	S	21-Nov-14	21-Nov-14	Fired on Safe Release	Altered Adjustments or Components	477208	F	Ilion repaired at n/c
10965	700	27476	270 WIN	5-Feb-97	N	S	21-Nov-14	21-Nov-14	Fired on Safe Release	Altered Adjustments or Components	477212	F	Ilion repaired at n/c
10966	770	85633	3006 SPRG	29-Jan-08	N	S	21-Nov-14	21-Nov-14	Fired on Bolt Closing	Could Not Duplicate Concern	477210	F	Per Ilion - Repair at n/c - goodwill
10972	660	not avail.	6MM	1-Jan-68	Y	S	21-Nov-14	12-Dec-14	Fired on Safe Release	Improper Maintenance	479593	F	Per Ilion - Repair at n/c under recall
10969	870	25098	12 GA	19-Sep-12	N	PD/S	21-Nov-14	6-Jan-15	Fired on Bolt Closing	Fired from Contact with Foreign Object	482828	F	Per Ilion - Repair at n/c
10970	700	not avail.	3006 SPRG	1-Mar-68	N	PD/S	21-Nov-14	27-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	481503	F	Repair @ n/c
10971	700	84126	3006 SPRG	26-Jul-11	N	S	21-Nov-14	16-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	485631	F	Per Ilion - Repair at n/c
10973	700	25787	243 WIN	23-Feb-84	N	S	21-Nov-14	17-Apr-15	Fired on Bolt Closing	Improper Maintenance	489643	F	Per Ilion: Repair at no charge
10968	700	n/a	7MM MAG	6-Jun-75	N	S	21-Nov-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
10982	700	25773	3006 SPRG	11-Sep-85	N	S	24-Nov-14	18-Dec-14	Fired on Safe Release	Improper Maintenance	480844	F	Ilion repaired at n/c
10985	700	27502	7MM STW	14-Apr-97	N	S	24-Nov-14	12-Dec-14	Fired on Safe Release	Altered Adjustments or Components	479563	F	Per Ilion - Replace TA & test @ n/c
10986	700	n/a	7MM RM	3-Jun-75	N	S	24-Nov-14	18-Dec-14	Fired on Safe Release	Altered Adjustments or Components	480784	F	Ilion repaired at n/c
10992	700	25935	300 WIN M	23-Feb-96	N	S	24-Nov-14	11-Dec-14	Unexplained Discharge Safe OFF	Improper Maintenance	479104	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10993	700	N/A	3006 SPRG	13-Jul-71	N	S	24-Nov-14	11-Dec-14	Delayed Firing - Firearms	Could Not Duplicate Concern	478986	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10977	887	82500	12 GA	6-Jun-14	N	PD/S	24-Nov-14	12-Feb-15	Fired on Bolt Closing	Sent in for Evaluation	485319	F	Replace with Ramac 81054 in exchange and \$875 for damage to house
10984	700	27361	270 WIN	19-Apr-12	N	S	24-Nov-14	22-Oct-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam

RAC001204

Confidential

10987	700	N/A	308 WIN	10-Mar-77	N	S	25-Nov-14	25-Nov-14	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	477227	F	Per Ilion, check over completely, repair as needed, and test at no charge.
10988	700	N/A	3006 SPR	15-Apr-74	N	S	25-Nov-14	25-Nov-14	Fired on Safe Release	Could Not Duplicate Concern	477324	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10990	700	27094	270 WIN	9-Jun-12	N	S	25-Nov-14	25-Nov-14	Delayed Firing - Firearms	Could Not Duplicate Concern	477348	F	Per Ilion - Repair at n/c
10991	700	N/A	3006 SPR	22-Jun-71	N	S	25-Nov-14	25-Nov-14	Fired on Safe Release	Fired on Safe Release	477347	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
10995	700	84461	308 WIN	25-Feb-10	N	S	25-Nov-14	18-Dec-14	Fired on Bolt Closing	Could Not Duplicate Concern	480674	F	Per Ilion - Repair at n/c under recall
11000	700	n/a	3006 SPRG	23-Jun-71	N	S	25-Nov-14	11-Dec-14	Unexplained Discharge Safe OFF	Altered Adjustments or Components	479321	F	Ilion repaired at n/c
11001	700	n/a	6MM	16-Mar-70	N	S	25-Nov-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Rifle not returned to Ilion for exam
11004	700	85478	270 WIN	18-May-10	N	S	26-Nov-14	26-Nov-14	Fired on Safe Release	Could Not Duplicate Concern	477691	F	Refunded purchase price in Consumer Service.
11085	700	26121	25-06 REM	25-Apr-97	N	S	26-Nov-14	6-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	483612	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11008	700	25791	270 WIN	22-Jun-12	N	S	26-Nov-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11009	700	N/A	3006 SPRG	28-Jun-76	N	S	26-Nov-14	22-Oct-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11010	710	27414	300 WM	25-Oct-06	Y	S	1-Dec-14	1-Dec-14	Fired on Safe Release	Altered Adjustments or Components	477868	F	Per Ilion - Quote to repair @ discount - goodwill
11011	700	not avail.	243 WIN	30-Apr-74	N	S	1-Dec-14	1-Dec-14	Delayed Firing - Firearms	Improper Maintenance	477823	F	Ilion repaired at n/c
11012	700	not avail.	270 WIN	9-May-74	N	S	1-Dec-14	1-Dec-14	Delayed Firing - Firearms	Sent in for Evaluation	477840	F	Per Ilion - Quote to repair @ discount for main spring
11013	700	25630	270 WIN	15-May-92	N	S	1-Dec-14	1-Dec-14	Fired on Safe Release	Improper Maintenance	477855	F	Ilion repaired at n/c
11032	700	29713	280 REM	25-May-94	N	S	1-Dec-14	18-Dec-14	Fired on Bolt Opening	Altered Adjustments or Components	480831	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11016	700	85433	223 REM	23-Feb-11	N	PD/S	1-Dec-14	23-Jan-15	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	481499	F	Check over completely, repair as needed, and test at no charge
11020	700	not avail.	25-06 REM	14-Mar-74	N	S	1-Dec-14	8-Jan-15	Fired on Bolt Closing	Improper Maintenance	484074	F	Ilion repaired at n/c
11033	700	N/A	243 WIN	1-Jun-66	N	S	1-Dec-14	12-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	484759	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11021	770	85630	243 WIN	14-May-08	N	S	1-Dec-14	13-Feb-15	Fired With Safe ON	Altered Adjustments or Components	493037	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11023	700	85492	7MM REM MA	4-Jan-13	N	S	1-Dec-14	9-Feb-15	Fired With Safe ON	Could Not Duplicate Concern	481490	F	Check over completely, repair as needed, and test at no charge and reimburse PD of \$1113.94
11093	700	26033	270 WIN	17-Apr-98	N	S	1-Dec-14	22-Oct-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11017	700	not avail.	3006 SPRG	21-Mar-69	N	S	1-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam

RAC001205

Confidential

11022	700	N/A	3006 SPRG	20-Mar-69	N	S	1-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11018	770	85633	3006 SPRG	14-Feb-08	Y	S	1-Dec-14	22-Oct-15	Unexplained Discharge Safe OFF	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11025	597	26537	22LR	29-May-08	N	PD/S	2-Dec-14	2-Dec-14	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	478023	F	Per Ilion - Repair at n/c - goodwill
11027	700	not avail.	243 WIN	23-Aug-88	N	S	2-Dec-14	2-Dec-14	Fired on Safe Release	Improper Maintenance	478056	F	Ilion repaired at n/c
11028	700	25851	270 WIN	10-Feb-04	N	S	2-Dec-14	2-Dec-14	Fired on Safe Release	Could Not Duplicate Concern	478042	F	Ilion repaired at n/c
11029	700	25767	243 WIN	31-Jul-89	N	S	2-Dec-14	2-Dec-14	Delayed Firing - Firearms	Could Not Duplicate Concern	477995	F	Ilion repaired at n/c
11030	700	27508	300 WIN MA	12-May-04	N	S	2-Dec-14	2-Dec-14	Fired on Bolt Closing	Improper Maintenance	478021	F	Ilion repaired at n/c
11031	600	N/A	6MM	1-Dec-65	N	S	2-Dec-14	2-Dec-14	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	477908	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11044	700	84213	17 FIREBAL	8-Aug-07	N	PD/S	2-Dec-14	23-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	481489	F	Check over completely, repair as needed, and test at no charge
11045	700	N/A	7MM REM MA	1-Aug-67	N	S	2-Dec-14	6-Jan-15	Fired on Safe Release	Altered Adjustments or Components	482807	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11046	700	85435	308 WIN	6-Aug-10	N	S	2-Dec-14	18-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	481682	F	Check over completely, repair as needed, and test at N/C, reimburse vehicle damage
11034	700	85463	270 WIN	8-Aug-13	N	PD/S	2-Dec-14	16-Apr-15	Fired on Bolt Closing	Could Not Duplicate Concern	488804	F	Per Release - Check for \$1,194 & replace gun w/27499 in exchange
11058	700	N/A	3006 SPRG	25-Mar-79	N	PD/S	2-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11059	1187	29917	20 GA	20-Jun-11	N	PD/S	2-Dec-14	22-Oct-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11056	700	25819	243 WIN	10-Aug-89	N	S	2-Dec-14	13-Oct-15	Fired on Safe Release	Could Not Duplicate Concern	504692	F	Per Ilion, quote to check over completely, repair as needed, and test, replace trigger at no charge
11038	700	27144	300 WSM	30-Jun-06	N	S	2-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11039	700	27478	3006 SPRG	12-Mar-99	N	S	3-Dec-14	22-Dec-14	Fired on Safe Release	Could Not Duplicate Concern	481494	F	Ilion repaired at n/c
11048	700	not avail.	300 RUM	1-May-99	N	S	3-Dec-14	22-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	486666	F	Per Ilion - Repair at n/c - goodwill
11049	700	not avail.	7MM MAG	7-Feb-69	N	S	3-Dec-14	16-Jan-15	Fired on Bolt Opening	Could Not Duplicate Concern	485521	F	Per Ilion - Repair at n/c - goodwill
11051	700	27478	3006 SPRG	10-Mar-99	N	S	3-Dec-14	7-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	483703	F	Per Ilion - Repair at n/c
11076	700	N/A	222 REM	20-Feb-69	N	S	3-Dec-14	6-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	482806	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11047	887	82502	12 GA	26-Feb-11	N	S	3-Dec-14	22-Oct-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11052	7	24786	7MM08 REM	31-Oct-84	N	S	4-Dec-14	4-Dec-14	Fired on Safe Release	Could Not Duplicate Concern	478090	F	Ilion repaired at n/c

RAC001206

Confidential

11053	7	24779	243 WIN	6-Apr-00	N	S	4-Dec-14	4-Dec-14	Fired on Safe Release	Could Not Duplicate Concern	478077	F	Per Ilion - Quote to repair @ discount
11054	700	27478	3006 SPR	12-Dec-01	N	S	4-Dec-14	4-Dec-14	Fired With Safe ON	Altered Adjustments or Components	478402	F	Ilion repaired at n/c
11055	700	27225	308 WIN	19-Oct-11	N	S	4-Dec-14	4-Dec-14	Fired on Safe Release	Altered Adjustments or Components	478390	F	Per Ilion - Repair at n/c - goodwill
11061	700	N/A	3006 SPRG	9-Jul-73	N	S	4-Dec-14	6-Jan-15	Fired on Bolt Opening	Could Not Duplicate Concern	482804	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11063	710	27408	270 WIN	28-Jun-02	N	PD/S	4-Dec-14	6-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	483672	F	Replace with Ramac 85844 in exchange
11066	887	82502	12 GA	4-Apr-13	N	S	4-Dec-14	7-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	491819	F	Ilion repaired at n/c
11095	700	N/A	243 WIN	11-Oct-72	N	S	4-Dec-14	27-Mar-15	Fired on Safe Release	Altered Adjustments or Components	497370	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11060	700	27480	7MM REM MA	22-Jul-95	N	S	4-Dec-14	22-Oct-15	Delayed Firing - Firearms	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11069	700	not avail.	3006SPR	17-Feb-81	N	S	5-Dec-14	5-Dec-14	Fired With Safe ON	Improper Maintenance	478481	F	Ilion repaired at n/c
11070	700	not avail.	3006SPR	4-Mar-82	N	S	5-Dec-14	5-Dec-14	Fired on Bolt Closing	Improper Maintenance	478475	F	Ilion repaired at n/c
11071	700	25793	3006 SPRG	30-Apr-03	N	S	5-Dec-14	5-Dec-14	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	478559	F	Ilion repaired at n/c
11072	700	27361	270 WIN	12-Sep-07	N	S	8-Dec-14	12-Jan-15	Fired on Safe Release	Altered Adjustments or Components	484635	F	Per Ilion - Repair at n/c - goodwill
11075	700	N/A	3006 SPRG	1-Nov-74	N	S	8-Dec-14	22-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	486374	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11077	721	not avail.	270 WIN	1-Nov-71	Y	S	8-Dec-14	9-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	484241	F	Ilion repaired at n/c
11078	700	25803	7MM MAG	22-Sep-89	N	S	8-Dec-14	6-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	482803	F	Per Ilion - Repair at n/c
11079	700	26033	270 WIN	10-Feb-98	N	S	8-Dec-14	12-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	484518	F	Per Ilion - Repair at n/c - goodwill
11082	700ML	27572	50 CAL	28-Aug-96	Y	S	8-Dec-14	21-Jan-15	Fired on Safe Release	Sent in for Evaluation	486367	F	Per Ilion - Repair at n/c - goodwill
11103	700	not avail.	270 WIN	3-May-76	N	S	8-Dec-14	22-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	486694	F	Per Ilion - Repair at n/c
11073	700	25793	3006 SPRG	16-Apr-03	N	S	8-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11090	700	84203	308 WIN	22-Jun-12	N	S	9-Dec-14	9-Dec-14	Fired on Safe Release	Could Not Duplicate Concern	478812	F	Per Ilion - Repair at n/c under recall
11091	700	not avail.	270 WIN	1-Jul-65	N	S	9-Dec-14	9-Dec-14	Fired on Safe Release	Improper Maintenance	478752	F	Ilion - repair at n/c
11089	597	26516	17 HMIR	11-Dec-02	N	PD/S	9-Dec-14	24-Feb-15	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	478819	F	Replace with Ramac 70723 in exchange
11098	700	not avail.	7MM MAG	28-Apr-77	N	PI/S	9-Dec-14	23-Feb-15	Fired on Safe Release	Improper Maintenance	485292	F	Repair @ n/c
11101	700	25860	243 WIN	14-Dec-82	N	S	9-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11099	700	N/A	3006 SPRG		N	S	9-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11100	700	N/A	243 WIN		N	S	9-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11111	700	N/A	270 WIN	23-Apr-76	N	S	10-Dec-14	23-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	487068	F	Check over completely, repair as needed, and test at no charge

RAC001207

Confidential

11108	700	29692	7MM REM MA	20-Mar-96	N	S	10-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11110	700	27355	243 WIN	6-Aug-09	N	S	11-Dec-14	11-Dec-14	Fired on Safe Release	Could Not Duplicate Concern	479326	F	Per Ilion - Repair at n/c under recall
11115	700	not avail.	3006 SPRG	1-Dec-83	N	PD/S	11-Dec-14	21-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	485290	F	Per Ilion - Repair at n/c - goodwill
11119	700	25771	270 WIN	25-Mar-92	N	S	11-Dec-14	26-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	487348	F	Check over completely, repair as needed, and test at no charge
11122	770	85632	270 WIN	3-Oct-12	Y	PD/S	11-Dec-14	20-Jan-15	Ammunition Exploded	Sent in for Evaluation	485838	A	Per Ilion, replace in exchange with Ramac 85632 at no charge. Lonoke sent customer 2 boxes of ammo
11126	700	N/A	7MM REM MA	26-Jul-71	N	S	11-Dec-14	15-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	485231	F	Check over completely, repair as needed, and test at no charge
11127	700	27453	7MM-08 REM	28-Mar-02	N	S	11-Dec-14	3-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	489176	F	Per Ilion, check over completely, repair as needed, and test at no charge.
11123	770	85657	7MM REM MA	3-Feb-09	Y	PD/S	11-Dec-14	22-Oct-15	Fired With Safe ON	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11118	700	N/A	300 WIN M	23-Apr-81	N	S	11-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11124	7400	29759	270 WIN	11-Jun-97	Y	S	12-Dec-14	12-Dec-14	Went Automatic	Could Not Duplicate Concern	479591	F	Returned as Received - customer request
11125	700	26259	3006 SPR	14-Oct-97	N	S	12-Dec-14	12-Dec-14	Fired on Safe Release	Improper Maintenance	479435	F	Ilion repaired at n/c
11128	Handi Rifle	72652	243 WIN	6-Nov-13	N	PD/S	12-Dec-14	30-Jan-15	Ammunition Exploded	Sent in for Evaluation	487638	F	Check over completely, repair as needed, and test at no charge
11130	710	27408	270 WIN	14-May-03	N	S	12-Dec-14	15-Jan-15	Fail to Fire	Could Not Duplicate Concern	485191	F	Quote to repair at 50% discount
11132	887	82500	12 GA	8-Nov-13	N	S	12-Dec-14	6-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	484778	F	Replace with Ramac 26927 in exchange and check for \$625 for damage to house
11129	700	84179	7MM REM MA	26-Jul-12	N	S	12-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11135	700	N/A	6MM REM	27-Oct-77	N	PI/S	15-Dec-14	23-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	485729	F	Check over completely, repair as needed, and test at no charge
11138	700	27476	270 WIN	18-Aug-97	N	S	15-Dec-14	16-Feb-15	Unexplained Discharge Safe ON	Could Not Duplicate Concern	488301	F	Check over completely, repair as needed, and test at no charge
11139	700	not avail.	243 WIN	11-Apr-72	N	PD/S	15-Dec-14	25-Mar-15	Fired on Safe Release	Could Not Duplicate Concern	487643	F	Repair @ n/c - goodwill
11136	700	27269	3006 SPRG	28-Mar-07	N	PD/S	15-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11140	700	84076	270 WIN	9-Oct-13	N	S	16-Dec-14	16-Dec-14	Dissatisfied with Service - Firearms	Could Not Duplicate Concern	480313	F	Per Ilion - Repair at n/c
11142	770	85646	270 WIN	28-Nov-12	N	S	16-Dec-14	16-Dec-14	Fired on Bolt Closing	Could Not Duplicate Concern	480293	F	Call Center issued a refund to customer
11143	700	not avail.	2506 REM	24-Aug-72	N	S	16-Dec-14	16-Dec-14	Fired With Safe ON	Could Not Duplicate Concern	479634	F	Ilion repaired at n/c
11144	700	N/A	7MM RUM	25-Jun-02	N	PI/S	16-Dec-14	23-Jan-15	Fired on Safe Release	Altered Adjustments or Components	486275	F	Check over completely, repair as needed, and test at no charge

RAC001208

Confidential

11145	700	N/A	3006 SPRG	5-Sep-79	N	PD/S	16-Dec-14	21-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	485415	F	Check over completely, repair as needed, and test at no charge
11149	700	N/A	3006 SPRG	17-Oct-69	N	PD/S	16-Dec-14	9-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	488780	F	Check over completely, repair as needed, and test at no charge
11150	597	26516	17 HMR	28-Aug-03	N	PI/PD/S	16-Dec-14	3-Feb-15	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	488714	F	Replace with Ramac 70723 in exchange
11148	597	26536	17 HMR	21-Mar-03	N	PI/PD/S	16-Dec-14	2-Mar-15	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	492361	O	Replace with Ramac 70723 in exchange
11147	770	85633	3006 SPRG	22-May-07	Y	PD/S	16-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11153	700	not avail.	243 WIN	12-Apr-72	N	PD/S	17-Dec-14	4-Mar-15	Fired on Safe Release	Altered Adjustments or Components	488061	F	Repair @ n/c - goodwill
11155	597	80854	22 LR	9-Oct-08	N	PD/S	17-Dec-14	8-Apr-15	Unexplained Discharge Safe OFF	Other - Unspecified or Undetermined - Firearms	491724	F	Replace w/80854 in exchange
11157	770	85633	3006 SPRG	9-Apr-13	Y	PD/S	17-Dec-14	10-Jul-15	Fired With Safe ON	Could Not Duplicate Concern	500343	F	Replace w/85846 in exchange
11156	700	27361	270 WIN	16-Jan-06	N	PD/S	17-Dec-14	22-Oct-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11158	700	not avail.	6MM REM	18-Nov-77	N	S	18-Dec-14	18-Dec-14	Fired on Bolt Closing	Altered Adjustments or Components	480673	F	Per Ilion - Repair at n/c
11159	700	N/A	25-06 REM	1-Oct-74	N	S	18-Dec-14	18-Dec-14	Fired on Bolt Closing	Could Not Duplicate Concern	480832	F	Per Ilion replace trigger at no charge.
11162	700	84218	308 WIN	9-May-08	N	S	18-Dec-14	18-Dec-14	Fired on Bolt Closing	Altered Adjustments or Components	480758	F	Per Ilion - Repair at n/c under recall
11163	700	not avail.	243 WIN	27-Jan-72	N	S	18-Dec-14	18-Dec-14	Fired on Safe Release	AFT MKT TRIGGER ASSM	480828	F	Per Ilion - Quote to repair @ discount
11181	700	N/A	3006 SPRG	24-Jun-71	N	S	18-Dec-14	26-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	487184	F	Check over completely, repair as needed, and test at no charge
11161	700	27009	2506 REM	7-Feb-13	N	PI/S	18-Dec-14	27-Feb-15	Fired on Safe Release	Altered Adjustments or Components	480752	F	Check over completely, repair as needed, and test at no charge
11179	710	27425	3006 SPRG	20-Apr-04	Y	PD/S	18-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11171	710	27410	3006 SPR	23-Mar-05	Y	S	19-Dec-14	19-Dec-14	Fired on Safe Release	Altered Adjustments or Components	481310	F	Per Ilion - Quote to repair @ discount
11172	700	not avail.	300 WIN MA	16-Nov-78	N	S	19-Dec-14	19-Dec-14	Fired on Safe Release	Improper Maintenance	481317	F	Ilion repaired at n/c
11173	Seven	85953	22-250 REM	20-Aug-10	N	S	19-Dec-14	19-Dec-14	Fired on Bolt Closing	Altered Adjustments or Components	481293	F	Per Ilion - Repair at no charge under recall
11174	700	27361	270 WIN	27-Jan-12	N	S	19-Dec-14	19-Dec-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	481192	F	Per Ilion: Repair at no charge
11175	700	not avail.	3006 SPR	18-Mar-74	N	S	19-Dec-14	19-Dec-14	Delayed Firing - Firearms	Improper Maintenance	481309	F	Per Ilion: Repair at no charge
11176	1187	83626	20 GA	20-May-14	N	S	19-Dec-14	19-Dec-14	Fired on Bolt Closing	Could Not Duplicate Concern	481333	F	Per Ilion: Repair at no charge
11177	700	84150	243 WIN	27-Jan-10	N	S	19-Dec-14	19-Dec-14	Fired on Safe Release	Could Not Duplicate Concern	481331	F	Per Ilion - Repair at no charge under recall.
11182	700	27140	300 RUM	14-Dec-10	N	PI/S	19-Dec-14	19-Dec-14	Fired on Safe Release	Other - Unexamined	n/a	F	Consumer refused to send rifle in for exam
11196	700	N/A	3006 SPRG	25-May-78	N	S	19-Dec-14	28-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	488164	F	Replace trigger assembly, check over and test fire at no charge

RAC001209

Confidential

11197	700	N/A	243 WIN	1-Jun-76	N	S	19-Dec-14	27-Jan-15	Fired on Bolt Opening	Could Not Duplicate Concern	488032	F	Replace trigger assembly, check over and test fire at no charge
11195	887	82500	12 GA	26-May-10	N	PI/S	19-Dec-14	4-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	488059	F	Check over completely, repair as needed, and test at no charge
11180	700	N/A	7MM REM MA		N	PI/S	19-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11186	770	85651	243 WIN	25-Mar-13	Y	S	22-Dec-14	22-Dec-14	Fired on Bolt Closing	Could Not Duplicate Concern	481497	F	Per Ilion: Repair at no charge
11187	XM15-E2S	90829	5.56 MM	12-Mar-13	N	S	22-Dec-14	22-Dec-14	Receiver Damaged	Sent in for Evaluation	481375	F	Per Ilion: Repair at no charge
11188	1100	82800	12 GA	30-May-12	N	S	22-Dec-14	22-Dec-14	Failed to Extract	Sent in for Evaluation	481408	F	Per Ilion: Repair at no charge
11184	SP10	24809	10GA	3-Jun-99	Y	PI/S	22-Dec-14	4-Mar-15	Fired Out of Battery	Sent in for Evaluation	481632	F	Check over & test @ n/c
11194	770	85637	243 WIN	7-Oct-13	Y	PI/S	22-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11198	700	not avail.	7MM MAG	7-Mar-72	N	S	23-Dec-14	15-Jan-15	Fired on Bolt Closing	Altered Adjustments or Components	485289	F	Per Ilion - Repair at n/c - goodwill
11202	700	not avail.	7MM RM	1-Apr-67	N	S	26-Dec-14	26-Dec-14	Firing Pin Follows Down	AFT MKT TRIGGER ASSM	481824	F	Per Ilion: Repair at no charge
11205	7	24791	300 SAUM	26-Sep-02	N	S	26-Dec-14	26-Dec-14	Fired on Bolt Closing	Altered Adjustments or Components	481810	F	Per Ilion: Repair at no charge
11206	600	not avail.	6MM REM	1-May-64	Y	S	26-Dec-14	26-Dec-14	Fired on Bolt Closing	Improper Maintenance	481788	F	Per Ilion - Repair at no charge under recall.
11207	700	not avail.	6MM REM	9-Aug-72	N	S	26-Dec-14	26-Dec-14	Fired on Bolt Closing	Altered Adjustments or Components	481828	F	Per Ilion - Replace TA & test @ n/c
11208	700	not avail.	3006 SPRG	1-Aug-66	N	S	26-Dec-14	26-Dec-14	Fired on Safe Release	Could Not Duplicate Concern	481877	F	Per Ilion: Repair at no charge
11211	770	85652	270 WIN	24-Jun-08	N	S	29-Dec-14	27-Jan-15	Fired With Safe ON	Could Not Duplicate Concern	487896	F	Per Ilion - Replace w/Item# 85652 at n/c
11214	700	27011	270 WIN	26-Apr-04	N	PD/S	29-Dec-14	28-Jan-15	Fired on Safe Release	Altered Adjustments or Components	486986	F	Repair @ n/c - goodwill gesture
11217	600	not avail.	35 REM	1-Jul-65	Y	S	29-Dec-14	26-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	487640	F	Per Ilion - Repair at n/c - goodwill
11212	700	not avail.	270 WIN	10-Nov-72	N	PD/S	29-Dec-14	25-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	487078	F	Repair @ n/c - goodwill
11218	700	26436	300 SAUM	27-Aug-02	N	PD/S	29-Dec-14	23-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	488019	F	Repair @ n/c - goodwill gesture
11215	700	26035	3006 SPRG	30-Jul-01	N	PI/S	29-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11220	710	27410	3006 SPRG	19-May-05	Y	PD/S	30-Dec-14	23-Feb-15	Fired on Bolt Opening	Could Not Duplicate Concern	487938	F	Repair @ n/c - goodwill gesture
11223	700	84079	300 WIN MA	8-May-13	N	S	30-Dec-14	4-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	490509	F	Ilion repaired at n/c
11222	700	27095	3006 SPRG	2-Mar-12	N	PD/S	30-Dec-14	9-Apr-15	Fired With Safe ON	Could Not Duplicate Concern	486364	F	Per Release - Check for \$589.55 & repair rifle @ n/c
11224	700	27097	7MM MAG	18-Sep-08	N	PD/S	30-Dec-14	8-Oct-15	Fired on Bolt Closing	Could Not Duplicate Concern	490123	F	Repair rifle @ n/c under XMP recall, Release for Gilliland - Ck for \$2,943.18
11229	700	not avail.	7mm Expres	25-Sep-79	N	S	31-Dec-14	27-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	487886	F	Ilion repaired at n/c - goodwill
11226	700	27476	270 WIN	27-Jun-02	N	S	31-Dec-14	13-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	493081	F	Ilion repaired at n/c
11228	700	not avail.	3006 SPRG	19-Jul-72	N	S	31-Dec-14	4-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	490081	F	Ilion repaired at n/c
11225	700	85446	243 WIN	20-May-11	N	PD/S	31-Dec-14	22-Oct-15	Unexplained Discharge - No Mention of Safety Position	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam

RAC001210

Confidential

11230	700	27389	300 RUM	11-Aug-06	N	S	31-Dec-14	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11233	700	27474	243 WIN	7-Apr-03	N	S	2-Jan-15	19-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	493689	F	Ilion repaired at n/c
11234	597	26536	17 HMR 338 WIN MA	1-Apr-03	N	PD/S	2-Jan-15	19-Mar-15	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	496641	F	Replace with Ramac 70723 in exchange
11232	700	29725	MA	8-Oct-92	N	PI/S	2-Jan-15	22-Oct-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11237	7	24780	223 REM	22-Aug-83	N	S	5-Jan-15	5-Jan-15	Fired on Bolt Closing	Improper Maintenance	483051	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11238	770	85630	243 WIN	19-Sep-12	N	S	5-Jan-15	5-Jan-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	483314	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11240	870	25133	12 GA SM	1-Oct-12	N	S	5-Jan-15	5-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	483318	F	Per Ilion: Repair at no charge
11241	700	not avail.	270 WIN	1-Jan-80	N	S	5-Jan-15	5-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	483322	F	Per Ilion: Repair at no charge
11242	721	not avail.	270WIN	1-Jan-67	Y	S	5-Jan-15	5-Jan-15	Fired on Safe Release	Improper Maintenance	483212	F	Per Ilion: Repair at no charge
11255	770	85633	3006 SPRG	10-Jul-08	N	S	5-Jan-15	26-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	487760	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11245	700	not avail.	3006 SPR	9-May-73	Y	S	6-Jan-15	6-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	483640	F	Per Ilion- Replace TA under BLP
11246	721	not avail.	3006SPR 7MM REM MA	1-Jan-68	Y	S	6-Jan-15	6-Jan-15	Fired on Safe Release	Improper Maintenance	482812	F	Per Ilion: Repair at no charge
11254	700	25803	MA	6-Oct-86	N	S	6-Jan-15	6-Jan-15	Fired on Bolt Closing	Altered Adjustments or Components	483675	F	Per Ilion: Repair at no charge
11256	541	not avail.	22 RF	13-Nov-73	Y	S	6-Jan-15	6-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	482336	F	Per Ilion: Repair at no charge
11260	700	26287	3006 SPRG	29-Jun-04	N	S	6-Jan-15	22-Oct-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11262	700	not avail.	3006 SPRG	18-Jul-75	N	S	6-Jan-15	22-Oct-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11249	700	20000			N	S	6-Jan-15	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11261	887	82500	12 GA 7MM08 REM	21-Oct-09	N	S	6-Jan-15	22-Oct-15	Unexplained Discharge - No Mention of Safety Position	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11264	700	85591		24-Jun-11	N	S	7-Jan-15	7-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	483751	F	Per Ilion- Repair at no charge under recall.
11266	SPR 310	89564	12 GA 22-250 REM	3-Sep-07	Y	S	7-Jan-15	7-Jan-15	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	483741	F	Per Customer- Return as received
11275	700	not avail.		12-Jan-79	N	PD/S	7-Jan-15	7-Jan-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
11271	700	not avail.	3006 SPR 7MM REM MA	13-Jul-73	N	S	8-Jan-15	8-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	484158	F	Per Ilion: Repair at no charge
11273	770	85635		3-Nov-10	Y	S	8-Jan-15	8-Jan-15	Fired With Safe ON	Altered Adjustments or Components	483967	F	Per Ilion: Repair at no charge
11274	722	not avail.	243 WIN	1-Jul-61	Y	S	8-Jan-15	8-Jan-15	Fired on Bolt Closing	Improper Maintenance	483960	F	Per Ilion- Replace TA under BLP
11276	770	85649	243 WIN	21-Nov-12	N	S	8-Jan-15	3-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	489177	F	Ilion repaired at n/c

RAC001211

Confidential

11278	700	27389	300 RUM	9-Aug-06	N	PD/S	8-Jan-15	24-Mar-15	Fired on Safe Release	Could Not Duplicate Concern	490807	F	Repair @ n/c
11279	700	25771	270 WIN	19-Nov-85	N	S	9-Jan-15	9-Jan-15	Safety not working properly	Sent in for Evaluation	484238	F	Per Ilion: Repair at no charge
11280	870	not avail.	12 GA	6-Feb-88	N	S	9-Jan-15	9-Jan-15	Broken Part	Sent in for Evaluation	484221	F	Per Ilion: Repair at no charge
11283	700	27337	3006 SPRG	7-Feb-07	N	S	9-Jan-15	29-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	488846	F	Ilion repaired at n/c
11286	700	not avail.	3006 SPRG	11-Sep-75	N	S	9-Jan-15	29-Jan-15	Fired on Bolt Opening	Could Not Duplicate Concern	488906	F	Ilion repaired at n/c
11303	700	N/A	25-06 REM	23-Mar-81	N	PD/S	9-Jan-15	12-Feb-15	Fired on Safe Release	Improper Maintenance	491859	F	Check over completely, repair as needed, and test at no charge
11302	700	N/A	3006 SPRG 22-250 REM	8-Jun-78	N	PD/S	9-Jan-15	26-May-15	Fired on Safe Release	Could Not Duplicate Concern	499481	F	Check over completely, repair as needed, and test at no charge
11292	700	N/A		12-Jul-77	N	PD/S	9-Jan-15	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11291	700	25767	243 WIN	13-Nov-86	N	PD/S	9-Jan-15	22-Oct-15	Unexplained Discharge - No Mention of Safety Position	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11293	700	not avail.	3006 SPR	24-Mar-75	N	S	12-Jan-15	12-Jan-15	Fired on Bolt Closing	Altered Adjustments or Components	484779	F	Per Ilion- Replace TA under BUP
11294	700	27476	270 WIN	16-May-96	N	S	12-Jan-15	12-Jan-15	Delayed Firing - Firearms	Improper Maintenance	484774	F	Per Ilion: Repair at no charge
11295	788	not avail.	243 WIN	20-Aug-81	Y	S	12-Jan-15	12-Jan-15	Fired on Safe Release	Improper Maintenance	484506	F	Per Ilion: Repair at no charge
11296	700	26253	270 WIN	23-Mar-01	N	S	12-Jan-15	12-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	484491	F	Per Ilion: Repair at no charge
11297	721	not avail.	270WIN	1-Apr-71	Y	S	12-Jan-15	12-Jan-15	Fired on Safe Release	Sent in for Evaluation	484514	F	Per Ilion- Replace TA under BUP
11298	700	25791	270 WIN	30-Oct-95	N	S	12-Jan-15	12-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	484534	F	Per Ilion: Repair at no charge
11299	660	not avail.	243 WIN	1-Feb-68	Y	S	12-Jan-15	12-Jan-15	Fired on Safe Release	Improper Maintenance	484511	F	Per Ilion- Replace TA under BUP
11306	700	N/A	3006 SPRG	29-May-74	N	PD/S	12-Jan-15	12-Feb-15	Fired on Bolt Opening	Could Not Duplicate Concern	492377	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11300	700	not avail.	3006 SPRG	17-Jun-81	N	PI/PD/S	12-Jan-15	8-Apr-15	Fired on Safe Release	Could Not Duplicate Concern	491734	F	Repair @ n/c - goodwill
11308	700	not avail.	243 WIN	3-Nov-83	N	S	13-Jan-15	13-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	484800	F	Per Ilion: Repair at no charge
11309	EXCELL AUTO	72350	12GA VT 7M REM MAG	26-May-10	N	S	13-Jan-15	13-Jan-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	484861	F	Per Ilion- Replace under warranty with Ramac #72350
11310	700	25803		26-Oct-89	N	S	13-Jan-15	13-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	484796	F	Per Ilion: Repair at no charge
11311	700	not avail.	270 WIN	24-Jun-80	N	S	13-Jan-15	13-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	484817	F	Per Ilion- Replace TA under BUP
11312	700	85577	300 WIN MA	27-May-10	N	S	13-Jan-15	13-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	484971	F	Per Ilion- Repair at no charge under recall.
11313	R15	60018	5.56MM	9-Jan-14	N	S	13-Jan-15	13-Jan-15	Went Automatic	Could Not Duplicate Concern	484844	F	Per Ilion: Repair at no charge

RAC001212

Confidential

11315	700	25815	7MM REM MA	20-Apr-91	N	PI/S	13-Jan-15	19-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	492563	F	Check over completely, repair as needed, and test at no charge
11317	700	26285	7MM-08	31-Jul-02	N	S	14-Jan-15	12-Feb-15	Dissatisfied with Service - Firearms	Sent in for Evaluation	493039	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11319	700	26039	7MM REM MA	22-Jul-00	N	S	14-Jan-15	9-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	490763	F	Per Ilion, check over completely, repair as needed, and test at no charge.
11320	700	not avail.	3006 SPRG	14-Feb-76	N	S	14-Jan-15	5-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	490501	F	Ilion repaired at n/c
11322	700	25834	300 RUM	17-Aug-00	N	S	15-Jan-15	15-Jan-15	Fired on Bolt Opening	Could Not Duplicate Concern	485392	F	Per Ilion: Repair at no charge
11324	700	not avail.	308 WIN	17-Feb-83	N	S	15-Jan-15	15-Jan-15	Fired on Safe Release	Improper Maintenance	485404	F	Per Ilion: Repair at no charge
11326	700	not avail.	243WIN	30-Jun-75	N	S	15-Jan-15	15-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	485239	F	Per Ilion- Replace TA under BLP
11327	700	not avail.	3006SPR	23-May-80	N	S	15-Jan-15	15-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	485291	F	Per Ilion- Replace TA under BLP
11328	700	27011	270 WIN	14-May-04	N	S	15-Jan-15	15-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	485230	F	Per Ilion: Repair at no charge
11329	887	82540	12 GA	24-Feb-14	N	S	15-Jan-15	15-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	485293	F	Per Ilion- Repair under 887 recall
11330	700	84216	22-250REM	24-May-13	N	S	15-Jan-15	15-Jan-15	Fired on Bolt Opening	Could Not Duplicate Concern	485312	F	Per Ilion: Repair at no charge
11331	770	85636	300 WIN MA	15-Aug-14	Y	S	15-Jan-15	15-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	485237	F	Per Ilion- Replace under warranty with Ramac #85636
11337	700	N/A	243 WIN	1-Jul-65	N	S	15-Jan-15	16-Jan-15	Fired on Safe Release	Improper Maintenance	485655	F	Per Ilion, replace trigger and test at no charge.
11334	700	25773	3006 SPRG	29-Jun-94	N	S	15-Jan-15	9-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	490761	F	Per Ilion: Repair at no charge
11335	700	not avail.	3006 SPR	29-May-75	N	S	16-Jan-15	16-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	485529	F	Per Ilion- Replace TA under BLP
11336	700	N/A	3006 SPR	20-Mar-69	N	S	16-Jan-15	16-Jan-15	Other - Firearms	Sent in for Evaluation	485567	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11338	700	not avail.	3006 SPRG		N	S	16-Jan-15	16-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	485525	F	Repair @ n/c - goodwill gesture
11339	700	N/A	25-06 REM	6-May-70	N	S	16-Jan-15	16-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	485569	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11340	700	N/A	7MM REMMAG	31-Oct-78	N	S	16-Jan-15	16-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	485474	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11341	SEVEN	27297	308 WIN	27-Mar-07	N	S	16-Jan-15	16-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	485649	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11345	700	N/A	222 REM	4-Mar-74	N	PD/S	16-Jan-15	16-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	490751	F	Check over completely, repair as needed, and test at no charge
11347	597	26536	17 HMR	29-Jan-03	N	PD/S	16-Jan-15	11-Feb-15	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	492056	F	Converting to 22 WMR as requested by customer

RAC001213

Confidential

11349	700	not avail.	270 WIN	24-May-72	N	PD/S	16-Jan-15	9-Feb-15	Fired on Bolt Closing	Altered Adjustments or Components	491618	F	Ilion repaired at n/c - goodwill
11351	700	not avail.	3006 SPRG	13-Jul-73	N	S	16-Jan-15	10-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	490800	F	Per Ilion- Replace TA under BLP
11352	700	not avail.	3006 SPRG	23-Oct-87	N	S	16-Jan-15	12-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	493030	F	Per Ilion: Replace TA at no charge
11350	700	27093	243 WIN	11-Jun-08	N	S	16-Jan-15	2-Mar-15	Fired on Safe Release	Sent in for Evaluation	494556	F	Replace with Ramac 27355 in exchange
11346	700	25854	22-250 REM	23-Apr-86	N	PD/S	16-Jan-15	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11344	700	not avail.	3006 SPRG		N	PD/S	16-Jan-15	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11348	700	27299	25-06 REM	20-May-09	N	PI/PD/S	16-Jan-15	*	Fired on Safe Release	Could Not Duplicate Concern	491875	F	
11362	887	82500	12 GA	16-Jul-14	N	S	19-Jan-15	25-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	493967	F	Refunded purchase price.
11363	597	26516	17 HMR	30-Sep-03	N	PI/PD/S	19-Jan-15	18-Feb-15	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	492132	F	Sending \$200 coupon in exchange for gun.
11353	700	27476	270 WIN	18-Mar-04	N	S	20-Jan-15	20-Jan-15	Fired on Safe Release	Improper Maintenance	485042	F	Per Ilion: Repair at no charge
11355	Seven	not avail.	223 REM	8-Mar-88	N	S	20-Jan-15	20-Jan-15	Safety not working properly	Altered Adjustments or Components	486204	F	Per Ilion: Repair at no charge
11358	700	27387	300WIN MAG	29-Nov-05	N	S	20-Jan-15	20-Jan-15	Fired on Bolt Closing	Altered Adjustments or Components	486103	F	Per Ilion: Repair at no charge
11359	700	not avail.	3006 SPR	4-Mar-80	N	S	20-Jan-15	20-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	485875	F	Per Ilion- Replace TA under BLP
11360	700	not avail.	25-06REM	4-May-70	N	S	20-Jan-15	20-Jan-15	Other - Firearms	Sent in for Evaluation	486145	F	Per Ilion- Replace TA under BLP
11361	770	85633	3006 SPR	3-Dec-13	Y	S	20-Jan-15	20-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	485821	F	Per Ilion: Repair at no charge
11364	700	20000	7MM MAG		N	PD/S	20-Jan-15	22-Oct-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11366	1911 R1	96323	45 ACP	19-Apr-13	N	S	21-Jan-15	21-Jan-15	Fired With Safe ON	Sent in for Evaluation	485982	F	Per Ilion: Repair at no charge
11367	VERSA MAX	81048	12 GA	27-Jan-14	N	S	21-Jan-15	21-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	486404	F	Per Ilion: Replace with Ramac #81048
11368	870	81136	12 GA	5-Aug-13	N	S	21-Jan-15	21-Jan-15	Fails to Eject	Could Not Duplicate Concern	486362	F	Per Ilion: Repair at no charge
11370	700	25801	17 REM	13-Feb-02	N	S	21-Jan-15	21-Jan-15	Fired on Safe Release	Altered Adjustments or Components	486245	F	Per Ilion: Repair at no charge
11371	783	85837	308 WIN	23-Sep-13	N	S	21-Jan-15	21-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	486695	F	Per Ilion: Repair at no charge
11372	700	not avail.	270 WIN	23-Feb-72	N	S	21-Jan-15	21-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	486690	F	Per Ilion: Repair at no charge
11373	700	not avail.	3006 SPR	1-Jun-64	N	S	21-Jan-15	21-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	486248	F	Per Ilion- Replace TA under BLP
11374	700	not avail.	7MM REM MA	13-Sep-77	N	S	21-Jan-15	21-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	486232	F	Per Ilion- Replace TA under BLP
11375	700	not avail.	6MM REM	19-Apr-80	N	S	21-Jan-15	21-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	486691	F	Per Ilion- Replace TA under BLP
11391	597	26536	17 HMR	19-Nov-02	N	PD/S	21-Jan-15	25-Feb-15	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	493023	F	Replace with Ramac 70723 in exchange
11388	700	N/A	270 WIN	22-Jul-78	N	PD/S	21-Jan-15	24-Apr-15	Fired on Bolt Closing	Could Not Duplicate Concern	498765	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11384	700	N/A	3006 SPRG	1-Apr-71	N	PD/S	21-Jan-15	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam

RAC001214

Confidential

11377	DPMS A-15	not avail.	5.56MM	1-Jan-14	N	S	22-Jan-15	22-Jan-15	Unknown Claim	Sent in for Evaluation	486660	F	Per Ilion: Repair at no charge
11378	700	not avail.	270 WIN	6-Apr-72	N	S	22-Jan-15	22-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	486373	F	Per Ilion- Replace TA under BLP
11379	700	85619	270 WIN	7-Mar-13	N	S	22-Jan-15	22-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	486639	F	Per Ilion- Repair at no charge under recall.
11380	700	not avail.	3006 SPR	31-Oct-73	N	S	22-Jan-15	22-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	486382	F	Per Ilion- Replace TA under BLP
11381	700	not avail.	22-250REM	28-Feb-73	N	S	22-Jan-15	22-Jan-15	Fired With Safe ON	Altered Adjustments or Components	486431	F	Per Ilion- Replace TA under BLP
11382	700	27480	7MM REM MA	31-Oct-96	N	S	22-Jan-15	22-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	486351	F	Per Ilion: Repair at no charge
11385	770	85633	3006 SPR	27-Apr-12	N	S	22-Jan-15	22-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	486380	F	Per Ilion, check over completely, repair as needed, and test at no charge.
11386	710	27410	3006 SPR	20-Sep-06	Y	S	22-Jan-15	22-Jan-15	Fail to Fire	Could Not Duplicate Concern	486738	F	Check over completely, repair as needed, and test at no charge
11389	700	25789	2506 REM	20-Feb-92	N	S	22-Jan-15	22-Jan-15	Delayed Firing - Firearms	Could Not Duplicate Concern	486735	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11390	700	27165	270 WIN	17-Sep-07	N	S	22-Jan-15	22-Jan-15	Fired With Safe ON	Could Not Duplicate Concern	486795	F	Per Ilion- Repair at no charge under recall.
11393	700	25803	7MM REM MA	26-Feb-86	N	S	23-Jan-15	23-Jan-15	Fired on Safe Release	Altered Adjustments or Components	486996	F	Per Ilion: Repair at no charge
11394	788	not avail.	243 WIN	26-Mar-81	Y	S	23-Jan-15	23-Jan-15	Fired on Safe Release	Improper Maintenance	486819	F	Per Ilion- Repair at 1/2 cost good will gesture
11395	700	not avail.	6MM REM	4-Dec-75	N	S	23-Jan-15	23-Jan-15	Other - Firearms	Could Not Duplicate Concern	486994	F	Per Ilion- Replace TA under BLP
11396	700	27474	243 WIN	6-Mar-98	N	S	23-Jan-15	23-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	487066	F	Per Ilion: Repair at no charge
11397	700	not avail.	270 WIN	10-Oct-80	N	S	23-Jan-15	23-Jan-15	Fired on Safe Release	Improper Maintenance	487061	F	Per Ilion- Replace TA under BLP
11399	700	25845	260 REM	10-May-01	N	S	23-Jan-15	23-Jan-15	Barrel Damaged/Bulged (Other than Burst)	Sent in for Evaluation	487072	F	Per Ilion: Repair at no charge
11400	700	25709	308 WIN	28-Feb-07	N	S	23-Jan-15	23-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	487080	F	Per Ilion: Repair at no charge
11401	700	25709	308 WIN	14-Jan-03	N	S	23-Jan-15	23-Jan-15	Fired With Safe ON	Could Not Duplicate Concern	487081	F	Per Ilion: Repair at no charge
11403	700	25711	308 WIN	9-Nov-00	N	S	23-Jan-15	23-Jan-15	Fired With Safe ON	Could Not Duplicate Concern	487064	F	Per Ilion: Repair at no charge
11405	CARBON 15	90872	5.56MM	3-Dec-13	N	S	25-Jan-15	25-Jan-15	Went Automatic	Could Not Duplicate Concern	487531	F	Per Ilion: Repair at no charge
11406	770	85633	3006 SPR	8-Sep-10	N	S	25-Jan-15	25-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	487156	F	Per Ilion: Repair at no charge
11410	700	25632	280 REM	14-May-90	N	S	26-Jan-15	26-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	487167	F	Per Ilion: Repair at no charge
11412	700	not avail.	3006 SPR	27-Aug-82	N	S	26-Jan-15	26-Jan-15	Delayed Firing - Firearms	Could Not Duplicate Concern	487565	F	Per Ilion: Repair at no charge
11413	700	25709	308 WIN	5-Dec-01	N	S	26-Jan-15	26-Jan-15	Fired on Safe Release	Altered Adjustments or Components	487457	F	Per Ilion: Repair at no charge
11414	700	not avail.	3006 SPR	7-Dec-70	N	S	26-Jan-15	26-Jan-15	Fired on Safe Release	Altered Adjustments or Components	487456	F	Per Ilion- Replace TA under BLP
11415	SEVEN	29543	7MM REM SA	3-Feb-03	N	S	26-Jan-15	26-Jan-15	Fired on Safe Release	Improper Maintenance	487642	F	Per Ilion: Repair at no charge
11417	700	85373	270 WIN	19-Jan-10	N	S	26-Jan-15	26-Jan-15	Fired on Bolt Closing	Altered Adjustments or Components	487503	F	Per Ilion: Repair at no charge
11419	700	not avail.	3006 SPR	9-Apr-75	N	S	26-Jan-15	26-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	487639	F	Per Ilion- Replace TA under BLP

RAC001215

Confidential

11424	700	25767	243 WIN	10-Aug-95	N	S	26-Jan-15	20-Mar-15	Fired on Bolt Closing Unexplained Discharge - No	Other - Unspecified or Undetermined - Firearms	495879	F	Ilion replaced trigger assemb. @ n/c
11426	700	N/A	3006 SPR	21-Sep-71	N	S	27-Jan-15	27-Jan-15	Sent in for Evaluation		487644	F	Per Ilion, check over completely, repair as needed,
11427	600	not avail.	6MM REM	1-Mar-67	Y	S	27-Jan-15	27-Jan-15	Fired on Safe Release	Altered Adjustments or Components	487929	F	Per Ilion: Repair at no charge
11429	700	27478	3006 SPR	5-Feb-01	N	S	27-Jan-15	27-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	487974	F	Per Ilion- Repair at 1/2 cost good will gesture
11430	887	82500	12 GA	23-Jun-14	N	S	27-Jan-15	27-Jan-15	Fired on Bolt Closing	Sent in for Evaluation	487691	F	Per Ilion- Repair at no charge under recall.
11428	700	not avail.	7MM REM MA	26-Oct-78	N	PD/S	27-Jan-15	2-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	487651	F	Repair @ n/c - goodwill gesture
11439	700	not avail.	243 WIN	13-Dec-75	N	PD/S	27-Jan-15	8-Apr-15	Fired on Safe Release	Improper Maintenance	492392	F	Repair @ n/c - goodwill
11436	700	N/A	3006 SPRG	2-Jun-71	N	PI/S	27-Jan-15	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11443	870	25133	12 GA SMAG	16-Aug-13	N	S	28-Jan-15	28-Jan-15	Action works hard	Fired from Contact with Foreign Object	488036	F	Per Ilion: Repair at no charge
11444	700	not avail.	243 WIN	18-Sep-81	N	S	28-Jan-15	28-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	488013	F	Per Ilion- Replace TA under BLP
11446	700	not avail.	243 WIN	1-May-68	N	S	28-Jan-15	28-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	488123	F	Per Ilion- Replace TA under BLP
11447	700	25935	300 WIN MA	30-Nov-99	N	S	28-Jan-15	28-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	488104	F	Per Ilion - Repair at n/c - goodwill
11448	700	not avail.	3006 SPR	30-Sep-88	N	S	28-Jan-15	28-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	488077	F	Per Ilion: Repair at no charge
11449	700	not avail.	25-06 REM	12-Apr-76	N	S	28-Jan-15	28-Jan-15	Fired on Safe Release	Altered Adjustments or Components	488092	F	Per Ilion- Replace TA under BLP
11453	700	not avail.	25-06 REM	18-May-70	N	S	28-Jan-15	28-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	488242	F	Per Ilion- Replace TA under BLP
11454	700	25803	7MM REM MA	12-Nov-03	N	S	28-Jan-15	28-Jan-15	Fired on Bolt Closing	Could Not Duplicate Concern	488361	F	Per Ilion: Repair at no charge
11456	700	not avail.	7MM REM MA	1-Nov-68	N	S	28-Jan-15	28-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	488234	F	Per Ilion: Repair at no charge
11457	700	not avail.	7MM MAG		N	S	28-Jan-15	28-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	488277	F	Per Ilion- Replace TA under BLP
11459	770	85666	308 WIN	14-May-13	N	S	28-Jan-15	28-Jan-15	Delayed Firing - Firearms	Sent in for Evaluation	488389	F	Per Ilion: Repair at no charge
11460	700	N/A	3006 SPR	10-Mar-76	N	S	28-Jan-15	28-Jan-15	Fired on Bolt Opening	Altered Adjustments or Components	488279	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11455	700	not avail.		9-May-74	N	PD/S	28-Jan-15	22-Oct-15	Fired on Bolt Opening	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11463	SEVEN	24786	7MM-08 REM	6-Nov-98	N	S	29-Jan-15	29-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	488637	F	Per Ilion: Repair at no charge
11465	700	not avail.	3006 SPR	1-Oct-74	N	S	29-Jan-15	29-Jan-15	Fired on Bolt Closing	Altered Adjustments or Components	488720	F	Per Ilion- Replace TA under BLP
11466	700	not avail.	3006 SPR	1-Sep-78	N	S	29-Jan-15	29-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	488683	F	Per Ilion- Replace TA under BLP
11467	700	25846	300 WIN MA	23-Jun-83	N	S	29-Jan-15	29-Jan-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	488593	F	Per Ilion: Repair at no charge
11469	725	not avail.	222 REM	1-Feb-61	Y	S	29-Jan-15	29-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	488807	F	Per Ilion- Repair at 1/2 cost
11470	700	26342	7MM-08 REM	26-Feb-01	N	S	29-Jan-15	29-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	488912	F	Per Ilion: Repair at no charge
11471	700	not avail.	3006 SPR	3-Mar-71	N	S	29-Jan-15	29-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	488781	F	Per Ilion- Replace TA under BLP

RAC001216

Confidential

11472	700	not avail.	3006 SPR	14-Jun-79	N	S	29-Jan-15	29-Jan-15	Fired on Safe Release	Could Not Duplicate Concern	488777	F	Per Ilion- Replace TA under BLP
11473	700	not avail.	3006 SPR	1-Jan-68	N	S	29-Jan-15	29-Jan-15	Fired on Safe Release	Improper Maintenance	488938	F	Per Ilion- Replace TA under BLP
11474	700	27009	25-06 REM	18-Nov-04	N	PD/S	29-Jan-15	16-Apr-15	Fired on Bolt Closing	Could Not Duplicate Concern	493880	F	Repair @ n/c - goodwill gesture
11475	700	27136	308 WIN	29-Mar-11	N	S	30-Jan-15	3-Feb-15	Fired on Safe Release	Other - Unexamined	n/a	F	Dealer offered to replace the trigger for the consumer
11480	700	N/A	22-250 REM	20-Mar-78	N	PD/S	30-Jan-15	11-Mar-15	Fired on Bolt Opening	Improper Maintenance	493900	F	Replace trigger assembly, check over and test fire at no charge
11481	700	84203	308 WIN	18-Jun-12	N	PI/PD/S	2-Feb-15	22-Oct-15	Unexplained Discharge - No Mention of Safety Position	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11482	700	27095	3006 SPR	8-Jan-13	N	S	3-Feb-15	3-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	489367	F	Per Ilion: Repair at no charge
11483	770	85633	3006 SPR	8-Oct-08	Y	S	3-Feb-15	3-Feb-15	Fired on Bolt Closing	Altered Adjustments or Components	489363	F	Per Ilion: Repair at no charge
11486	700	not avail.	243 WIN	19-Jun-75	N	S	3-Feb-15	3-Feb-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	489102	F	Per Ilion- Replace TA under BLP
11487	700	84100	280 REM	12-Mar-07	N	S	3-Feb-15	3-Feb-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	489037	F	Per Ilion- Repair at no charge under recall.
11488	700	not avail.	3006 SPR	13-Sep-79	N	S	3-Feb-15	3-Feb-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	489157	F	Per Ilion- Replace TA under BLP
11490	700	not avail.	7MM REM MA	1-Sep-84	N	S	3-Feb-15	3-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	489149	F	Per Ilion- Replace TA under BLP
11492	700	25773	3006 SPR	12-Oct-89	N	S	3-Feb-15	3-Feb-15	Fired on Safe Release	Altered Adjustments or Components	488954	F	Per Ilion: Repair at no charge
11493	600	not avail.	308 WIN	1-Jul-05	Y	S	3-Feb-15	3-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	489370	F	Per Ilion- Replace TA under BLP
11495	700	29679	7MM REM MA	17-Jul-96	N	S	3-Feb-15	3-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	489362	F	Per Ilion: Repair at no charge
11496	700	not avail.	3006 SPR	2-May-77	N	S	3-Feb-15	3-Feb-15	Fired on Bolt Closing	Altered Adjustments or Components	489361	F	Per Ilion- Replace TA under BLP
11497	700	25813	3006 SPR	25-Aug-89	N	S	3-Feb-15	3-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	489360	F	Per Ilion: Repair at no charge
11499	700	not avail.	3006 SPRIG	1-Apr-71	N	PD/S	3-Feb-15	25-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	493806	F	Ilion repaired at n/c
11491	700	85272	243 WIN	9-May-12	N	S	3-Feb-15	13-Mar-15	Fired on Bolt Closing	Could Not Duplicate Concern	495467	F	Check over completely, repair as needed, and test at no charge
11542	700	85598	7MM MAG	3-Feb-12	N	PI/S	3-Feb-15	3-Mar-15	Fired on Safe Release	Could Not Duplicate Concern	494674	F	Per Ilion- Repair at no charge under recall.
11501	600	not avail.	6MM REM	1-May-64	Y	S	4-Feb-15	4-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	490350	F	Per Ilion- Replace TA under BLP
11503	700	not avail.	270 WIN	27-Oct-70	N	S	4-Feb-15	4-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	490477	F	Per Ilion- Replace TA under BLP
11504	700	25903	300 WBY MA	20-Jun-89	N	S	4-Feb-15	4-Feb-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	490218	F	Per Ilion: Repair at no charge
11505	700	27480	7MM REM MA	27-Jul-00	N	S	4-Feb-15	4-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	490085	F	Per Ilion: Repair at no charge

RAC001217

Confidential

11506	700	not avail.	270 WIN	27-Apr-72	N	S	4-Feb-15	4-Feb-15	Fired on Safe Release	Improper Maintenance	490405	F	Per Ilion: Repair at no charge
11508	600	not avail.	308 WIN	1-Apr-68	N	S	4-Feb-15	4-Feb-15	Fired on Safe Release	Improper Maintenance	489851	F	Per Ilion- Replace TA under BLP
11509	600	not avail.	308 WIN	1-Jul-66	N	S	4-Feb-15	4-Feb-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	489776	F	Per Ilion- Replace TA under BLP
11510	700	not avail.	3006 SPR	1-Oct-74	N	S	4-Feb-15	4-Feb-15	Delayed Firing - Firearms	Could Not Duplicate Concern	490543	F	Per Ilion- Replace TA under BLP
11513	700	not avail.	243 WIN	21-Jul-72	N	S	4-Feb-15	4-Feb-15	Fired on Bolt Closing	Altered Adjustments or Components	490467	F	Per Ilion- Replace TA under BLP
11514	700	not avail.	3006 SPR	21-Aug-75	N	S	4-Feb-15	4-Feb-15	Fired on Bolt Closing	Altered Adjustments or Components	489763	F	Per Ilion- Replace TA under BLP
11515	SEVEN	24788	308 WIN	26-Apr-99	N	S	4-Feb-15	4-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	490315	F	Per Ilion: Repair at no charge
11516	700	not avail.	3006 SPR	11-Apr-75	N	S	4-Feb-15	4-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	489685	F	Per Ilion- Replace TA under BLP
11518	SEVEN	24734	260 REM	11-Jan-00	N	S	4-Feb-15	4-Feb-15	Fired on Bolt Closing	Altered Adjustments or Components	489603	F	Per Ilion: Repair at no charge
11512	700	27105	270 WIN	6-Sep-07	N	PD/S	4-Feb-15	22-Oct-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11522	700	29692	7MM REM MA	9-Jan-95	N	S	5-Feb-15	5-Feb-15	Wrong Ammunition Fired in Gun	Sent in for Evaluation	489771	F	Per Ilion- Repair at 1/2 cost
11523	700	27357	7MM-08 REM	22-Sep-05	N	S	5-Feb-15	5-Feb-15	Unknown Claim	Sent in for Evaluation	489403	F	Per Ilion: Repair at no charge
11524	700	not avail.	243 WIN	10-Feb-72	N	S	5-Feb-15	5-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	489399	F	Per Ilion- Replace TA under BLP
11525	700	not avail.	3006 SPR	1-Sep-85	N	S	5-Feb-15	5-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	489833	F	Per Ilion: Repair at no charge
11526	700	29694	300 WIN MA	16-Jan-95	N	S	5-Feb-15	5-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	490540	F	Per Ilion: Repair at no charge
11527	700	not avail.	3006 SPR	24-Aug-76	N	S	5-Feb-15	5-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	489401	F	Per Ilion- Replace TA under BLP
11530	700	not avail.	308 WIN	16-Jun-76	N	S	5-Feb-15	5-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	489552	F	Per Ilion- Replace TA under BLP
11533	887	82530	12 GA	9-Apr-10	N	S	5-Feb-15	5-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	491852	F	Per Ilion: Repair at no charge
11534	870	25100	12 GA SMAG	20-Oct-99	N	S	5-Feb-15	5-Feb-15	Fired With Safe ON	Could Not Duplicate Concern	491536	F	Per Ilion- Repair at 1/2 cost
11535	700	27249	338 LAPUA	7-Feb-11	N	S	6-Feb-15	6-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	490873	F	Per Ilion: Repair at no charge
11540	870	25102	12 GA SMAG	19-May-00	N	S	6-Feb-15	6-Feb-15	Fired With Safe ON	Could Not Duplicate Concern	491863	F	Per Ilion- Repair at 1/2 cost
11543	700	not avail.	3006 SPRG	20-May-83	N	S	6-Feb-15	6-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	491662	F	Per Ilion: Repair at no charge
11545	700	not avail.	35 WHELEN 22-250 REM	25-Jul-88	N	S	7-Feb-15	7-Feb-15	Fired on Bolt Closing	Improper Maintenance	490828	F	Per Ilion: Repair at no charge
11547	700	25783	22-250 REM	13-Oct-03	N	S	7-Feb-15	7-Feb-15	Fired on Safe Release	Altered Adjustments or Components	491733	F	Per Ilion: Repair at no charge
11549	700	not avail.	3006 SPRG	19-Feb-82	N	S	7-Feb-15	7-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	491866	F	Per Ilion- Replace TA under BLP
11550	700	not avail.	3006 SPRG	13-Jul-73	N	S	7-Feb-15	7-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	491850	F	Per Ilion- Replace TA under BLP
11551	660	not avail.	308 WIN	1-Oct-68	Y	S	7-Feb-15	7-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	491861	F	Per Ilion- Replace TA under BLP
11553	700	not avail.	25-06 REM	30-Mar-71	N	S	8-Feb-15	8-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	491870	F	Per Ilion- Replace TA under BLP
11555	700	25791	270 WIN	26-Feb-86	N	S	8-Feb-15	8-Feb-15	Fired on Bolt Closing	Sent in for Evaluation	491735	F	Per Ilion: Repair at no charge

RAC001218

Confidential

11556	700	not avail.	270 WIN	8-May-74	N	S	8-Feb-15	8-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	491862	F	Per Ilion- Replace TA under BLP
11557	700	25773	3006 SPRG	22-Jan-86	N	S	8-Feb-15	8-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	491872	F	Per Ilion: Repair at no charge
11558	600	not avail.	243 WIN		Y	S	9-Feb-15	9-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	491440	F	Per Ilion- Replace TA under BLP
11559	600	not avail.	222 REM	1-Mar-67	Y	S	9-Feb-15	9-Feb-15	Other - Firearms	Sent in for Evaluation	491441	F	Per Ilion- Replace TA under BLP
11560	700	not avail.	3006 SPRG	5-Apr-73	N	S	9-Feb-15	9-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	490864	F	Per Ilion- Replace TA under BLP
11561	700	not avail.	270 WIN	14-May-74	N	S	9-Feb-15	9-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	490984	F	Per Ilion- Replace TA under BLP
11562	700	27359	308 WIN	22-Jun-05	N	S	9-Feb-15	9-Feb-15	Fired on Safe Release	Improper Maintenance	491018	F	Per Ilion: Repair at no charge
11563	700	not avail.	7MM REM MA	1-Jun-75	N	S	9-Feb-15	9-Feb-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	491745	F	Per Ilion- Replace TA under BLP
11564	700	not avail.	22-250 REM	16-Aug-83	N	S	9-Feb-15	9-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	491728	F	Per Ilion: Repair at no charge
11565	700	not avail.	3006 SPRG	2-Feb-72	N	S	9-Feb-15	9-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	490834	F	Per Ilion- Replace TA under BLP
11567	700	84015	3006 SPRG	2-Apr-14	N	S	9-Feb-15	9-Feb-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	491729	F	Per Ilion: Repair at no charge
11568	700	not avail.	22-250 REM	29-May-74	N	S	9-Feb-15	9-Feb-15	Fired on Bolt Closing	Altered Adjustments or Components	491741	F	Per Ilion- Replace TA under BLP
11569	700	27474	243 WIN	14-May-96	N	S	9-Feb-15	9-Feb-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	491615	F	Per Ilion: Repair at no charge
11570	710	27410	3006 SPRG	14-Dec-05	Y	PD/S	9-Feb-15	14-Apr-15	Fired on Bolt Closing	Other - Unspecified or Undetermined - Firearms	494426	F	Repair @ n/c - goodwill gesture
11571	700	84218	308 WIN	8-Dec-10	N	S	10-Feb-15	10-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	491738	F	Per Ilion- Repair at no charge under recall.
11572	700	25818	308 WIN	11-Aug-89	N	S	10-Feb-15	10-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	491737	F	Per Ilion: Repair at no charge
11574	700	not avail.	6MM REM	8-Apr-71	N	S	10-Feb-15	10-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	490819	F	Per Ilion- Replace TA under BLP
11575	770	85631	7MM-08 REM	27-Nov-12	Y	S	10-Feb-15	10-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	491498	F	Per Ilion: Repair at no charge
11576	700	not avail.	270 WIN	18-Dec-80	N	S	10-Feb-15	10-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	491553	F	Per Ilion- Replace TA under BLP
11577	700	not avail.	3006 SPRG	5-Oct-70	N	S	10-Feb-15	10-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	490968	F	Per Ilion- Replace TA under BLP
11578	700	25803	7MM REM MA	4-Dec-92	N	S	10-Feb-15	10-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	491555	F	Per Ilion: Repair at no charge
11580	700	not avail.	7MM REM MA	1-Jul-74	N	S	10-Feb-15	10-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	491178	F	Per Ilion- Replace TA under BLP
11582	700	not avail.	3006 SPRG	5-Jan-72	N	S	10-Feb-15	10-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	492369	F	Per Ilion- Replace TA under BLP
11583	700	27315	7MM RUM	23-Sep-08	N	S	10-Feb-15	10-Feb-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	492389	F	Per Ilion- Repair at no charge under recall.
11584	SEVEN	85952	223 REM	10-Jan-08	N	S	10-Feb-15	10-Feb-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	491977	F	Per Ilion- Repair at no charge under recall.

RAC001219

Confidential

11588	700	not avail.	3006 SPRG	29-Jul-74	N	S	11-Feb-15	11-Feb-15	Other - Firearms	Sent in for Evaluation	492319	F	Per Ilion- Replace TA under BLP
11589	788	not avail.	243 WIN	14-Jun-81	Y	S	11-Feb-15	11-Feb-15	Fired on Bolt Opening	Improper Maintenance	492375	F	Per Ilion: Repair as needed.
11590	700	29737	7MM-08 REM	17-May-93	N	S	11-Feb-15	11-Feb-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	492146	F	Per Ilion: Repair at no charge
11591	700	25746	308 WIN	16-Feb-93	N	S	11-Feb-15	11-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	491896	F	Per Ilion: Repair at no charge
11592	700	27121	270 WIN	20-Jun-13	N	S	11-Feb-15	11-Feb-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	492387	F	Per Ilion- Repair at no charge under recall.
11593	700	not avail.	7MM REM MA	25-Jul-75	N	S	11-Feb-15	11-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	492366	F	Per Ilion- Replace TA under BLP
11595	700	not avail.	3006 SPRG	7-Oct-70	N	S	11-Feb-15	11-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	492550	F	Per Ilion- Replace TA under BLP
11596	700	not avail.	3006 SPRG	18-Sep-84	N	S	11-Feb-15	11-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	492551	F	Per Ilion: Repair at no charge
11598	700	27361	270 WIN	27-Jan-12	N	S	11-Feb-15	11-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	492372	F	Per Ilion- Repair at no charge under recall.
11599	597	26516	17 HMR	25-Oct-04	N	PD/S	11-Feb-15	22-Oct-15	My Gun Blew Up	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11597	700	25798	223 REM	25-Feb-02	N	S	11-Feb-15	22-Oct-15	Fired on Bolt Opening	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11600	700	29735	243 WIN	13-May-93	N	S	12-Feb-15	12-Feb-15	Fired on Safe Release	Altered Adjustments or Components	492371	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11601	700	N/A	270 WIN	12-May-75	N	S	12-Feb-15	12-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	492501	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11604	700	84360	17 REM FIR	9-Mar-07	N	S	12-Feb-15	12-Feb-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	492364	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11605	700	25939	270 WIN	1-Jun-06	N	S	12-Feb-15	12-Feb-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	492379	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11606	770	85662	270 WIN	12-May-10	Y	S	12-Feb-15	12-Feb-15	Delayed Firing - Firearms	Could Not Duplicate Concern	492621	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11607	700	N/A	3006 SPR	5-Oct-73	N	S	12-Feb-15	12-Feb-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	492393	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11609	700	25803	7MM REM MA	11-Nov-91	N	S	12-Feb-15	12-Feb-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	493015	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11610	700	not avail.	243 WIN	1-Jul-77	N	S	12-Feb-15	12-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	493026	F	Per Ilion- Replace TA under BLP
11603	870	25133	12 GA	6-May-14	N	PI/S	12-Feb-15	1-Apr-15	Excessive Recoil	Sent in for Evaluation	492400	F	Check over, repair if needed & test @ n/c
11615	1100	25414	28 GA	25-Sep-76	N	S	13-Feb-15	13-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	493036	F	Per Ilion- Repair at 1/2 cost good will gesture
11617	770	85634	308 WIN	27-Aug-13	Y	S	13-Feb-15	13-Feb-15	Jar-Off Safe ON	Could Not Duplicate Concern	493061	F	Per Ilion: Repair at no charge
11618	SEVEN	24782	243 WIN	22-Apr-83	N	S	13-Feb-15	13-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	493027	F	Per Ilion: Repair at no charge

RAC001220

Confidential

11619	700	25804	280 REM	3-Sep-92	N	S	13-Feb-15	13-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	493059	F	Per Ilion: Repair at no charge
11621	700	not avail.	243 WIN	10-Jun-76	N	S	13-Feb-15	13-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	493050	F	Per Ilion: Repair at no charge
11623	700	27480	7MM REM MA	21-Jun-01	N	S	13-Feb-15	13-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	493032	F	Per Ilion: Repair at no charge
11624	700	85432	308 WIN	20-Jul-10	N	S	13-Feb-15	13-Feb-15	Light Trigger Pull	Could Not Duplicate Concern	493076	F	Per Ilion: Repair at no charge under recall.
11625	700	25773	3006 SPRG	27-Jul-84	N	S	13-Feb-15	13-Feb-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	493174	F	Per Ilion: Repair at no charge
11620	1911	96324	45 ACP	27-Nov-12	N	PD/S	13-Feb-15	13-Mar-15	Fired Out of Battery	Other - Unspecified or Undetermined - Ammunition	495010	F	Per Ilion, check over completely, repair as needed, and test at no charge.
11627	700	85622	7MM REM MA	29-Nov-12	N	PI/S	13-Feb-15	22-Oct-15	Unexplained Discharge Safe ON	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam
11633	700	26169	7MM REM MA	10-Jun-99	N	S	17-Feb-15	17-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	493197	F	Per Ilion: Repair at no charge
11634	SEVEN	24789	308 WIN	9-Jun-01	N	S	17-Feb-15	17-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	493196	F	Per Ilion: Repair at no charge
11635	700	not avail.	3006 SPRG	2-Oct-70	N	S	17-Feb-15	17-Feb-15	Fired on Bolt Closing	Improper Maintenance	493193	F	Per Ilion- Replace TA under BLP
11637	700	not avail.	270 WIN	15-Apr-69	N	S	17-Feb-15	17-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	493195	F	Per Ilion- Replace TA under BLP
11638	700	29717	3006 SPRG	2-Mar-93	N	S	17-Feb-15	17-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	493366	F	Per Ilion: Repair at no charge
11641	700	27478	3006 SPRG	1-Oct-01	N	S	17-Feb-15	17-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	493192	F	Per Ilion: Repair at no charge
11643	MOKAWK 600	not avail.	6MM REM	8-Feb-73	Y	S	17-Feb-15	17-Feb-15	Fired on Bolt Closing	Altered Adjustments or Components	493365	F	Per Ilion- Replace TA under BLP
11644	700	not avail.	243 WIN	1-May-68	N	S	17-Feb-15	17-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	493302	F	Per Ilion: Repair at no charge
11654	700	27095	3006 SPRG	1-Nov-13	N	PD/S	18-Feb-15	22-May-15	Fired on Bolt Closing Action Opened on Firing	Could Not Duplicate Concern	499441	F	Check over completely, repair as needed, and test at no charge
11645	332	25237	12 GA	17-Aug-04	Y	S	19-Feb-15	19-Feb-15		Sent in for Evaluation	492166	F	Per Ilion: Repair at no charge
11647	700	N/A	3006 SPRG	22-Sep-70	N	S	19-Feb-15	19-Feb-15	Fired on Bolt Opening	Improper Maintenance	493449	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11650	700	N/A	25-06 REM	1-Mar-70	N	S	19-Feb-15	19-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	493681	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11651	700	85486	243 WIN	28-Apr-12	N	S	19-Feb-15	19-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	493683	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11653	700	not avail.	243 WIN	22-Sep-81	N	S	19-Feb-15	19-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	493679	F	Per Ilion- Replace TA under BLP
11655	770	85633	3006 SPRG	19-Jan-10	Y	S	19-Feb-15	19-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	493677	F	Per Ilion: Repair at no charge
11656	700	not avail.	3006 SPRG	21-Jul-77	N	S	19-Feb-15	19-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	493454	F	Per Ilion- Replace TA under BLP
11659	700	84370	223 REM	2-Sep-09	N	PD/S	19-Feb-15	27-Mar-15	Fired on Bolt Closing	Sent in for Evaluation	497115	F	Check over completely, repair as needed, and test at no charge
11658	887	82502	12 GA	8-Sep-09	N	PD/S	19-Feb-15	22-Oct-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Firearm not returned to Ilion for exam

RAC001221

Confidential

11663	870	25098	12 GA	16-Dec-08	N	PD/S	24-Feb-15	10-Mar-15	My Gun Blew Up	Fired from Contact with Foreign Object	495356	F	Per Ilion, check over completely, repair as needed, and test at no charge.
11664	887	82500	12 GA	18-Mar-15	N	S	25-Feb-15	25-Feb-15	Delayed Firing - Firearms	Could Not Duplicate Concern	493838	F	Per Ilion: Repair at no charge
11665	700	27337	3006 SPRG	24-May-05	N	S	25-Feb-15	25-Feb-15	Fired on Safe Release	Altered Adjustments or Components	493807	F	Per Ilion: Repair at no charge
11666	700	25793	3006 SPRG	11-Sep-86	N	S	25-Feb-15	25-Feb-15	Fired With Safe ON	Could Not Duplicate Concern	493805	F	Per Ilion: Repair at no charge
11668	700	not avail.	7MM REM MA	22-Mar-72	N	S	25-Feb-15	25-Feb-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	493821	F	Per Ilion- Replace TA under BLP
11669	887	82540	12 GA	18-Jun-12	N	S	25-Feb-15	25-Feb-15	Failed to Extract	Sent in for Evaluation	493965	F	Per Ilion- Evaluate for WIP
11670	700	25791	270 WIN	20-Jun-86	N	S	25-Feb-15	25-Feb-15	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	493922	F	Per Ilion: Repair at no charge
11671	700	85362	223 REM	23-Jun-07	N	S	25-Feb-15	25-Feb-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	493899	F	Per Ilion, check over completely, replace trigger assembly under recall at no charge
11672	700	N/A	270 WIN	27-Oct-88	N	S	25-Feb-15	25-Feb-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	493872	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11674	597	N/A	17 HMR	15-Nov-06	N	PD/S	25-Feb-15	25-Feb-15	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	493990	F	Call Center sent customer \$200
11675	700	25793	3006 SPRG	16-Dec-86	N	S	25-Feb-15	25-Feb-15	Fired With Safe ON	Could Not Duplicate Concern	493952	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11677	700	84371	308 WIN	5-Jun-13	N	PD/S	25-Feb-15	27-Apr-15	Fired on Bolt Closing	Could Not Duplicate Concern	496994	F	Repaired rifle @ n/c under XMP recall
11678	660	not avail.	222 REM	1-Jan-68	Y	S	26-Feb-15	26-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	493273	F	Per Ilion- Replace TA under BLP
11680	700	29694	300 WIN M	27-Apr-93	N	S	26-Feb-15	26-Feb-15	Fired on Safe Release	Could Not Duplicate Concern	494348	F	Per Ilion: Repair at no charge
11681	700	not avail.	264 WIN MA	4-Oct-77	N	S	26-Feb-15	26-Feb-15	Fired on Bolt Closing	Altered Adjustments or Components	494338	F	Per Ilion- Replace TA under BLP
11682	700	26010	300 RUM	2-Dec-02	N	S	26-Feb-15	26-Feb-15	Fired on Bolt Closing	Altered Adjustments or Components	494162	F	Per Ilion: Repair at no charge
11683	700	25791	270 WIN	21-Jan-89	N	S	26-Feb-15	26-Feb-15	Fired on Bolt Closing	Improper Maintenance	494186	F	Per Ilion: Repair as needed.
11685	700	not avail.	270 WIN	13-Oct-76	N	S	26-Feb-15	26-Feb-15	Fired on Bolt Closing	Could Not Duplicate Concern	494318	F	Per Ilion- Replace TA under BLP
11686	700	26139	300 RUM	28-Apr-01	N	S	26-Feb-15	26-Feb-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	494193	F	Per Ilion: Repair at no charge
11687	700	not avail.	243 WIN	2-Aug-83	N	S	26-Feb-15	26-Feb-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	494202	F	Per Ilion: Repair at no charge
11688	700	25793	3006 SPRG	3-Nov-91	N	S	26-Feb-15	26-Feb-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	494199	F	Per Ilion: Repair at no charge

RAC001222

Confidential

11689	700	not avail.	7MM REM MA	31-Mar-78	N	S	26-Feb-15	26-Feb-15	Fired on Bolt Closing	Improper Maintenance	494196	F	Per Ilion- Replace TA under BLP
11691	700	not avail.	7MM REM MA	17-Jan-73	N	S	2-Mar-15	2-Mar-15	Unknown Claim	Altered Adjustments or Components	494563	F	Per Ilion- Replace TA under BLP
11692	700	26133	7MM REM MA	14-Mar-01	N	S	2-Mar-15	2-Mar-15	Fired on Safe Release	Altered Adjustments or Components	494561	F	Per Ilion- Repair at no charge
11693	700	not avail.	7MM REM MA	1-May-67	N	S	2-Mar-15	2-Mar-15	Fired With Safe ON	Altered Adjustments or Components	494559	F	Per Ilion- Replace TA under BLP
11694	700	25771	270 WIN	30-Sep-97	N	S	2-Mar-15	2-Mar-15	Fired on Bolt Closing	Could Not Duplicate Concern	494558	F	Per Ilion- Repair at no charge
11695	700	20000	35 WHELEN	28-Jul-88	N	S	2-Mar-15	2-Mar-15	Fired on Bolt Closing	Could Not Duplicate Concern	494555	F	Per Ilion- Repair at no charge
11696	700	not avail.	270 WIN	1-Mar-72	N	S	2-Mar-15	2-Mar-15	Fired on Bolt Closing	Could Not Duplicate Concern	494552	F	Per Ilion- Replace TA under BLP
11697	700	not avail.	3006 SPRG	1-Mar-65	N	S	2-Mar-15	2-Mar-15	Fired on Bolt Closing	Improper Maintenance	494554	F	Per Ilion- Replace TA under BLP
11700	597	26516	17 HMR	21-Jan-03	N	PD/S	2-Mar-15	27-Mar-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	497434	F	Replace with Ramac 70723 in exchange
11701	887	82502	12 GA	21-Jan-14	N	S	3-Mar-15	3-Mar-15	Failed to Extract	Sent in for Evaluation	494665	F	Per Ilion- Repair at no charge
11704	700	not avail.	3006 SPRG	1-Nov-66	N	S	3-Mar-15	3-Mar-15	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	494638	F	Per Ilion- Replace TA under BLP
11705	700	26010	300 RUM	18-Dec-02	N	S	3-Mar-15	3-Mar-15	Went Automatic	Could Not Duplicate Concern	494669	F	Per Ilion- Repair at no charge
11709	597	26536	17 HMR	27-May-03	N	PI/PD/S	3-Mar-15	17-Mar-15	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	495824	F	Converting to 22 WMR as requested by customer
11710	700	not avail.	270 WIN	21-Apr-77	N	S	5-Mar-15	5-Mar-15	Fired on Safe Release	Altered Adjustments or Components	495085	F	Per Ilion- Replace TA under BLP
11711	700	29717	3006 SPRG	6-Nov-03	N	S	5-Mar-15	5-Mar-15	Fired on Bolt Closing	Improper Maintenance	495088	F	Per Ilion- Repair at no charge
11713	597	26516	17 HMR	24-Jul-03	N	PI/PD/S	5-Mar-15	*	My Gun Blew Up	Other - Unexamined		F	
11715	700	not avail.	3006 SPRG	8-Feb-78	N	S	6-Mar-15	6-Mar-15	Fired on Bolt Closing	Could Not Duplicate Concern	495250	F	Per Ilion- Replace TA under BLP
11716	700	not avail.	3006 SPRG	2-Sep-69	N	S	6-Mar-15	6-Mar-15	Fired on Safe Release	Could Not Duplicate Concern	495248	F	Per Ilion- Replace TA under BLP
11717	770	85658	300 WIN MA	10-Feb-09	Y	S	6-Mar-15	6-Mar-15	Fired on Safe Release	Other - Unspecified or Undetermined - Firearms	495261	F	Per Ilion- Repair at no charge
11721	700	not avail.	308 WIN	13-Feb-76	N	S	10-Mar-15	10-Mar-15	Fired on Safe Release	Could Not Duplicate Concern	495293	F	Per Ilion- Replace TA under BLP
11722	700	not avail.	7MM REM MA	1-Dec-80	N	S	11-Mar-15	11-Mar-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	495468	F	Per Ilion- Replace TA under BLP
11723	700	N/A	243 WIN	21-Apr-72	N	S	11-Mar-15	11-Mar-15	Fired on Bolt Closing	Altered Adjustments or Components	495469	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11724	700	25851	270 WIN	22-Apr-03	N	S	11-Mar-15	11-Mar-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	495386	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11726	700	25771	270 WIN	25-Jan-84	N	S	11-Mar-15	11-Mar-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	495458	F	Per Ilion, replace trigger assembly, check over and test fire at no charge

RAC001223

Confidential

11727	700	84207	308 WIN	13-May-08	N	S	11-Mar-15	11-Mar-15	Fired on Safe Release	Could Not Duplicate Concern	495464	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11728	597	26516	17 HMR	3-Oct-06	N	PD/S	11-Mar-15	11-Mar-15	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	495459	F	Sending \$200 coupon in exchange for gun.
11733	700	27523	308 WIN	5-Apr-02	N	S	12-Mar-15	12-Mar-15	Fired on Safe Release	Could Not Duplicate Concern	495650	F	Per Ilion: Repair at no charge
11734	700	25777	7MM REM MA	23-Jul-85	N	S	12-Mar-15	12-Mar-15	Fired on Safe Release	Sent in for Evaluation	495652	F	Per Ilion: Repair at no charge
11735	700	not avail.	3006 SPRG	10-Mar-77	N	S	12-Mar-15	12-Mar-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	495661	F	Per Ilion- Replace TA under BLP
11736	700	25771	270 WIN	1-Jul-85	N	S	12-Mar-15	12-Mar-15	Fired on Bolt Closing	Improper Maintenance	495649	F	Per Ilion: Repair at no charge
11739	700	26410	300 RUM	18-Feb-03	N	S	12-Mar-15	12-Mar-15	Fired on Safe Release	Improper Maintenance	495648	F	Per Ilion: Repair at no charge
11741	700	25811	270 WIN	18-May-89	N	S	16-Mar-15	16-Mar-15	Fired With Safe ON	Improper Maintenance	495659	F	Per Ilion: Repair at no charge
11742	700	N/A	3006 SPRG	9-Apr-73	N	S	16-Mar-15	16-Mar-15	Fired on Bolt Closing	Altered Adjustments or Components	495923	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11743	700	N/A	7MM REM MA	20-Nov-81	N	S	16-Mar-15	16-Mar-15	Fired on Safe Release	Could Not Duplicate Concern	495813	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11744	700	26039	7MM REM MA	25-Feb-97	N	S	16-Mar-15	16-Mar-15	Fired on Safe Release	Could Not Duplicate Concern	495814	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11746	870	81062	12 GA	17-Feb-15	N	PD/S	16-Mar-15	25-Mar-15	Action Opened on Firing	Sent in for Evaluation	497215	F	Per Ilion, check over completely, repair as needed, and test at no charge.
11749	700	N/A	270 WIN	12-May-75	N	S	17-Mar-15	17-Mar-15	Safety not working properly	Could Not Duplicate Concern	496309	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11750	700	N/A	3006 SPRG	16-Jun-71	N	S	17-Mar-15	17-Mar-15	Fired on Safe Release	Altered Adjustments or Components	496192	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11751	700	85446	243 WIN	18-Sep-12	N	S	17-Mar-15	17-Mar-15	Fired on Bolt Closing	Could Not Duplicate Concern	496261	F	Per Ilion- Repair at no charge under recall.
11752	700	25793	3006 SPRG	22-Jun-12	N	S	17-Mar-15	17-Mar-15	Fail to Fire	Could Not Duplicate Concern	496260	F	Per Ilion: Repair at no charge
11753	700	27476	270 WIN	27-Feb-95	N	S	17-Mar-15	17-Mar-15	Fired on Safe Release	Could Not Duplicate Concern	496257	F	Per Ilion: Repair at no charge
11755	597	26516	17 HMR	15-Nov-06	N	S	17-Mar-15	17-Mar-15	Other - Firearms	Other - Unspecified or Undetermined - Firearms	496255	F	Per Ilion- Rebate Coupon mailed to consumer.
11754	597	26536	17 HMR	19-Jun-03	N	S	17-Mar-15	28-Apr-15	Other - Firearms	Other - Unspecified or Undetermined - Firearms	496269	F	Replace w/70723 in exchange
11756	Pardner Pump	72312	12 GA	4-Feb-14	N	PI/PD/S	17-Mar-15	6-Apr-15	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	497678	F	Check over completely, repair as needed, and test at no charge
11761	870	25568	12 GA	26-Aug-08	N	S	19-Mar-15	19-Mar-15	Unknown Claim	Other - Unspecified or Undetermined - Firearms	496332	F	Per Customer- Return as received
11762	700	not avail.	7MM REM MA	17-Mar-79	N	S	19-Mar-15	19-Mar-15	Other - Firearms	Improper Maintenance	496632	F	Per Ilion- Replace TA under BLP
11763	700	84344	220 SWIFT	15-Jun-09	N	S	19-Mar-15	19-Mar-15	Fired on Safe Release	Could Not Duplicate Concern	496633	F	Per Ilion- Repair at no charge under recall.

RAC001224

Confidential

11764	788	not avail.	223 REM	3-Jul-75	Y	S	19-Mar-15	19-Mar-15	Fired on Safe Release	Improper Maintenance	496636	F	Per Lion: Repair at no charge
11765	700	26311	300 WSM	5-Oct-05	N	S	19-Mar-15	19-Mar-15	Fired on Bolt Closing	Could Not Duplicate Concern	496634	F	Per Lion: Repair at no charge
11766	1911	96335	45 ACP	4-Sep-13	N	S	19-Mar-15	19-Mar-15	Safety not working properly	Aft Mkt Safety	496493	F	Per Lion-Quote to repair at discount.
11773	700	not avail.	270 WIN	27-Sep-76	N	PI/S	19-Mar-15	17-Aug-15	Fired on Safe Release	Sent in for Evaluation	499358	F	Davis Release agreement - Item# 83205, Doran Release Agreement - Item# 60037
11769	700	27269	3006 SPRG	6-May-05	N	S	20-Mar-15	20-Mar-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	496635	F	Per Lion, replace trigger assembly, check over and test fire at no charge
11770	770	85633	3006 SPRG	28-Mar-13	Y	S	20-Mar-15	20-Mar-15	Fired on Bolt Closing	Could Not Duplicate Concern	496954	F	Per Lion: Repair at no charge
11771	721	N/A	3006 SPRG	1-Aug-50	Y	S	20-Mar-15	20-Mar-15	Unexplained Discharge Safe OFF	Sent in for Evaluation	496915	F	Per Lion, check over completely, replace trigger assembly under BLM at no charge
11774	700	N/A	270 WIN	15-Jul-77	N	S	20-Mar-15	20-Mar-15	Unexplained Discharge Safe OFF	Altered Adjustments or Components	496957	F	Per Lion, replace trigger assembly, check over and test fire at no charge
11778	700	not avail.	17 REM	3-May-74	N	S	23-Mar-15	23-Mar-15	Fired on Bolt Closing	Could Not Duplicate Concern	496986	F	Per Lion- Replace TA under BLP
11780	700	N/A	3006 SPRG	3-Jun-75	N	S	23-Mar-15	23-Mar-15	Fired on Safe Release	Could Not Duplicate Concern	496990	F	Per Lion, check over completely, replace trigger assembly under BLM at no charge
11781	700	25795	308 WIN	1-Sep-94	N	S	23-Mar-15	23-Mar-15	Fired on Safe Release	Could Not Duplicate Concern	496987	F	Per Lion, replace trigger assembly, check over and test fire at no charge
11782	700	N/A	3006 SPRG	24-Feb-76	N	S	23-Mar-15	23-Mar-15	Fired on Safe Release	Could Not Duplicate Concern	496989	F	Per Lion, replace trigger assembly, check over and test fire at no charge
11784	770	85635	7MM REM MA	10-Jun-11	Y	S	23-Mar-15	23-Mar-15	Delayed Firing - Firearms	Sent in for Evaluation	497052	F	Per Lion: Repair at no charge
11785	700	27391	7MM-08 REM	25-Sep-09	N	S	23-Mar-15	23-Mar-15	Unexplained Discharge Safe ON	Could Not Duplicate Concern	496991	F	Per Lion, replace trigger assembly, check over and test fire at no charge
11786	597	not avail.	17 HMR	21-Jan-03	N	PI/PD/S	23-Mar-15	20-May-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	499699	F	Convert to 22 WMR - customer request
11788	770	85632	270 WIN	5-Nov-09	Y	S	25-Mar-15	25-Mar-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	497189	F	Per Lion: Repair at no charge
11789	700	not avail.	222 REM	1-Jan-67	N	S	25-Mar-15	25-Mar-15	Fired on Bolt Closing	Improper Maintenance	497214	F	Per Lion- Replace TA under BLP
11790	597	26513	22 LR	28-Oct-13	N	S	25-Mar-15	25-Mar-15	Unknown Claim	Other - Unspecified or Undetermined - Firearms	497122	F	Per Lion: Repair at no charge
11792	XM15-E25	not avail.	223/5.56	30-Jan-06	N	S	25-Mar-15	25-Mar-15	Went Automatic	Could Not Duplicate Concern	497218	F	Per Lion: Repair at no charge
11795	XM15-E25	not avail.	223/5.56	30-Jan-06	N	S	25-Mar-15	25-Mar-15	Went Automatic	Could Not Duplicate Concern	497219	F	Per Lion: Repair at no charge
11804	700	25791	270 WIN	2-Feb-84	N	S	27-Mar-15	27-Mar-15	Fired on Bolt Closing	Could Not Duplicate Concern	497283	F	Per Lion: Repair at no charge
11805	700	25773	3006 SPRG	21-Jan-89	N	S	27-Mar-15	27-Mar-15	Fired on Bolt Closing	Could Not Duplicate Concern	497290	F	Per Lion: Repair at no charge

RAC001225

Confidential

11806	700	not avail.	270 WIN	12-Jan-72	N	S	27-Mar-15	27-Mar-15	Unknown Claim	Sent in for Evaluation	497431	F	Per Ilion- Replace TA under BLP
11807	700	25801	17 REM	29-Feb-96	N	S	27-Mar-15	27-Mar-15	Fired on Safe Release	Altered Adjustments or Components	497367	F	Per Ilion: Repair at no charge
11808	700	27478	3006 SPRG	5-Sep-95	N	S	27-Mar-15	27-Mar-15	Fired on Safe Release	Could Not Duplicate Concern	497297	F	Per Ilion: Repair at no charge
11813	597	26560	22 WMR	12-Aug-14	N	S	31-Mar-15	31-Mar-15	Fail to Fire	Sent in for Evaluation	497489	F	Per Ilion: Repair at no charge
11818	700	not avail.	3006 SPRG	10-May-72	N	S	31-Mar-15	31-Mar-15	Fired With Safe ON	Altered Adjustments or Components	497548	F	Per Ilion- Replace TA under BLP
11821	700	not avail.	222 REM	1-May-64	N	S	31-Mar-15	31-Mar-15	Fired on Bolt Closing	Could Not Duplicate Concern	497568	F	Per Ilion- Replace TA under BLP
11822	700	25811	270 WIN	17-Oct-86	N	S	31-Mar-15	31-Mar-15	Delayed Firing - Firearms	Sent in for Evaluation	497494	F	Per Ilion: Repair at no charge
11823	700	not avail.	222 REM	11-Jan-71	N	S	31-Mar-15	31-Mar-15	Fired on Safe Release	Altered Adjustments or Components	497549	F	Per Ilion- Replace TA under BLP
11824	700	27311	7MM REM MA	4-Jun-12	N	PI/S	31-Mar-15	23-Apr-15	Fired on Safe Release	Could Not Duplicate Concern	498612	F	Check over completely, repair as needed, and test at no charge
11825	788	not avail.	22-250 REM	18-Apr-80	Y	S	31-Mar-15	13-May-15	Fired on Safe Release	Could Not Duplicate Concern	497567	F	Clean TA @ n/c - goodwill gesture
11816	788	not avail.	243 WIN	6-Feb-78	Y	S	31-Mar-15	13-May-15	Fired on Safe Release	Improper Maintenance	497518	F	Clean TA @ n/c - goodwill gesture
11837	700	84370	223 REM	28-Mar-13	N	PD/S	31-Mar-15	16-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	499015	F	Per Release - Repair rifle @ n/c under XMP recall & reimbursement check for \$443
11836	700	84528	300 RUM	17-Aug-10	N	S	2-Apr-15	2-Apr-15	Fired on Bolt Closing	Could Not Duplicate Concern	497681	F	Ilion repaired at n/c
11838	78	26162	270 WIN	19-Nov-85	Y	S	2-Apr-15	2-Apr-15	Fired on Safe Release	Altered Adjustments or Components	497707	F	Per Ilion, replace trigger assembly, check over and test fire at no charge
11839	700	26263	7MM REM MA	28-Feb-97	N	S	2-Apr-15	2-Apr-15	Fired on Safe Release	Could Not Duplicate Concern	497711	F	Check over completely, repair as needed, and test at no charge
11844	1187	29819	12 GA	27-May-95	N	S	7-Apr-15	28-Apr-15	Fired Out of Battery	Fired from Contact with Foreign Object	497831	F	Per Ilion- Repair at 1/2 cost
11846	700	not avail.	6MM REM	30-Aug-76	N	S	7-Apr-15	7-Apr-15	Fired on Safe Release	Could Not Duplicate Concern	497867	F	Per Ilion- Replace TA under BLP
11852	700	27363	3006 SPRG	17-Nov-08	N	S	8-Apr-15	8-May-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	499364	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
11854	CARBON 15	91037	223/5.56	6-Mar-14	N	S	9-Apr-15	9-Apr-15	Jar-Off Safe ON	Sent in for Evaluation	498080	F	Per Ilion: Repair at no charge
11857	700	25845	260 REM	10-May-01	N	S	9-Apr-15	9-Apr-15	Other - Firearms	Sent in for Evaluation	497975	F	Per Ilion: Repair at no charge
11858	700	25815	7MM REM MA	12-Jul-83	N	S	9-Apr-15	9-Apr-15	Fired on Safe Release	Could Not Duplicate Concern	498018	F	Per Ilion: Repair at no charge
11860	710	27408	270 WIN	17-Feb-04	Y	S	9-Apr-15	9-Apr-15	Fired on Safe Release	Altered Adjustments or Components	498077	F	Per Ilion: Repair at no charge
11862	700	not avail.	3006 SPRG	24-Sep-76	N	S	14-Apr-15	14-Apr-15	Fired on Bolt Closing	Sent in for Evaluation	498152	F	Per Ilion- Replace TA under BLP
11863	700	84164	300 WIN MA	18-Dec-14	N	S	14-Apr-15	14-Apr-15	Fired on Bolt Closing	Could Not Duplicate Concern	498169	F	Per Ilion- Repair at no charge under recall.
11864	700	not avail.	3006 SPRG	15-Sep-71	N	S	14-Apr-15	14-Apr-15	Fired on Bolt Closing	Could Not Duplicate Concern	498274	F	Per Ilion- Replace TA under BLP
11865	700	not avail.	308 WIN	9-May-78	N	S	14-Apr-15	14-Apr-15	Fired on Safe Release	Could Not Duplicate Concern	498219	F	Per Ilion- Replace TA under BLP
11866	700	not avail.	270 WIN	31-Aug-70	N	S	14-Apr-15	14-Apr-15	Fired on Safe Release	Could Not Duplicate Concern	498221	F	Per Ilion- Replace TA under BLP

RAC001226

Confidential

11868	770	85634	308 WIN	26-Apr-07	Y	S	14-Apr-15	14-Apr-15	Fired on Bolt Closing	Sent in for Evaluation	498250	F	Per Ilion: Repair at no charge
11867	597	26516	17 HMR	31-Jul-03	N	S	14-Apr-15	22-May-15	Other - Firearms	Other - Unspecified or Undetermined - Firearms	498278	F	Rebate coupon mailed to consumer
11870	597	N/A	17 HMR		N	PI/PD/S	14-Apr-15	*	My Gun Blew Up	Other - Unexamined		F	
11876	710	27408	270 WIN	12-Mar-05	Y	S	16-Apr-15	27-Apr-15	Fired on Bolt Closing	Sent in for Evaluation	498332	F	Call Center replaced at no charge w/Model 783
11877	700	84645	243 WIN	2-Aug-12	N	S	16-Apr-15	16-Apr-15	Fired on Bolt Closing	Could Not Duplicate Concern	498447	F	Per Ilion- Repair at no charge under recall.
11878	700	not avail.	270 WIN	1-Jan-63	N	S	16-Apr-15	16-Apr-15	Fired on Safe Release	Could Not Duplicate Concern	498305	F	Per Ilion- Replace TA under BLP
11879	7400	24716	3006 SPRG 7MM REM MA	23-Jan-85	Y	PD/S	16-Apr-15	16-Apr-15	Failed to Extract	Rotated Barrel Extension	498324	F	Per Ilion: Repair at no charge
11880	700	not avail.	7MM REM MA	1-Dec-79	N	S	16-Apr-15	16-Apr-15	Fired on Safe Release	Could Not Duplicate Concern	498283	F	Per Ilion- Replace TA under BLP
11881	700	not avail.	6MM REM	19-Sep-78	N	S	16-Apr-15	16-Apr-15	Fired on Safe Release	Improper Maintenance	498284	F	Per Ilion- Replace TA under BLP
11882	700	not avail.	243 WIN	25-Sep-79	N	S	16-Apr-15	16-Apr-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	498459	F	Per Ilion- Replace TA under BLP
11885	1187	83617	12 GA	18-Nov-11	N	S	20-Apr-15	20-Apr-15	Fired on Bolt Closing	Could Not Duplicate Concern	498570	F	Per Ilion: Repair at no charge
11888	700	20000	22-250 REM	20-May-71	N	S	20-Apr-15	20-Apr-15	Other - Firearms	Rotated Barrel Extension	498474	F	Per Ilion: Repair at no charge
11889	887	82540	12 GA	17-Jul-10	N	S	20-Apr-15	20-Apr-15	Fired on Bolt Closing	Could Not Duplicate Concern	498549	F	Per Ilion: Repair at no charge
11890	597	26516	17 HMR	10-Jul-05	N	S	20-Apr-15	20-Apr-15	Other - Firearms	Other - Unspecified or Undetermined - Firearms	498520	F	Per Ilion: Repair at no charge
11891	700	not avail.	270 WIN	22-Sep-71	N	S	20-Apr-15	20-Apr-15	Fired on Safe Release	Could Not Duplicate Concern	498485	F	Per Ilion- Replace TA under BLP
11892	887	82502	12 GA	19-Jul-13	N	S	20-Apr-15	20-Apr-15	Fired on Safe Release	Could Not Duplicate Concern	498482	F	Per Ilion: Repair at no charge
11894	700	not avail.	25-06 REM	1-Apr-76	N	S	22-Apr-15	22-Apr-15	Fired on Bolt Closing	Altered Adjustments or Components	498613	F	Per Ilion- Replace TA under BLP
11895	700	not avail.	3006 SPRG	21-Feb-77	N	S	22-Apr-15	22-Apr-15	Fired on Safe Release	Altered Adjustments or Components	498660	F	Per Ilion- Replace TA under BLP
11896	700	26063	3006 SPRG	11-May-93	N	S	22-Apr-15	22-Apr-15	Fired on Safe Release	Could Not Duplicate Concern	498574	F	Per Ilion: Repair at no charge
11897	700	not avail.	25-06 REM	1-Oct-74	N	S	22-Apr-15	22-Apr-15	Fired on Bolt Closing	Could Not Duplicate Concern	498658	F	Per Ilion- Replace TA under BLP
11903	700	not avail.	3006 SPRG	29-Jul-76	N	S	24-Apr-15	24-Apr-15	Fired on Safe Release	Altered Adjustments or Components	498796	F	Per Ilion- Replace TA under BLP
11904	700	not avail.	270 WIN	13-Sep-77	N	PD/S	24-Apr-15	24-Apr-15	Fired on Safe Release	Could Not Duplicate Concern	498791	F	Per Ilion- Replace TA under BLP
11906	700	84218	308 WIN	1-Oct-14	N	S	24-Apr-15	24-Apr-15	Fired on Bolt Closing	Rotated Barrel Extension	498767	F	Per Ilion- Repair at no charge under recall.
11907	742	not avail.	3006 SPRG	1-Aug-76	Y	S	24-Apr-15	24-Apr-15	Other - Firearms	Sent in for Evaluation	498792	F	Per Ilion- Return As Received
11908	700	not avail.	222 REM	18-Dec-75	N	S	24-Apr-15	24-Apr-15	Fired on Bolt Closing	Could Not Duplicate Concern	498766	F	Per Ilion- Replace TA under BLP
11911	700	not avail.	25-06 REM	20-Mar-72	N	S	24-Apr-15	24-Apr-15	Fired on Bolt Closing	Could Not Duplicate Concern	498736	F	Per Ilion- Replace TA under BLP
11913	700	27169	7MM REM MA	17-Aug-06	N	PD/S	24-Apr-15	15-Jun-15	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	500402	F	Check over completely, repair as needed, and test at no charge
11920	SEVEN	24782	243 WIN	3-Dec-96	N	S	28-Apr-15	28-Apr-15	Fired on Bolt Closing	Could Not Duplicate Concern	498308	F	Per Ilion: Repair at no charge

RAC001227

Confidential

11921	597	26536	17 HMR	24-Mar-03	N	S	28-Apr-15	28-Apr-15	Other - Firearms	Other - Unspecified or Undetermined - Firearms	498907	F	Per Iion: Repair at no charge
11922	700	85435	308 WIN	5-Mar-14	N	S	28-Apr-15	28-Apr-15	Fired on Safe Release	Altered Adjustments or Components	498909	F	Per Iion: Replace with Ramac #81048
11925	887	82500	12 GA	29-Jun-12	N	PI/S	28-Apr-15	29-May-15	Fired on Bolt Closing	Could Not Duplicate Concern	499815	F	Check over, repair if needed & test @ n/c
11923	Handi Rifle	72652	223 REM	6-Nov-13	N	S	28-Apr-15	14-May-15	Ammunition Exploded	Sent in for Evaluation	499369	F	Refunded purchase price in Consumer Service.
11937	700	25630	270 WIN	17-Jan-86	N	S	1-May-15	27-May-15	Fired on Safe Release	Sent in for Evaluation	499989	F	Per Iion, replace trigger assembly, check over, and test fire at no charge
11935	700	not avail.	3006 sprg	16-Feb-70	N	S	1-May-15	1-May-15	Fired on Bolt Closing	Could Not Duplicate Concern	499014	F	Per Iion- Replace TA under BLP
11936	700	27123	3006 SPRG	18-Mar-06	N	S	1-May-15	22-May-15	Fired on Safe Release	Could Not Duplicate Concern	499013	F	Per Iion - Repair at n/c - goodwill
11938	700	25773	3006 SPRG	7-Nov-89	N	S	1-May-15	27-May-15	Fired on Safe Release	Could Not Duplicate Concern	499996	F	Per Iion, quote to check over completely, repair as needed, and test, replace trigger at no charge
11934	710	27408	270 WIN	23-Aug-02	Y	S	1-May-15	1-May-15	Fired on Bolt Closing	Altered Adjustments or Components	499034	F	Per Iion- Replace with Ramac #85844
11932	710	27410	3006 sprg	20-May-05	Y	S	1-May-15	1-May-15	Fired on Bolt Closing	Could Not Duplicate Concern	499029	F	Per Iion- Replace with Ramac #85846
11942	700	84217	243 WIN	22-Mar-13	N	S	5-May-15	5-May-15	Fired on Bolt Closing	Could Not Duplicate Concern	499202	F	Per Iion: Repair at no charge
11943	700	27363	3006 SPRG	17-Apr-09	N	S	5-May-15	5-May-15	Fired on Bolt Closing	Sent in for Evaluation	499203	F	Per Iion- Repair at no charge under recall.
11940	887	82502	12 GA	6-Apr-10	N	S	5-May-15	5-May-15	Fired Out of Battery	Sent in for Evaluation	499204	F	Per Iion, check over completely, repair as needed, and test at no charge.
11941	SEVEN	24782	243 WIN	25-May-90	N	S	5-May-15	5-May-15	Fired on Safe Release	Could Not Duplicate Concern	499199	F	Per Iion: Repair at no charge
11944	597	26514	17 HMR	17-Jun-04	N	PI/PD/S	5-May-15	10-Aug-15	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	500821	F	Replace with Ramac 27491 in exchange
11948	700	84408	300 RUM	6-Feb-09	N	PD/S	6-May-15	7-May-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	n/a	F	Check for \$954.56 CA \$\$ for truck damage
11946	700	N/A	270 WIN	14-Jan-81	N	PD/S	6-May-15	2-Jun-15	Fired on Safe Release	Altered Adjustments or Components	500106	F	Check over completely, repair as needed, and test at no charge
11950	700	not avail.	243 win	1-Mar-67	N	S	8-May-15	8-May-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	499359	F	Per Iion- Replace TA under BLP
11954	700	27094	270 WIN	16-Jan-06	N	S	8-May-15	8-May-15	Fired With Safe ON	Could Not Duplicate Concern	499366	F	Per Iion: Repair at no charge
11957	700	25971	300 RUM	15-Mar-01	N	S	8-May-15	8-May-15	Fired on Safe Release	Could Not Duplicate Concern	499357	F	Per Iion: Repair at no charge
11955	700	25807	300 WIN MA	16-Apr-93	N	S	8-May-15	8-May-15	Fired on Safe Release	Improper Maintenance	499319	F	Per Iion: Repair at no charge
11952	700	not avail.	308 WIN	17-Sep-71	N	S	8-May-15	8-May-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	499367	F	Per Iion- Repair at no charge under recall.
11951	700	not avail.	7MM REM MA	8-Mar-72	N	S	8-May-15	8-May-15	Fired on Safe Release	Could Not Duplicate Concern	499365	F	Per Iion- Replace TA under BLP

RAC001228

Confidential

11964	770	85634	308 WIN	29-Apr-14	Y	S	12-May-15	12-May-15	Fail to Fire	Could Not Duplicate Concern	499379	F	Per Ilion: Repair at no charge
11962	887	82502	12 GA	28-Mar-14	N	S	12-May-15	12-May-15	Unexplained Discharge - No Mention of Safety Position	Rotated Barrel Extension	499402	F	Per Ilion: Repair at no charge
11959	597	26514	17 HMR	23-Feb-05	N	PI/PD/S	12-May-15	9-Jun-15	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	500403	F	Converting to 22 WMR as requested by customer
11968	597	26536	17 HMR	26-Mar-03	N	PI/PD/S	12-May-15	9-Jun-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	500404	F	Replace with Ramac 70723 in exchange
11973	700	84207	308 WIN	25-Oct-13	N	PD/S	12-May-15	4-May-16	Fired on Safe Release	Not Examined by Product Service	n/a	F	Rifle not returned to Ilion for exam
11971	700	N/A	3006 SPRG	29-Nov-72	N	PD/S	13-May-15	17-Jun-15	Fired on Safe Release	Could Not Duplicate Concern	500657	F	Check over completely, repair as needed, and test at no charge
11974	700	not avail.	3006 SPRG	1-Feb-68	N	S	15-May-15	15-May-15	Fired on Bolt Closing	Could Not Duplicate Concern	498910	F	Per Ilion- Replace TA under BLP
11975	721	not avail.	270 WIN	1-Nov-73	Y	S	15-May-15	15-May-15	Fired on Safe Release	Sent in for Evaluation	499587	F	Per Ilion - Replace TA @ n/c
11978	SPR 210	89524	12 GA	19-Dec-05	Y	PI/S	19-May-15	28-Aug-15	Personal Injury while using firearm	Could Not Duplicate Concern	501093	F	Returned as Received as requested by customer
11982	700	27333	300 WSM	14-Feb-06	N	S	20-May-15	20-May-15	Fired on Safe Release	Could Not Duplicate Concern	499702	F	Per Ilion: Repair at no charge
11985	700	not avail.	3006 SPRG	15-Oct-69	N	S	20-May-15	20-May-15	Fired on Safe Release	Could Not Duplicate Concern	499716	F	Per Ilion- Replace TA under BLP
11981	700	26449	6.8MM SPC	21-Sep-05	N	S	20-May-15	20-May-15	Fired on Safe Release	Altered Adjustments or Components	499714	F	Per Ilion: Repair at no charge
11983	700	not avail.	7MM REM MA	1-Sep-64	N	S	20-May-15	20-May-15	Fired With Safe ON	Altered Adjustments or Components	499718	F	Per Ilion- Replace TA under BLP
11980	788	not avail.	6MM REM	18-Sep-78	Y	S	20-May-15	20-May-15	Fired on Safe Release	Improper Maintenance	499693	F	Per Ilion: Repair at no charge
11979	887	82502	12 GA	13-Aug-10	N	S	20-May-15	20-May-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	499694	F	Per Ilion: Repair at no charge
11986	700	N/A	3006 SPRG	1-Mar-61	N	S	20-May-15	4-Jun-15	Light Trigger Pull	Could Not Duplicate Concern	500188	F	Per Ilion, check over completely, repair as needed, and test at no charge.
11995	700	not avail.	25-06 REM	5-May-75	N	S	22-May-15	22-May-15	Fired on Bolt Closing	Altered Adjustments or Components	499853	F	Per Ilion- Replace TA under BLP
11993	700	not avail.	270 WIN	27-Jul-79	N	S	22-May-15	22-May-15	Fired on Bolt Closing	Broken or Missing Parts	499816	F	Per Ilion- Replace TA under BLP
11996	700	not avail.	3006 SPRG	24-Feb-76	N	S	22-May-15	22-May-15	Fired on Safe Release	Altered Adjustments or Components	499820	F	Per Ilion- Replace TA under BLP
11994	700	25833	308 WIN	9-Jan-92	N	S	22-May-15	22-May-15	Fired on Bolt Closing	Altered Adjustments or Components	499818	F	Per Ilion: Repair at no charge
11997	700	27480	7MM REM MA	31-Aug-99	N	S	22-May-15	22-May-15	Fired on Bolt Closing	Could Not Duplicate Concern	499819	F	Per Ilion: Repair at no charge
11998	1911R1	96323	45 ACP	18-Feb-14	N	S	22-May-15	22-May-15	Went Automatic	Could Not Duplicate Concern	499851	F	Per Ilion: Repair at no charge
11999	597	26536	17 HMR	25-Oct-02	N	PI/PD/S	22-May-15	*	My Gun Blew Up	Other - Unexamined		F	
12006	597	26513	22 LR	13-Mar-14	N	S	27-May-15	27-May-15	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	499906	F	Per Ilion: Repair at no charge
12009	700	25793	3006 SPRG	5-Mar-85	N	S	27-May-15	27-May-15	Fired on Bolt Closing	Could Not Duplicate Concern	499893	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge

RAC001229

Confidential

12007	870	26462	20 GA	5-Jun-14	N	S	27-May-15	27-May-15	Jar-Off - No Mention of Safety Position	Could Not Duplicate Concern	499939	F	Per Iion: Repair at no charge
12010	SEVEN	85952	223 REM	8-Jan-08	N	S	27-May-15	27-May-15	Other - Firearms	Sent in for Evaluation	499894	F	Per Iion: Repair at no charge
12008	597	26537	22 LR	15-Aug-09	N	PI/S	27-May-15	24-Jul-15	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	501168	F	Replace w/26537 in exchange
12014	597	26537	22 LR	4-Sep-14	N	PD/S	27-May-15	21-Oct-15	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	504642	F	Check over completely, repair as needed, and test at no charge
12017	597	N/A	17 HMIR		N	PD/S	29-May-15	*	My Gun Blew Up	Other - Unexamined		F	
12022	700	25793	3006 SPRG	5-Mar-85	N	S	1-Jun-15	1-Jun-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	500103	F	Per Iion: Repair at no charge
12021	700	25775	308 WIN	6-Sep-91	N	S	1-Jun-15	1-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500102	F	Per Iion- Repair at no charge under XMP recall.
12018	700	27325	7MM-08 REM	30-May-03	N	S	1-Jun-15	1-Jun-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	500108	F	Per Iion- Repair at no charge under XMP recall.
12020	710	27410	3006 SPRG	19-Jun-06	Y	S	1-Jun-15	17-Jun-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	500101	F	Replace w/85631 in exchange thru SNC
12031	700	84214	204 RUGER 22-250	19-Dec-11	N	S	4-Jun-15	4-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500233	F	Per Iion- Repair at no charge under XMP recall.
12026	700	not avail.	REM	17-Feb-78	N	S	4-Jun-15	4-Jun-15	Fired on Bolt Closing	Could Not Duplicate Concern	500247	F	Per Iion- Replace TA under BUP
12024	700	26915	3006 SPRG	15-Dec-93	N	S	4-Jun-15	4-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500160	F	Per Iion- Repair at no charge under XMP recall.
12027	700	not avail.	3006 SPRG	17-Sep-76	N	S	4-Jun-15	4-Jun-15	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	500158	F	Per Iion- Replace TA under BUP
12028	700	not avail.	3006 SPRG	13-Jul-76	N	S	4-Jun-15	4-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500157	F	Per Iion- Repair at no charge under XMP recall.
12032	700	not avail.	3006 SPRG	7-May-74	N	S	4-Jun-15	4-Jun-15	Fired on Safe Release	Could Not Duplicate Concern	500227	F	Per Iion- Replace TA under BUP
12030	700	not avail.	7MM REM MA	3-Oct-87	N	S	4-Jun-15	4-Jun-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	500165	F	Per Iion: Repair at no charge
12023	887	82502	12 GA	26-Aug-09	N	S	4-Jun-15	4-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500159	F	Per Iion: Repair at no charge
12029	887	82502	12 GA	2-Aug-10	N	S	4-Jun-15	4-Jun-15	Fired on Bolt Opening	Sent in for Evaluation	500144	F	Per Iion: Repair at no charge

RAC001230

Confidential

12041	700	not avail.	22-250 REM	14-Jan-79	N	S	8-Jun-15	8-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500347	F	Per Ilion- Replace TA under BLP
12042	700	not avail.	3006 SPRG	2-Mar-80	N	S	8-Jun-15	8-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500346	F	Per Ilion: Repair at no charge
12043	700	not avail.	3006 SPRG		N	S	8-Jun-15	8-Jun-15	Fired on Safe Release	Altered Adjustments or Components	500342	F	Per Ilion- Replace TA under BLP
12045	700	25793	3006 SPRG	7-Dec-83	N	S	8-Jun-15	8-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500349	F	Per Ilion- Repair at no charge under XMP recall.
12047	597	26516	17 HMR	12-Feb-03	N	PD/S	8-Jun-15	21-Aug-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	500946	F	Replace with Ramac 70712 in exchange
12051	710	27410	3006 sprg	17-Mar-02	Y	S	9-Jun-15	9-Jun-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	500415	F	Per Ilion- Replace with Ramac #85849
12049	887	82502	12 GA	11-Jul-11	N	S	9-Jun-15	9-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500389	F	Per Ilion: Repair at no charge
12050	VERSA MAX	81042	12 GA	10-Jan-12	N	S	9-Jun-15	9-Jun-15	Jamming/Feeding issues	Choke Tube Concentricity	500401	F	Per Ilion: Repair at no charge
12065	597	26537	22 LR	25-Mar-13	N	PD/S	10-Jun-15	10-Jun-15	Fired on Bolt Closing	Other - Unspecified or Undetermined - Firearms	500444	F	Per Ilion: Repair at no charge
12059	700	not avail.	223 REM	1-Jul-63	N	S	10-Jun-15	10-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500348	F	Per Ilion, replace trigger assembly at no charge, replace bolt at 25% discount
12057	700	85372	243 WIN	9-Apr-08	N	S	10-Jun-15	10-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500441	F	Per Ilion: Repair at no charge
12058	700	not avail.	270 WIN	1-Dec-87	N	S	10-Jun-15	10-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500440	F	Per Ilion- Repair at no charge under XMP update.
12060	700	not avail.	3006 SPRG	21-Aug-79	N	S	10-Jun-15	10-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500451	F	Per Ilion- Repair at no charge under XMP update.
12062	700	not avail.	3006 SPRG	4-Mar-80	N	S	10-Jun-15	10-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500453	F	Per Ilion- Repair at no charge under XMP update.
12063	700	25773	3006 SPRG	16-Apr-93	N	S	10-Jun-15	10-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500452	F	Per Ilion- Replace TA under BLP
12061	700	not avail.	7MM REM MA	1-Jul-62	N	S	10-Jun-15	10-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500442	F	Per Ilion- Replace TA under BLP

RAC001231

Confidential

12056	SEVEN	24793	243 WIN	16-Mar-01	N	S	10-Jun-15	10-Jun-15	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance Could Not Duplicate Concern	500482	F	Per Ilion: Repair at no charge
12066	700	not avail.	3006 SPRG	1-Oct-74	N	S	12-Jun-15	12-Jun-15	Fired on Safe Release		500587	F	Per Ilion- Replace TA under BLP
12067	700	not avail.	3006 SPRG	15-May-69	N	S	12-Jun-15	12-Jun-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	500536	F	Per Ilion- Repair at no charge under XMP update.
12069	700	25793	3006 SPRG	16-Aug-11	N	S	12-Jun-15	12-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500538	F	Per Ilion- Repair at no charge under XMP update.
12070	700	not avail.	6MM REM	26-Feb-71	N	S	12-Jun-15	12-Jun-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	500535	F	Per Ilion- Repair at no charge under XMP update.
12068	700	not avail.	7MM REM MA	28-Oct-76	N	S	12-Jun-15	12-Jun-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	500537	F	Per Ilion- Replace TA under BLP
12071	597	26516	17 HMR	15-Mar-05	N	PD/S	12-Jun-15	*	My Gun Blew Up	Other - Unexamined		F	
12078	597	26516	22 WMR	28-Aug-03	N	PD/S	16-Jun-15	16-Jun-15	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Ammunition	500601	F	Per Ilion: Repair at no charge
12074	700	not avail.	270 WIN	23-Apr-76	N	S	16-Jun-15	16-Jun-15	Fired on Bolt Closing	Improper Maintenance	500675	F	Per Ilion- Replace TA under BLP
12077	700	not avail.	270 WIN	29-Mar-72	N	S	16-Jun-15	16-Jun-15	Fired on Bolt Closing	Altered Adjustments or Components	500613	F	Per Ilion- Replace TA under BLP
12079	700	not avail.	270 WIN	1-Mar-64	N	S	16-Jun-15	16-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500660	F	Per Ilion- Repair at no charge under XMP update.
12080	700	not avail.	270 WIN	16-Oct-75	N	S	16-Jun-15	16-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500659	F	Per Ilion- Replace TA under BLP
12075	700	25813	3006 SPRG	3-Sep-96	N	S	16-Jun-15	16-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500676	F	Per Ilion- Repair at no charge under XMP update.
12081	1100	25330	12 GA	10-Feb-75	N	S	16-Jun-15	16-Jun-15	Fired Out of Battery	Could Not Duplicate Concern	500666	F	Per Ilion- Repair at 1/2 cost
12092	597	80850	22WMR	11-Dec-14	N	S	18-Jun-15	18-Jun-15	Cartridge Cases Damaged during firing	Wrong Ammunition Fired in Gun	500744	F	Per Ilion- Repair as needed at no charge.
12087	700	25773	3006 SPRG	30-Dec-94	N	S	18-Jun-15	18-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500798	F	Per Ilion- Replace TA under XMP update
12093	700	Not Avail.	6MM REM	5-Apr-72	N	S	18-Jun-15	18-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500769	F	Per Ilion- Repair at no charge
12088	887	82500	12GA	27-Apr-11	N	S	18-Jun-15	18-Jun-15	Fired on Bolt Closing	Could Not Duplicate Concern	500729	F	Per Ilion- Repair at no charge

RAC001232

Confidential

12091	710	27418	243 WIN	8-Nov-06	Y	S	18-Jun-15	17-Jul-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	500768	F	Replace with Ramac 85842 in exchange
12095	870	25098	12 GA	8-Apr-10	N	PI/PD/S	18-Jun-15	18-Aug-15	Fired Out of Battery	Slow to Peak	502312	F	Check over completely, repair as needed, and test at no charge
12103	700	not avail.	243 WIN	1-Nov-62	N	S	23-Jun-15	23-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500839	F	Per Ilion- Repair at no charge under XMP update.
12102	700	27173	270 WSM 300 WIN MA	17-Nov-09	N	S	23-Jun-15	23-Jun-15	Fired on Bolt Closing	Could Not Duplicate Concern	500833	F	Per Ilion- Repair at no charge under XMP update.
12099	700	87882		27-Jun-13	N	S	23-Jun-15	23-Jun-15	Fired on Bolt Closing	Could Not Duplicate Concern	500802	F	Per Ilion: Repair at no charge
12098	700	not avail.	308 WIN	16-Jun-81	N	S	23-Jun-15	23-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500819	F	Per Ilion- Repair at no charge under XMP update.
12101	710	27408	270 WIN	19-Sep-05	Y	S	23-Jun-15	23-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500820	F	Per Ilion, replace with Ramac 85844 in exchange
12100	770	85656	3006 SPRG	1-Jun-09	Y	S	23-Jun-15	21-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500840	F	Per Ilion: Replace w/85846 @ no charge
12111	887	82500	12 GA	18-Feb-10	N	PD/S	25-Jun-15	25-Jun-15	Broken Part	Sent in for Evaluation	500947	F	Per Ilion: Repair at no charge
12109	700	84600	223 REM	5-Sep-12	N	S	25-Jun-15	25-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500948	F	Per Ilion- Repair at no charge under XMP update.
12106	700	not avail.	3006 SPRG	4-Feb-78	N	S	25-Jun-15	25-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500923	F	Per Ilion- Replace TA under BUP
12107	700	not avail.	3006 SPRG	20-Aug-75	N	S	25-Jun-15	25-Jun-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	500924	F	Per Ilion- Repair at no charge under XMP update.
12108	700	not avail.	7MM REM MA	7-Mar-78	N	S	25-Jun-15	25-Jun-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	500925	F	Per Ilion- Replace TA under BUP
12110	870	25549	12 GA	27-Mar-14	N	S	25-Jun-15	25-Jun-15	Fail to Fire	Sent in for Evaluation	500968	F	Per Ilion: Repair at no charge
12114	700	84600	223 REM	12-Sep-13	N	PD/S	30-Jun-15	*	Fired on Bolt Closing	Other - Unexamined		F	
12117	597	26536	17 HMR	24-Oct-02	N	PD/S	1-Jul-15	1-Jul-15	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	501062	F	Per Ilion, converting to 22 WMR as requested by customer.
12118	700	26909	270 WIN	3-Dec-93	N	S	1-Jul-15	1-Jul-15	Delayed Firing - Firearms	Could Not Duplicate Concern	501052	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12115	700	N/A	3006 SPRG	25-May-78	N	S	1-Jul-15	1-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501060	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge

RAC001233

Confidential

12116	700	N/A	3006 SPRG	26-Jul-76	N	S	1-Jul-15	1-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501061	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12119	700	25934	3006 SPRG	8-Feb-12	N	S	1-Jul-15	1-Jul-15	Other - Firearms	Sent in for Evaluation	501053	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12120	700	27269	3006 SPRG	19-Sep-11	N	S	1-Jul-15	1-Jul-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	501054	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12121	700 ML	27589	50 CAL	17-Oct-02	N	S	6-Jul-15	6-Jul-15	Fired on Bolt Closing	Sent in for Evaluation	501095	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12126	700	N/A	7MM REM MA	13-Oct-70	N	S	7-Jul-15	7-Jul-15	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	501270	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12128	710	27410	3006 SPRG	3-Apr-03	Y	S	7-Jul-15	28-Jul-15	Fired With Safe ON	Sent in for Evaluation	501273	F	Per Ilion - Replace w/85846 - goodwill
12129	887	82500	12 GA	9-Nov-09	N	S	7-Jul-15	7-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501182	F	Per Ilion - Repair at n/c
12124	1187	29591	20 GA	26-Oct-99	N	S	7-Jul-15	7-Jul-15	Safety not working properly	Could Not Duplicate Concern	501277	F	Per Ilion - Repair at n/c - goodwill
12125	ACR	90838	223/5.56	3-Oct-13	N	S	7-Jul-15	7-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501219	F	Per Ilion, check over completely, repair as needed, and test at no charge.
12133	700	25798	223 REM	13-Dec-94	N	S	8-Jul-15	8-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501271	F	Per Ilion - Repair at n/c
12132	700	27363	3006 SPRG	7-Mar-05	N	S	8-Jul-15	8-Jul-15	Fired on Bolt Closing	Altered Adjustments or Components	501274	F	Per Ilion - Repair at n/c
12131	SEVEN	24786	7MM-08 REM	24-Sep-91	N	S	8-Jul-15	8-Jul-15	Fired on Bolt Opening	Altered Adjustments or Components	501272	F	Per Ilion - Repair at n/c
12134	770	85634	308 WIN	5-Mar-08	Y	S	8-Jul-15	17-Aug-15	Fired on Safe Release	Altered Adjustments or Components	501268	F	Per Ilion - Replace w/85847 in exchange & ck for \$26.50 (transfer fee)
12143	597	26514	17 HMIR	20-Nov-06	N	S	10-Jul-15	10-Jul-15	Other - Firearms	Other - Unspecified or Undetermined - Firearms	501383	F	Converting to 22 WMIR as requested by customer
12146	700	84226	22-250 REM	24-Jul-12	N	S	10-Jul-15	10-Jul-15	Other - Firearms - XMP Update	Could Not Duplicate Concern	501377	F	Per Ilion, replace trigger assembly, replace action, check over, and test fire at no charge
12145	700	not avail.	243 WIN	27-Nov-79	N	S	10-Jul-15	10-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501403	F	Per Ilion - Replace TA & test @ n/c
12147	700	25771	270 WIN	7-May-84	N	S	10-Jul-15	10-Jul-15	Fired on Safe Release	Could Not Duplicate Concern	501342	F	Per Ilion - Replace TA & test @ n/c
12144	700	not avail.	3006 SPRG	31-May-74	N	S	10-Jul-15	10-Jul-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	501280	F	Per Ilion - Replace TA @ n/c
12149	700	N/A	3006 SPRG	29-Mar-76	N	S	10-Jul-15	10-Jul-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	501407	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge

RAC001234